



GE Fanuc Automation

Computer Numerical Control Products

Alpha Series AC Servo Motor

Descriptions Manual

GFZ-65142E/04

February 2001

Warnings, Cautions, and Notes as Used in this Publication

Warning

Warning notices are used in this publication to emphasize that hazardous voltages, currents, temperatures, or other conditions that could cause personal injury exist in this equipment or may be associated with its use.

In situations where inattention could cause either personal injury or damage to equipment, a Warning notice is used.

Caution

Caution notices are used where equipment might be damaged if care is not taken.

Note

Notes merely call attention to information that is especially significant to understanding and operating the equipment.

This document is based on information available at the time of its publication. While efforts have been made to be accurate, the information contained herein does not purport to cover all details or variations in hardware or software, nor to provide for every possible contingency in connection with installation, operation, or maintenance. Features may be described herein which are not present in all hardware and software systems. GE Fanuc Automation assumes no obligation of notice to holders of this document with respect to changes subsequently made.

GE Fanuc Automation makes no representation or warranty, expressed, implied, or statutory with respect to, and assumes no responsibility for the accuracy, completeness, sufficiency, or usefulness of the information contained herein. No warranties of merchantability or fitness for purpose shall apply.

FANUC SERVO MOTOR series

SAFETY PRECAUTIONS

This "Safety Precautions" section describes the precautions which must be observed to ensure safety when using FANUC servo motors (including spindle motors). Users of any servo motor model are requested to read this manual carefully before using the servo motor.

The users are also requested to read this manual carefully and understand each function of the motor for correct use.

The users are basically forbidden to do any behavior or action not mentioned in the "Safety Precautions." They are invited to ask FANUC previously about what behavior or action is prohibited.

Contents

| | |
|---|-----|
| 1. DEFINITION OF WARNING, CAUTION, AND NOTE | s-2 |
| 2. WARNING | s-3 |
| 3. CAUTION | s-5 |
| 4. NOTE | s-6 |

1

DEFINITION OF WARNING, CAUTION, AND NOTE

This manual includes safety precautions for protecting the user and preventing damage to the machine. Precautions are classified into Warning and Caution according to their bearing on safety. Also, supplementary information is described as a Note. Read the Warning, Caution, and Note thoroughly before attempting to use the machine.

WARNING

Applied when there is a danger of the user being injured or when there is a damage of both the user being injured and the equipment being damaged if the approved procedure is not observed.

CAUTION

Applied when there is a danger of the equipment being damaged, if the approved procedure is not observed.

NOTE

The Note is used to indicate supplementary information other than Warning and Caution.

- **Read this manual carefully, and store it in a safe place.**

2

WARNING

WARNING

- **Be safely dressed when handling a motor.**

Wear safety shoes or gloves when handling a motor as you may get hurt on any edge or protrusion on it or electric shocks.

- **Use a crane or lift to move a motor from one place to another.**

Motors are heavy. When moving them, use a crane or lift as required. (For the weight of motors, refer to their respective specification manuals.)

When moving a motor using a crane or lift, use a hanging bolt if the motor has a corresponding tapped hole, or textile rope if it has no tapped hole. If a motor is attached with a machine or any other heavy stuff, do not use a hanging bolt to move the motor as the hanging bolt and/or motor may get broken. When moving a motor, be careful not to apply excessive force to its windings as the windings may break and/or their insulation may deteriorate.

- **Do not touch a motor with a wet hand.**

A failure to observe this caution is vary dangerous because you may get electric shocks.

- **Before starting to connect a motor to electric wires, make sure they are isolated from an electric power source.**

A failure to observe this caution is vary dangerous because you may get electric shocks.

- **Do not bring any dangerous stuff near a motor.**

Motors are connected to a power line, and may get hot. If a flammable is placed near a motor, it may be ignited, catch fire, or explode.

- **Be sure to ground a motor frame.**

To avoid electric shocks, be sure to connect the grounding terminal in the terminal box to the grounding terminal of the machine.

- **Do not ground a motor power wire terminal or short-circuit it to another power wire terminal.**

A failure to observe this caution may cause electric shocks or a burned wiring.

* Some motors require a special connection such as a winding changeover. Refer to their respective motor specification manuals for details.

WARNING**● Connect power wires securely so that they will not get loose.**

A failure to observe this caution may cause a wire to be disconnected, resulting in a ground fault, short circuit, or electric shock.

● Do not supply the power to the motor while any terminal is exposed.

A failure to observe this caution is very dangerous because you may get electric shocks if your body or any conductive stuff touches an exposed terminal.

● Do not get close to a rotary section of a motor when it is rotating.

A rotating part may catch your cloths or fingers. Before starting a motor, ensure that there is no stuff that can fly away (such as a key) on the motor.

● Before touching a motor, shut off the power to it.

Even if a motor is not rotating, there may be a voltage across the terminals of the motor. Especially before touching a power supply connection, take sufficient precautions. Otherwise you may get electric shocks.

● Do not touch any terminal of a motor for a while (at least 5 minutes) after the power to the motor is shut off.

High voltage remains across power line terminals of a motor for a while after the power to the motor is shut off. So, do not touch any terminal or connect it to any other equipment. Otherwise, you may get electric shocks or the motor and/or equipment may get damaged.

● To drive a motor, use a specified amplifier and parameters.

An incorrect combination of a motor, amplifier, and parameters may cause the motor to behave unexpectedly. This is dangerous, and the motor may get damaged.

● Do not touch a motor when it is running or immediately after it stops.

A motor may get hot when it is running. Do not touch the motor before it gets cool enough. Otherwise, you may get burned.

● Be careful not get your hair or cloths caught in a fan.

Be careful especially for a fan used to generate an inward air flow. Be careful also for a fan even when the motor is stopped, because it continues to rotate while the amplifier is turned on.

● Ensure that motors and related components are mounted securely.

If a motor or its component slips out of place or comes off when the motor is running, it is very dangerous.

3

CAUTION

CAUTION

- **FANUC motors are designed for use with machines. Do not use them for any other purpose.**

If a FANUC motor is used for an unintended purpose, it may cause an unexpected symptom or trouble. If you want to use a motor for an unintended purpose, previously consult with FANUC.

- **Ensure that a base or frame on which a motor is mounted is strong enough.**

Motors are heavy. If a base or frame on which a motor is mounted is not strong enough, it is impossible to achieve the required precision.

- **Be sure to connect motor cables correctly.**

An incorrect connection of a cable cause abnormal heat generation, equipment malfunction, or failure. Always use a cable with an appropriate current carrying capacity (or thickness). For how to connect cables to motors, refer to their respective specification manuals.

- **Ensure that motors are cooled if they are those that require forcible cooling.**

If a motor that requires forcible cooling is not cooled normally, it may cause a failure or trouble. For a fan-cooled motor, ensure that it is not clogged or blocked with dust and dirt. For a liquid-cooled motor, ensure that the amount of the liquid is appropriate and that the liquid piping is not clogged. For both types, perform regular cleaning and inspection.

- **When attaching a component having inertia, such as a pulley, to a motor, ensure that any imbalance between the motor and component is minimized.**

If there is a large imbalance, the motor may vibrates abnormally, resulting in the motor being broken.

- **Be sure to attach a key to a motor with a keyed shaft.**

If a motor with a keyed shaft runs with no key attached, it may impair torque transmission or cause imbalance, resulting in the motor being broken.

4

NOTE

NOTE

- **Do not step or sit on a motor.**

If you step or sit on a motor, it may get deformed or broken. Do not put a motor on another unless they are in packages.

- **When storing a motor, put it in a dry (non-condensing) place at room temperature (0 to 40 °C).**

If a motor is stored in a humid or hot place, its components may get damaged or deteriorated. In addition, keep a motor in such a position that its shaft is held horizontal and its terminal box is at the top.

- **Do not remove a nameplate from a motor.**

If a nameplate comes off, be careful not to lose it. If the nameplate is lost, the motor becomes unidentifiable, resulting in maintenance becoming impossible. For a nameplate for a built-in spindle motor, keep the nameplate with the spindle.

- **Do not apply shocks to a motor or cause scratches to it.**

If a motor is subjected to shocks or is scratched, its components may be adversely affected, resulting in normal operation being impaired. Be very careful when handling plastic portions, sensors, and windings, because they are very liable to break. Especially, avoid lifting a motor by pulling its plastic portion, winding, or power cable.

- **Do not conduct dielectric strength or insulation test for a detector.**

Such a test can damage elements in the detector.

- **When testing the winding or insulation resistance of a motor, satisfy the conditions stipulated in IEC34.**

Testing a motor under a condition severer than those specified in IEC34 may damage the motor.

- **Do not disassemble a motor.**

Disassembling a motor may cause a failure or trouble in it.

If disassembly is in need because of maintenance or repair, please contact a service representative of FANUC.

- **Do not modify a motor.**

Do not modify a motor unless directed by FANUC. Modifying a motor may cause a failure or trouble in it.

NOTE

- **Use a motor under an appropriate environmental condition.**

Using a motor in an adverse environment may cause a failure or trouble in it. Refer to their respective specification manuals for details of the operating and environmental conditions for motors.

- **Do not apply a commercial power source voltage directly to a motor.**

Applying a commercial power source voltage directly to a motor may result in its windings being burned. Be sure to use a specified amplifier for supplying voltage to the motor.

- **For a motor with a terminal box, make a conduit hole for the terminal box in a specified position.**

When making a conduit hole, be careful not to break or damage unspecified portions. Refer to an applicable specification manual.

- **Before using a motor, measure its winding and insulation resistances, and make sure they are normal.**

Especially for a motor that has been stored for a prolonged period of time, conduct these checks. A motor may deteriorate depending on the condition under which it is stored or the time during which it is stored. For the winding resistances of motors, refer to their respective specification manuals, or ask FANUC. For insulation resistances, see the following table.

- **To use a motor as long as possible, perform periodic maintenance and inspection for it, and check its winding and insulation resistances.**

Note that extremely severe inspections (such as dielectric strength tests) of a motor may damage its windings. For the winding resistances of motors, refer to their respective specification manuals, or ask FANUC. For insulation resistances, see the following table.

MOTOR INSULATION RESISTANCE MEASUREMENT

Measure an insulation resistance between each winding and motor frame using an insulation resistance meter (500 VDC). Judge the measurements according to the following table.

| Insulation resistance | Judgment |
|------------------------------|---|
| 100 M Ω or higher | Acceptable |
| 10 to 100 M Ω | The winding has begun deteriorating. There is no problem with the performance at present. Be sure to perform periodic inspection. |
| 1 to 10 M Ω | The winding has considerably deteriorated. Special care is in need. Be sure to perform periodic inspection. |
| Lower than 1 M Ω | Unacceptable. Replace the motor. |

PREFACE

This manual describes the specifications and characteristics of the α series servo motors. The manual consists of the following chapters:

I. SPECIFICATIONS FOR THE α series

This chapter provides general notes on the use of the α series and explains how to select the optimum motor for a given application. This chapter also provides the specifications common to each model of the α series, concerning the detectors, internal brakes, plug connectors, and so forth.

II. FANUC AC SERVO MOTOR α series

This chapter explains how to specify a certain α series servo motor and provides specifications, dimensions, and data sheets for the entire range of α series servo motors.

III. FANUC AC SERVO MOTOR α M series

This chapter explains how to specify a certain α M series servo motor and provides specifications, dimensions, and data sheets for the entire range of α M series servo motors.

IV. FANUC AC SERVO MOTOR α L series

This chapter explains how to specify a certain α L series servo motor and provides specifications, dimensions, and data sheets for the entire range of α L series servo motors.

V. FANUC AC SERVO MOTOR α C series

This chapter explains how to specify a certain α C series servo motor and provides specifications, dimensions, and data sheets for the entire range of α C series servo motors.

VI. FANUC AC SERVO MOTOR α (HV) series

This chapter explains how to specify a certain α (HV) series servo motor and provides specifications, dimensions, and data sheets for the entire range of α (HV) series servo motors.

VII. FANUC AC SERVO MOTOR α M(HV) series

This chapter explains how to specify a certain α (HV) series servo motor and provides specifications, dimensions, and data sheets for the entire range of α (HV) series servo motors.

VIII. SUPPLEMENT

This supplement explains how to increase the maximum allowable speed of AC servo motors.

Although this manual provides information on detector signal outputs, it does not describe connection to a servo amplifier or NC. For details of these connections, refer to the “FANUC SERVO MOTOR α series Maintenance Manual” (B-65165E).

Related manuals

The following six kinds of manuals are available for FANUC SERVO MOTOR α series. In the table, this manual is marked with an asterisk (*).

| Document name | Document number | Major contents | Major usage | |
|---|-----------------|--|---|---|
| FANUC AC SERVO MOTOR α series DESCRIPTIONS | B-65142E | <ul style="list-style-type: none"> ● Specification ● Characteristics ● External dimensions ● Connections | <ul style="list-style-type: none"> ● Selection of motor ● Connection of motor | * |
| FANUC AC SPINDLE MOTOR α series DESCRIPTIONS | B-65152E | <ul style="list-style-type: none"> ● Specification ● Characteristics ● External dimensions ● Connections | | |
| FANUC SERVO AMPLIFIER α series DESCRIPTIONS | B-65162E | <ul style="list-style-type: none"> ● Specifications and functions ● Installation | <ul style="list-style-type: none"> ● Selection of amplifier ● Connection of amplifier | |
| FANUC CONTROL MOTOR α series SERVO AMPLIFIER UNIT DESCRIPTIONS | B-65192E | <ul style="list-style-type: none"> ● External dimensions and maintenance area ● Connections | | |
| FANUC SERVO MOTOR α series MAINTENANCE MANUAL | B-65165E | <ul style="list-style-type: none"> ● Start up procedure ● Troubleshooting ● Maintenance of motor | <ul style="list-style-type: none"> ● Start up the system (Hardware) ● Troubleshooting ● Maintenance of motor | |
| FANUC AC SERVO MOTOR α series PARAMETER MANUAL | B-65150E | <ul style="list-style-type: none"> ● Initial setting ● Setting parameters ● Description of parameters | <ul style="list-style-type: none"> ● Start up the system (Software) ● Tuning the system (Parameters) | |
| FANUC AC SPINDLE MOTOR α series PARAMETER MANUAL | B-65160E | <ul style="list-style-type: none"> ● Initial setting ● Setting parameters ● Description of parameters | | |

Table of Contents

| | |
|---|------------|
| SAFETY PRECAUTIONS | s-1 |
| PREFACE | p-1 |
| I. DESCRIPTIONS FOR THE α series | |
| 1. GENERAL | 3 |
| 2. PRECAUTIONS ON USE | 5 |
| 2.1 APPLICABLE AMPLIFIERS | 6 |
| 2.1.1 Applicable Amplifiers | 6 |
| 2.1.2 Data for Selecting PSM | 13 |
| 2.2 INSTALLATION | 14 |
| 2.3 COUPLING | 15 |
| 2.4 AXIS LOAD | 17 |
| 2.5 ENVIRONMENT | 18 |
| 2.6 ACCEPTANCE AND STORAGE | 21 |
| 3. INSTRUCTIONS | 22 |
| 3.1 DRIVE SHAFT COUPLING | 23 |
| 3.2 MACHINE MOVEMENT PER 1 REVOLUTION OF MOTOR SHAFT | 26 |
| 4. SELECTING A MOTOR | 27 |
| 4.1 CALCULATING CONDITIONS FOR SELECTING A MOTOR | 28 |
| 4.1.1 Calculating the Load Torque and Load Inertia | 29 |
| 4.1.2 Calculating the Acceleration Torque | 34 |
| 4.1.3 Calculating the Root-mean-square Value of the Torques | 37 |
| 4.1.4 Calculating the Percentage Duty Cycle with the Maximum Cutting Torque | 39 |
| 4.2 PRECAUTIONS FOR USING LINEAR SCALE | 41 |
| 4.3 HOW TO FILL IN THE SERVO MOTOR SELECTION DATA TABLE | 43 |
| 4.3.1 Title | 44 |
| 4.3.2 Data | 45 |
| 4.4 CHARACTERISTIC CURVE AND DATA SHEET | 52 |
| 4.4.1 Performance Curves | 52 |
| 4.4.2 Data Sheet | 52 |
| 4.4.3 How to Use Duty Cycle Curves | 54 |
| 5. CONDITIONS FOR APPROVAL RELATED TO THE IEC34 STANDARD | 55 |
| 5.1 APPLICABLE MOTORS | 56 |
| 5.1.1 200 VAC Input Types | 56 |
| 5.1.2 400 VAC Input Types | 57 |
| 5.2 DRIVES | 58 |
| 5.2.1 200 VAC Input Types | 58 |
| 5.2.2 400 VAC Input Types | 58 |
| 5.3 POWER CABLE CONNECTORS | 59 |
| 5.3.1 Models $\alpha 1$ and $\alpha 2$ | 59 |
| 5.3.2 Models $\alpha 3$ and Higher | 61 |
| 5.4 APPROVED SPECIFICATIONS | 63 |
| 5.4.1 Motor Speed (IEC34-1) | 63 |
| 5.4.2 Output (IEC34-1) | 64 |

| | | |
|------------|--|------------|
| 5.4.3 | Protection Type (IEC34-5) | 64 |
| 5.4.4 | Cooling Method (ICE34-6) | 64 |
| 5.4.5 | Mounting Method (IEC34-7) | 65 |
| 5.4.6 | Heat Protection (IEC34-11) | 65 |
| 6. | FEEDBACK DETECTOR | 66 |
| 6.1 | BUILT-IN DETECTOR | 67 |
| 6.2 | PULSE CODER RESOLUTION AND CONTROL RESOLUTION | 68 |
| 6.3 | ABSOLUTE-TYPE PULSE CODER | 69 |
| 6.4 | DETECTOR INPUT/OUTPUT SIGNALS | 70 |
| 6.5 | SEPARATE TYPE POSITION DETECTOR | 71 |
| 6.5.1 | Separate Type Pulse Coder Type and Specifications | 71 |
| 6.5.2 | Separate Type Pulse Coder Specifications | 72 |
| 6.5.3 | Input Signals and Layout of Connector Pins of Separate Type Pulse Coder | 73 |
| 6.5.4 | External Dimensions of Separate Type Pulse Coder | 75 |
| 7. | BUILT-IN BRAKE | 79 |
| 7.1 | BRAKE SPECIFICATIONS | 80 |
| 7.2 | CAUTIONS | 81 |
| 7.3 | CONNECTOR SHAPES | 82 |
| 7.4 | CONNECTION OF THE BRAKES | 83 |
| 7.5 | RECOMMENDED PARTS IN BRAKE CIRCUITS | 84 |
| 7.6 | BRAKE CABLE (TUV/EMC COMPATIBLE) | 84 |
| 7.7 | REDUCING THE BRAKE SHAFT FALL AMOUNT | 85 |
| 8. | CONNECTORS | 86 |
| 8.1 | CONNECTOR ON THE MOTOR SIDE | 87 |
| 8.1.1 | Specifications of Connectors on the Motor Side | 87 |
| 8.2 | CONNECTORS ON THE CABLE SIDE (MODELS $\alpha 1$ AND $\alpha 2$) | 89 |
| 8.2.1 | Connector Kit Specifications | 89 |
| 8.2.2 | Cable Assembly Specifications (14m Standard) (for $\alpha 1$ and $\alpha 2$) | 90 |
| 8.3 | SPECIFICATIONS OF THE CONNECTORS ON THE CABLE SIDE (MODELS $\alpha 3$ AND HIGHER) | 91 |
| 8.3.1 | Specifications of Plug Connectors on the Cable Side (Waterproof TÜV-approved Type) | 93 |
| 8.3.2 | Specifications of Plug Connectors on the Cable Side (Waterproof Type) | 94 |
| 8.3.3 | Specifications of Plug Connectors on the Cable Side (Non-waterproof Type) | 96 |
| 8.3.4 | Cable Assembly Specifications ($\alpha 3$ or Above) (14m Standard) | 98 |
| 9. | COOLING FAN | 99 |
| 9.1 | COOLING FAN SPECIFICATIONS | 100 |
| 9.2 | MOTOR CONNECTOR SPECIFICATIONS | 100 |
| 9.3 | ABOUT CONNECTOR CABLES | 100 |
| 9.4 | WIRING DIAGRAM | 101 |
| II. | FANUC AC SERVO MOTOR α series | 103 |
| 1. | GENERAL | 105 |
| 2. | TYPES OF MOTORS AND DESIGNATION | 106 |

| | |
|---|------------|
| 3. SPECIFICATIONS AND CHARACTERISTICS | 109 |
| 3.1 TYPE OF MOTORS AND SPECIFICATIONS | 110 |
| 3.2 CHARACTERISTIC CURVE AND DATA SHEET | 112 |
| 3.3 OUTLINE DRAWINGS | 128 |
| 3.4 CONNECTION OF POWER LINE | 144 |
| | |
| III. FANUC AC SERVO MOTOR αM series | |
| | |
| 1. GENERAL | 149 |
| | |
| 2. TYPES OF MOTORS AND DESIGNATION | 150 |
| | |
| 3. SPECIFICATIONS AND CHARACTERISTICS | 152 |
| 3.1 TYPES OF MOTORS AND SPECIFICATIONS | 153 |
| 3.2 CHARACTERISTIC CURVE AND DATA SHEET | 154 |
| 3.3 OUTLINE DRAWINGS | 166 |
| 3.4 CONNECTION OF POWER LINE | 180 |
| | |
| IV. FANUC AC SERVO MOTOR αL series | |
| | |
| 1. GENERAL | 183 |
| | |
| 2. TYPES OF MOTORS AND DESIGNATION | 184 |
| | |
| 3. SPECIFICATIONS AND CHARACTERISTICS | 185 |
| 3.1 TYPES OF MOTORS AND SPECIFICATIONS | 186 |
| 3.2 CHARACTERISTIC CURVE AND DATA SHEET | 187 |
| 3.3 OUTLINE DRAWINGS | 193 |
| 3.4 CONNECTION OF POWER LINE | 198 |
| | |
| V. FANUC AC SERVO MOTOR αC series | |
| | |
| 1. GENERAL | 201 |
| | |
| 2. TYPES OF MOTORS AND DESIGNATION | 202 |
| | |
| 3. SPECIFICATIONS AND CHARACTERISTICS | 203 |
| 3.1 TYPES OF MOTORS AND SPECIFICATIONS | 204 |
| 3.2 CHARACTERISTIC CURVE AND DATA SHEET | 205 |
| 3.3 OUTLINE DRAWINGS | 210 |
| 3.4 CONNECTION OF POWER LINE | 217 |
| | |
| VI. FANUC AC SERVO MOTOR α (HV) series | |
| | |
| 1. GENERAL | 221 |
| | |
| 2. TYPES OF MOTORS AND DESIGNATION | 222 |

| | |
|--|------------|
| 3. SPECIFICATIONS AND CHARACTERISTICS | 224 |
| 3.1 TYPES OF MOTORS AND SPECIFICATIONS | 225 |
| 3.2 CHARACTERISTIC CURVE AND DATA SHEET | 226 |
| 3.3 OUTLINE DRAWINGS | 236 |
| 3.4 CONNECTION OF POWER LINE | 247 |

VII. FANUC AC SERVO MOTOR α M (HV) series

| | |
|--|------------|
| 1. GENERAL | 251 |
| 2. TYPES OF MOTORS AND DESIGNATION | 252 |
| 3. SPECIFICATIONS AND CHARACTERISTICS | 254 |
| 3.1 TYPES OF MOTORS AND SPECIFICATIONS | 255 |
| 3.2 CHARACTERISTIC CURVE AND DATA SHEET | 256 |
| 3.3 OUTLINE DRAWINGS | 264 |
| 3.4 CONNECTION OF POWER LINE | 274 |

VIII. SUPPLEMENT

(Following AC servo motors are extended the allowable maximum speed.)

| | |
|--|------------|
| 1. REQUIRED CONDITIONS | 277 |
| 2. SERVO MOTOR | 278 |
| 3. SERVO SOFTWARE | 279 |
| 4. SERVO PARAMETER | 280 |
| 5. SELECTING PSM | 281 |
| 6. "CHARACTERISTICS CURVE" AND "DATA SHEET" | 282 |

I. DESCRIPTIONS FOR THE α series

1 GENERAL

The FANUC AC servo motor α series has been designed for machine tool feed axis applications. This servo motor α series has the following features:

Smooth rotation

The special magnetic pole shape minimizes torque ripples which, when combined with precise current control and accurate pulse coder feedback, enables extremely smooth motor rotation.

Excellent acceleration

The use of a special rotor shape results in motors that are smaller and lighter than previous models, but which can develop a high level of torque. These motors, therefore, provide excellent acceleration characteristics.

High reliability

A totally-enclosed, friction-free brushless design is used. This allows the servo motors to be used in demanding environments with no need for special checks or maintenance.

Built-in, high-precision detector

A low-indexing-error optical encoder (pulse coder) is built into the motors. This pulse coder enables precise positioning. Pulse coders that output 65,536, or 1,000,000 pulses per rotation are available. As such, the α series motors can be used for positioning applications ranging from simple positioning to those requiring a high degree of precision. (Available pulse coders vary with the series and model of the motor being used.)

The FANUC AC servo motor α series consists of the α , α M, α C, α (HV) series, and α M (HV), all of which are suitable general machine tool, control applications, and the α L series, designed for controlling machine tools that require frequent positioning operations, such as punch presses and PCB drilling machines.

Each of these series is further divided into the following models:

- **α series**

α 1/3000, α 2/2000, α 2/3000, α 3/3000, α 6/2000, α 6/3000, α 12/2000, α 12/3000, α 22/1500, α 22/2000, α 22/3000, α 30/1200, α 30/2000, α 30/3000, α 40/2000, α 40/2000 (with fan), α 65/2000, α 100/2000, α 150/2000, α 300/2000, α 400/2000

- **α M series**

α M2/3000, α M2.5/3000, α M6/3000, α M9/3000, α M22/3000, α M30/3000, α M40/3000, α M40/3000 (with fan)

- **α L series**

α L6/3000, α L9/3000, α L25/3000, α L50/2000

- **α C series,**

α C3/2000, α C6/2000, α C12/2000, α C22/1500

- **α (HV) series**
 α 3/3000HV, α 6/3000HV, α 12/3000HV, α 22/3000HV, α 30/3000HV,
 α 40/2000HV, α 1000/2000HV
- **α M(HV) series**
 α M6/3000 (HV), α M9/3000 (HV), α M22/3000 (HV),
 α M30/3000 (HV), α M40/3000 (HV)

2 PRECAUTIONS ON USE



2.1 APPLICABLE AMPLIFIERS

2.1.1 Applicable Amplifiers

The FANUC α series AC servo motors can be driven using FANUC α series servo amplifiers.

| Servo motor | | Servo amplifier module (SVM)/ Servo amplifier unit (SVU) | | |
|---|--|---|--|-----------------|
| Model name | Specification | Model name | Specification | Connection axis |
| α 1/3000 α 2/2000 α 2/3000 | A06B-0371-B*** A06B-0372-B*** A06B-0373-B*** | SVM1-12 | A06B-6079-H101 A06B-6096-H101 | |
| | | SVM2-12/12 | A06B-6079-H201 A06B-6096-H201 | L and M axes |
| | | SVM2-12/20 | A06B-6079-H202 A06B-6096-H202 | L axis |
| | | SVM2-12/40 | A06B-6079-H204 A06B-6080-H204 | L axis |
| | | SVM3-12/12/12 | A06B-6079-H301 A06B-6080-H301 A06B-6096-H301 | L, M and N axes |
| | | SVM3-12/12/20 | A06B-6079-H302 A06B-6080-H302 A06B-6096-H302 | L and M axes |
| | | SVM3-12/20/20 | A06B-6079-H303 A06B-6080-H303 A06B-6096-H303 | L axis |
| | | SVM3-12/12/40 | A06B-6079-H305 A06B-6080-H305 A06B-6096-H305 | L and M axes |
| | | SVM3-12/20/40 | A06B-6079-H306 A06B-6080-H306 A06B-6096-H306 | L axis |
| | | SVU1-12 | A06B-6089-H101 | L and M axes |
| | | SVU2-12/12 | A06B-6089-H201 | L axis |
| | | SVU2-12/20 | A06B-6089-H202 | L axis |
| | | SVU2-12/40 | A06B-6089-H204 | L axis |
| | | SVU3-12/12/12 | A06B-6089-H301 | L, M and N axes |
| | | SVU3-12/12/20 | A06B-6089-H302 | L and M axes |
| | | SVU3-12/20/20 | A06B-6089-H303 | L axis |

| Servo motor | | Servo amplifier module (SVM)/ Servo amplifier unit (SVU) | | |
|--|--|---|--|-----------------|
| Model name | Specification | Model name | Specification | Connection axis |
| α M2/3000 α M2.5/3000 α C3/2000 α C6/2000 | A06B-0376-B*** A06B-0377-B*** A06B-0121-B*** A06B-0126-B*** | SVM1-20 | A06B-6079-H102 A06B-6096-H102 | |
| | | SVM2-12/20 | A06B-6079-H202 A06B-6096-H202 | M axis |
| | | SVM2-20/20 | A06B-6079-H203 A06B-6096-H203 | L and M axes |
| | | SVM2-20/40 | A06B-6079-H205 A06B-6096-H205 | L axis |
| | | SVM3-12/12/20 | A06B-6079-H302 A06B-6080-H302 A06B-6096-H302 | N axis |
| | | SVM3-12/20/20 | A06B-6079-H303 A06B-6080-H303 A06B-6096-H303 | M and N axes |
| | | SVM3-20/20/20 | A06B-6079-H304 A06B-6080-H304 A06B-6096-H304 | L, M and N axes |
| | | SVM3-12/20/40 | A06B-6079-H306 A06B-6080-H306 A06B-6096-H306 | M axis |
| | | SVM3-20/20/40 | A06B-6079-H307 A06B-6080-H307 A06B-6096-H307 | L and M axes |
| | | SVU1-20 | A06B-6089-H102 | |
| | | SVU2-12/20 | A06B-6089-H202 | M axis |
| | | SVU2-20/20 | A06B-6089-H203 | L and M axes |
| | | SVU2-20/40 | A06B-6089-H205 | L axis |
| | | SVU3-12/12/20 | A06B-6089-H302 | N axis |
| | | SVU3-12/20/20 | A06B-6089-H303 | M and N axes |
| | | SVU3-20/20/20 | A06B-6089-H304 | L, M and N axes |

| Servo motor | | Servo amplifier module (SVM)/ Servo amplifier unit (SVU) | | |
|------------------------------------|----------------------------------|---|--|-----------------|
| Model name | Specification | Model name | Specification | Connection axis |
| α 3/3000 α 6/2000 | A06B-0123-B*** A06B-0127-B*** | SVM1-40S | A06B-6079-H103 A06B-6096-H103 | |
| | | SVM2-12/40 | A06B-6079-H204 A06B-6096-H204 | M axis |
| | | SVM2-20/40 | A06B-6079-H205 A06B-6096-H205 | M axis |
| | | SVM2-40/40 | A06B-6079-H206 A06B-6096-H206 | L axis |
| | | SVM2-40/80 | A06B-6079-H207 A06B-6096-H207 | L axis |
| | | SVM2-40L/40L | A06B-6079-H209 A06B-6096-H209 | L and M axes |
| | | SVM3-12/12/40 | A06B-6079-H305 A06B-6080-H305 A06B-6096-H305 | N axis |
| | | SVM3-12/20/40 | A06B-6079-H306 A06B-6080-H306 A06B-6096-H306 | N axis |
| | | SVM3-20/20/40 | A06B-6079-H307 A06B-6080-H307 A06B-6096-H307 | N axis |
| | | SVU1-40 | A06B-6089-H104 | |
| | | SVU2-12/40 | A06B-6089-H204 | M axis |
| | | SVU2-20/40 | A06B-6089-H205 | M axis |
| | | SVU2-40/40 | A06B-6089-H206 | L and M axes |
| | | SVU2-40/80 | A06B-6089-H207 | L axis |

| Servo motor | | Servo amplifier module (SVM)/ Servo amplifier unit (SVU) | | |
|---|----------------------------------|---|--|-----------------|
| Model name | Specification | Model name | Specification | Connection axis |
| α 12/2000 α C22/1500 (The SVU2 is unap- plicable to the α C22/1500.) | A06B-0142-B*** A06B-0145-B*** | SVM1-40L | A06B-6079-H104 A06B-6096-H104 | |
| | | SVM2-12/40 | A06B-6079-H204 A06B-6096-H204 | M axis |
| | | SVM2-20/40 | A06B-6079-H205 A06B-6096-H205 | M axis |
| | | SVM2-40/40 | A06B-6079-H206 A06B-6096-H206 | L axis |
| | | SVM2-40/80 | A06B-6079-H207 A06B-6096-H207 | L axis |
| | | SVM2-40L/40L | A06B-6079-H209 A06B-6096-H209 | L and M axes |
| | | SVM3-12/12/40 | A06B-6079-H305 A06B-6080-H305 A06B-6096-H305 | N axis |
| | | SVM3-12/20/40 | A06B-6079-H306 A06B-6080-H306 A06B-6096-H306 | N axis |
| | | SVM3-20/20/40 | A06B-6079-H307 A06B-6080-H307 A06B-6096-H307 | N axis |
| | | SVU1-40 | A06B-6089-H104 | |
| | | SVU2-12/40 | A06B-6089-H204 | M axis |
| | | SVU2-20/40 | A06B-6089-H205 | M axis |
| | | SVU2-40/40 | A06B-6089-H206 | L and M axes |
| SVU2-40/80 | A06B-6089-H207 | L axis | | |
| α 22/1500 | A06B-0146-B*** | SVM1-40L | A06B-6079-H104 A06B-6096-H104 | |
| | | SVM2-40/80 | A06B-6079-H207 A06B-6096-H207 | L axis |
| | | SVM2-40L/40L | A06B-6079-H209 A06B-6096-H209 | L, M axes |
| | | SVU1-40 | A06B-6089-H104 | |

| Servo motor | | Servo amplifier module (SVM)/ Servo amplifier unit (SVU) | | | |
|---|--|---|---|-----------------|--|
| Model name | Specification | Model name | Specification | Connection axis | |
| α 6/3000 α M6/3000 | A06B-0128-B*** A06B-0162-B*** | SVM1-80 | A06B-6079-H105 A06B-6096-H105 | | |
| | | SVM2-40/80 | A06B-6079-H207 A06B-6096-H207 | M axis | |
| | | SVM2-80/80 | A06B-6079-H208 A06B-6096-H208 | L and M axes | |
| | | SVU1-80 | A06B-6089-H105 | | |
| | | SVU2-40/80 | A06B-6089-H207 | M axis | |
| | | SVU2-80/80 | A06B-6089-H208 | L and M axes | |
| | | SVU2-12/80 | A06B-6089-H209 | M axis | |
| | | SVU2-20/80 | A06B-6089-H210 | M axis | |
| α 12/3000 α 22/2000 α 30/1200 α M9/3000 α L6/3000 α L9/3000 | A06B-0143-B*** A06B-0148-B*** A06B-0151-B*** A06B-0163-B*** A06B-0562-B*** A06B-0564-B*** | SVM1-80 | A06B-6079-H105 A06B-6096-H105 | | |
| | | SVM2-40/80 | A06B-6079-H207 A06B-6096-H207 | M axis | |
| | | SVM2-80/80 | A06B-6079-H208 A06B-6096-H208 | L and M axes | |
| | | SVU1-80 | A06B-6089-H105 | | |
| α 22/3000 α 30/2000 α 30/3000 α 40/2000 α 40/2000 (with FAN) α M22/3000 α M30/3000 α L25/3000 α L50/2000 | A06B-0148-B*** A06B-0152-B*** A06B-0153-B*** A06B-0157-B*** A06B-0158-B*** A06B-0165-B*** A06B-0166-B*** A06B-0571-B*** A06B-0572-B*** | SVM1-130 | A06B-6079-H106 A06B-6096-H106 | | |
| | | SVM2-40/80 | A06B-6079-H207 A06B-6096-H207 | M axis | |
| | | SVM2-80/80 | A06B-6079-H208 A06B-6096-H208 | L and M axes | |
| | | SVU1-80 | A06B-6089-H105 | | |
| | | SVU1-130 | A06B-6089-H106 | | |
| | | | | | |
| | | | | | |
| α M40/3000 | A06B-0169-B*** | SVM1-130 SVU1-130 | A06B-6079-H106 (Note 7) A06B-6096-H106 (Note 7) A06B-6089-H106 (Note 8) | | |
| α 65/2000 | A06B-0331-B*** | SVM1-240 | A06B-6079-H107 A06B-6096-H107 | | |
| α M40/3000 (with fan) α 100/2000 α 150/2000 | A06B-0170-B*** | SVM1-360 | A06B-6079-H108 A06B-6096-H108 | | |
| | A06B-0332-B*** A06B-0333-B*** | | | | |
| α 300/2000 α 400/2000 | A06B-0137-B*** A06B-0138-B*** | SVM1-360 2 modules /1motor | A06B-6079-H108 or A06B-6096-H108 | | |

| Servo motor | | Servo amplifier module (SVM)/ Servo amplifier unit (SVU) | | |
|--|--|---|------------------------------------|-----------------|
| Model name | Specification | Model name | Specification | Connection axis |
| α 3/3000HV α 6/3000HV | A06B-0171-B*** A06B-0172-B*** | SVM1-20HV | A06B-6085-H102 A06B-6097-H102 | |
| | | SVM2-20/20HV | A06B-6085-H201 A06B-6097-H201 | L and M axes |
| | | SVM2-20/40HV | A06B-6085-H202 A06B-6097-H202 | L axis |
| | | SVM2-20/60HV | A06B-6085-H203 A06B-6097-H203 | L axis |
| α 12/3000HV α M6/3000HV α M9/3000HV | A06B-0176-B*** A06B-0182-B*** A06B-0183-B*** | SVM1-40HV | A06B-6085-H103 A06B-6097-H103 | |
| | | SVM2-20/40HV | A06B-6085-H202 A06B-6097-H202 | M axis |
| | | SVM2-40/40HV | A06B-6085-H204 A06B-6097-H204 | L and M axes |
| | | SVM2-40/60HV | A06B-6085-H205 A06B-6097-H205 | L axis |
| α 22/3000HV α 30/3000HV α M22/3000HV α M30/3000HV | A06B-0177-B*** A06B-0178-B*** A06B-0185-B*** A06B-0186-B*** | SVM1-60HV | A06B-6085-H104 A06B-6097-H104 | |
| | | SVM2-20/60HV | A06B-6085-H203 A06B-6097-H203 | M axis |
| | | SVM2-40/60HV | A06B-6085-H205 A06B-6097-H205 | M axis |
| | | SVM2-60/60HV | A06B-6085-H207 A06B-6097-H207 | L and M axes |
| α 40/2000HV | A06B-0179-B*** | SVM1-80HV | A06B-6097-H105 | (Note 9) |
| α M40/3000HV | A06B-0189-B*** | SVM1-80HV | A06B-6097-H105 | (Note 9) |
| α 1000/2000HV | A06B-0131-B*** | SVM1-320HV 2 modules /1 motor | A06B-6097-H107 (FSSB interface) | |

| Servo motor | | Dynamic Brake modules(DBM) | |
|--|----------------------------------|----------------------------|----------------|
| Model name | Specification | Model name | Specification |
| α 300/2000 α 400/2000 | A06B-0137-B*** A06B-0138-B*** | DBM 2 modules /1 motor | A06B-6079-H401 |
| α 1000/2000HV | A06B-0131-B*** | DBM 2 modules /1 motor | A06B-6079-H401 |

CAUTION

- 1 If a motor is used in a combination other than those listed above, it may become broken.
- 2 For details on the servo amplifier module (SVM), refer to "FANUC Servo Amplifier α series Descriptions" (B-65162E).
- 3 For details on the servo amplifier unit (SVU), refer to "FANUC Servo Amplifier α series Descriptions" (B-65162E).
- 4 When using the α series servo amplifier modules for three axes (SVM3) on the B type interface CNC such as FS20 and FS21 series, the specification varies from one NC to another. Refer to "FANUC Control Servo Amplifier α series Descriptions" (B-65162E).
- 5 When the SVM-130 is used to drive the α 22/3000, α 30/3000, α 40/2000 (with fan), α M22/3000, α M30/3000, α L25/3000, or α L50/2000, it must be cooled by forced air flow.
- 6 When using C series servo amplifiers, consult with our service person.
- 7 The fan adapter (A06B-6078-K002) is necessary for each servo motor amplifier. Refer to "FANUC Servo Motor Amplifier α series Descriptions (B-65162E)".
- 8 SVU1-130 can be connected to NC through only TYPE A I/F or TYPE B I/F, and FSSB I/F is not available.
- 9 SVU1-80HV can be connected to NC through only FSSB I/F.

2.1.2 Data for Selecting PSM

| Motor model | Rating output | Maximum output at accelerating | |
|------------------------------|---------------|--------------------------------|--------|
| | | Case 1 | Case 2 |
| α M40/3000 | 3.0kW | 18.4kW | 20.7kW |
| α M40/3000 (with fan) | 10kW | 30.2kW | 34.0kW |
| α 300/2000 | 37kW | 82kW | 94kW |
| α 400/2000 | 40kW | 84kW | 96kW |
| α 40/2000HV | 5.9kW | 16.7kW | 18.8kW |
| α M40/3000HV | 3.0kW | 21.4kW | 24.0kW |
| α 1000/2000HV | 100kW | 168kW | 189kW |

For Cases 1 and 2, refer to motor power output list for selecting the power supply of the FANUC SERVO AMPLIFIER α series DESCRIPTIONS (B-65162E).

CAUTION

These data is only for selecting the PSM and it does not guarantee the power of motors.

When the one motor driven in the α 300/2000, α 400/2000, or α 1000/2000HV, the selection is as follows.

| Motor Model | Case 1 | Case 2 | Case (high frequency)(*) |
|----------------------|--------------------|--------------------|--------------------------|
| α 300/2000 | PSM30 \times 2 | PSM30 \times 2 | PSM37 \times 2 |
| α 400/2000 | PSM30 \times 2 | PSM30 \times 2 | PSM37 \times 2 |
| α 1000/2000HV | PSM75HV \times 2 | PSM75HV \times 2 | PSM75HV \times 2 |


CAUTION

(*) In the case of high frequently positioning such as press machine or positioning over 30 times per minute, the PSM should be selected with the following condition. "The continuous rating of the PSM should be under the 1.5 times to the amount of acceleration maximum of the same time moving axis".


2.2 INSTALLATION

The servo motor contains a precision detector, and is carefully machined and assembled to provide the required precision. Pay attention to the following items to maintain the precision and prevent damage to the detector.


- Secure the servo motor uniformly using four bolt holes provided on the front flange.



- Ensure that the surface on which the machine is mounted is sufficiently flat.
- When mounting on the machine, take care not to apply a shock to the motor.




- When it is unavoidable to tap the motor for adjusting the position, etc., use a plastic hammer and tap only the front flange if possible.




2.3 COUPLING

A precision detector is directly connected to the servo motor shaft. Pay attention to the following items to prevent damage to the detector.


- When connecting the power transmission elements such as a gear, a pulley and a coupling to the shaft, take care not to apply a shock to the shaft.




- Generally, in the case of straight shaft, use a span ring for connection with the shaft.
- In the case of tapered shaft, match the tapered surface with the power transmission element and fix by tightening the screw at the end. When the woodruff key is too tight, don't tap it with a hammer. Use the woodruff key mainly for positioning, and use the tapered surface for torque transmission. Machine the tapered surface of the power transmission element so that over 70% of the whole surface is contacted.



- To remove the connected power transmission element, be sure to use a jig such as a gear puller.



- When tapping slightly to remove the tightly contacted tapered surface, tap in the radial direction to prevent a shock in the axial direction.



- Suppress the rotary unbalance of the connected power transmission element to the level as low as possible. It is usually believed that there is no problem in the symmetrical form. Be careful when rotating continuously the asymmetrical different form power transmission element. Even if the vibration caused by the unbalance is as small as 0.5G, it may damage the motor bearing or the detector.

An exclusive large oil seal is used in the front flange of the models $\alpha 3$ to $\alpha 40$.

The oil seal surface is made of steel plate. Take care not to apply a force to the oil seal when installing the motor or connecting the power transmission elements.

2.4 AXIS LOAD

The allowable axis load of the motor shaft is as follows.

| Motor model | Radial load | Axial load | Front bearing (reference) |
|--|-------------|------------|---------------------------|
| α 1/2 α M2/2.5 | 25 [kgf] | 8 [kgf] | 6003 |
| α 3/6 α M6/9 α L6/9 α C3/6 α 3/6HV α M6/9HV | 70 [kgf] | 20 [kgf] | 6205 |
| α 12/22/30/40 α M22/30/40/40 (with fan) α L25/50 α C12/22 α 12/22/30/40HV α M22/30/40HV | 450 [kgf] | 135 [kgf] | 6208 |
| α 65/100/150 | 900 [kgf] | 250 [kgf] | 6312 |
| α 300/400 | 1200 [kgf] | 200 [kgf] | NU2214 |
| α 1000 | 1400 [kgf] | 200 [kgf] | 6317 Combination bearing |


The above values are the reference assuming the use as a feed axis on the typical machine tool.

- The allowable radial load is the value when a load is applied to the shaft end. It indicates the total continuous force applied to the shaft in some methods of mounting (e.g, belt tension) and the force by load torque (e.g., moment/pulley radius).
- The belt tension is critical particularly when a timing belt is used. Too tight belt causes breakage of the shaft or other fault. Belt tension must be controlled so as not to exceed the limits calculated from the permissible radial load indicated above.
- In some operation conditions, the pulley diameter and the gear size need to be checked. For example, when using the model α 3 with a pulley/gear with the radius of 2.5cm or less, the radial load at the occurrence of 180kg·cm torque will exceed 70kg. In the case of timing belt, as the belt tension is added to this value, it is thus necessary to support the shaft end.
- Actually, when using a timing belt, a possible fault like a broken shaft can be prevented by positioning the pulley as close to the bearing as possible.
- When there is a possibility of a large load, the machine tool builder needs to examine the life by referring to the shaft diameter, bearing, etc.
- Since the standard single row deep groove ball bearing is used for the motor bearing, a very large axial load can not be used. Particularly, when using a worm gear and a helical gear, it is necessary to provide another bearing.
- The motor bearing is generally fixed with a C-snap ring, and there is a small play in the axial direction. When this play influences the positioning in the case of using a worm gear and a helical gear, for example, it is necessary to fix it with another bearing.

2.5 ENVIRONMENT

Ambient temperature

The ambient temperature should be 0°C to 40°C. When operating the machine at a higher temperature, it is necessary to lower the output power so that the motor temperature does not exceed the specified constant value. (The values in the data sheet are determined for an ambient temperature of 20°C.)



Vibration

When installed in a machine, the vibration applied to the motor must not exceed 5G.

Installation height


Up to 1,000 meters above the sea level requires, no particular provision for attitude. When operating the machine at a higher level, special care is unnecessary if the ambient temperature is lowered 1°C at every 100m higher than 1,000m. For example, when the machine is installed at a place of 1,500 meters above sea level, there is no problem if the ambient temperature is 35°C or less. For higher temperatures, it is necessary to limit the output power.

If any one of the three environmental conditions specified above is not satisfied, the output must be restricted.


Drip-proof environment

The level of motor protection is such that a single motor unit can satisfy IP65 of the IEC standard. (The connector section for the fan of fan-equipped models is excluded.) However, this standard relates only to short-term performance. So, note the following when using the motor in actual applications:

- Protect the motor surface from the cutting fluid or lubricant. Use a cover when there is a possibility of wetting the motor surface. Only the telescopic cover of the sliding part can not completely prevent leakage of the cutting fluid. Pay attention to the drop along the structure body, too.




- Prevent the cutting fluid from being led to the motor through the cable. When the motor connector is used in the up position, put a drip loop in the cable.



- When the motor connector is up, the cutting fluid is collected in the cable connector through the cable. Turn the motor connector sideways or downward as far as possible. Most of the defects caused by the cutting fluid have occurred in the cable connector.

The standard receptacle on the motor side is waterproof. If the cable connector will be subjected to moisture, it is recommended that an R class or waterproof plug be used. Suitable plugs are listed in the cable plug combination recommendations in Chapter 8. (The standard MS plug is not waterproof; water is liable to enter the pin section.)




Shaft attachment section requirements

The motor shaft is sealed to prevent penetration of oil into the motor housing. However, sealing may not be perfect under severe working conditions.

When oil bath lubrication is provided for the gear engagement, for example, the oil level must be below the lip of the shaft's oil seal. Set the oil level so that oil merely splashes the lip. Thus, as the shaft rotates, the oil seal can repel oil. If, however, pressure is applied continuously while the shaft is stopped, oil may penetrate the lip. When the shaft is always immersed in oil, for example, under the condition that the motor is to be used with the shaft oriented vertically a special design is required. For example, another oil seal could be installed on the machine side, and a drain provided so that oil penetrating that seal can drain off.

When grease is used for lubrication, the oil seal characteristics are usually lost.

In either case, ensure that no pressure is applied to the oil seal lip.



The motor shaft oil seal diameter is as shown below.

| Motor mode | Oil seal diameter |
|--|-------------------|
| α 1/2 α M2/2.5 | ϕ 15 [mm] |
| α 3/6 α M6/9 α L6/9 α C3/6 α 3/6HV α M6/9HV | ϕ 24 [mm] |
| α 12/22/30/40 α M22/30/40 α L25/50 α C12/22 α 12/22/30/40HV α M22/30/40HV | ϕ 35 [mm] |
| α 65/100/150 | ϕ 60 [mm] |
| α 300/400 | ϕ 70 [mm] |
| α 1000HV | ϕ 85 [mm] |

2.6 ACCEPTANCE AND STORAGE

When the servo motor is delivered, check the following items.

- The motor meets the specifications.
(Specifications of the model/shaft/detector)
- Damage caused by the transportation.
- The shaft is normal when rotated by hand.
- The brake works.
- Looseness or play in screws.

FANUC servo motors are completely checked before shipment, and the inspection at acceptance is normally unnecessary. When an inspection is required, check the specifications (wiring, current, voltage, etc.) of the motor and detector.

Store the motor indoors. The storage temperature is -20°C to $+60^{\circ}\text{C}$. Avoid storing in the following places.

- Place with high humidity so condensation will form.
- Place with extreme temperature changes.
- Place always exposed to vibration.
(The bearing may be damaged.)
- Place with much dust.

3

INSTRUCTIONS



3.1 DRIVE SHAFT COUPLING

There are four methods for connecting the motor shaft to the ball screw:

- Direct connection through a flexible coupling
- Direct connection through a rigid coupling
- Connection through gears
- Connection through timing belts

It is important to understand the advantages and disadvantages of each method, and select one that is most suitable for the machine.

Direct connection using a flexible coupling

Direct connection by a flexible coupling has the following advantages over connection using gears:

- Even if the angle of the motor shaft to the ball screw changes, it can be compensated to a certain extent.
- Because a flexible coupling connects elements with less backlash, driving noise from joints can be significantly suppressed.


However, this method has the following disadvantages:

- The motor shaft and the ball screw must not slide from each other in the radial direction (for single coupling).
- Loose assembly may result in lower rigidity.

When the motor shaft needs to be connected directly to the ball screw, connecting them using a flexible coupling facilitates adjustment and installation of the motor.

To use a single coupling, the machine needs to be designed so that the centers of the motor shaft and the ball screw are aligned. (In the same way as with a rigid coupling, the use of a single coupling demands that there be almost no relative eccentricity between the axes.)

If it is difficult to align the centers, a double coupling needs to be employed.



Direct connection using a rigid coupling

Direct connection using a rigid coupling has the following advantages over direct connection using a flexible coupling:

- More economical
- The coupling rigidity can be increased.
- If the rigidity is the same as with a flexible coupling, the inertia can be reduced.

However, this method has the following disadvantages:

- The motor shaft and the ball screw must not slide from each other in the radial direction, and the angle of the motor shaft to the ball screw must be fixed.

For this reason, a rigid coupling needs to be mounted very carefully. It is desirable that the run-out of the ball screw is 0.01 mm or less. When a rigid coupling is used on the motor shaft, the run-out of the hole for the ball screw must be set to 0.01 mm or less by adjusting the tightness of the span ring.

The run-out of the motor shaft and the ball screw in the radial direction can be adjusted or compensated to a certain extent by deflection. Note, however, that it is difficult to adjust or measure changes in the angle. Therefore, the structure of the machine should be such that precision can be fully guaranteed.

Gears

This method is used when the motor cannot be put in line with the ball screw because of the mechanical interference problem or when the reduction gear is required in order to obtain large torque. The following attention should be paid to the gear coupling method:

- Grinding finish should be given to the gear, and eccentricity, pitch error, tooth-shape deviations etc. should be reduced as much as possible. Please use the JIS, First Class as a reference of precision.
- Adjustment of backlash should be carefully performed. Generally, if there is too little backlash, a high-pitched noise will occur during high-speed operation, and if the backlash is too big, a drumming sound of the tooth surfaces will occur during acceleration/deceleration. Since these noises are sensitive to the amount of backlash, the structure should be so that adjustment of backlash is possible at construction time.

Timing belt

A timing belt is used in the same cases as gear connection, but in comparison, it has advantages such as low cost and reduced noise during operation, etc. However, it is necessary to correctly understand the characteristics of timing belts and use them appropriately to maintain high precision.

Generally, the rigidity of timing belt is sufficiently higher than that of other mechanical parts such as ball screw or bearing, so there is no danger of inferiority of performance of control caused by reduction of rigidity by using timing belt. When using a timing belt with a position detector on the motor shaft, there are cases where poor precision caused by backlash of the belt tooth and pulley tooth, or elongation of belt after a long time becomes problem, so consideration should be given to whether these errors significantly affect precision. In case the position detector is mounted behind the timing belt (for example, on the ball screw axis), a problem of precision does not occur.

Life of the timing belt largely varies according to mounting precision and tension adjustment. Please refer to the manufacturer's Instruction Manual for correct use.

Connection between the straight shaft and a connecting element

To use a straight shaft that has no key groove, connect the shaft with a coupling using a span ring.

Because the span ring connects elements by the friction generated when the screw is tightened, it is free from backlash and the concentration of stress. For this reason, the span ring is highly reliable for connecting elements.

To assure sufficient transmission with the span ring, factors such as the tightening torque of the screw, the size of the screw, the number of screws, the clamping flange, and the rigidity of connecting elements are important. Refer to the manufacturer's specifications before using the span ring.

When a coupling or gear is mounted using the span ring, tighten the screws to remove a run-out of the coupling or gear including the shaft.

3.2 MACHINE MOVEMENT PER 1 REVOLUTION OF MOTOR SHAFT

The machine movement per 1 revolution of motor shaft must be determined at the first stage of machine design referring the load torque, load inertia, rapid traverse speed, and relation between minimum increment and resolution of the position sensor mounted on the motor shaft. To determine this amount, the following conditions should be taken into consideration.

- The machine movement per 1 revolution of motor shaft (“L”) must be such that the desired rapid traverse speed can be obtained. For example, if the maximum motor speed is 1500 min^{-1} and the rapid traverse speed must be 12 m/min. , the amount of “L” must be 8 mm/rev. or higher.
- As the machine movement per 1 revolution of motor shaft is reduced, both the load torque and the load inertia reflected to motor shaft also decrease.

Therefore, to obtain large thrust, the amount of “L” should be the lowest value at which the desired rapid traverse speed can be obtained.

- Assuming that the accuracy of the reduction gear is ideal, it is advantageous to make the machine movement per 1 rev. of motor shaft as low as possible to obtain the highest accuracy in mechanical servo operations. In addition, minimizing the machine movement per 1 rev. of motor shaft can increase the servo rigidity as seen from the machine’s side, which can contribute to system accuracy and minimize the influence of external load changes.
- When the machine is operation is characterized by repeated acceleration/deceleration cycles, a heating problem may occur due to the current flow caused by the acceleration and deceleration. Should this occur, the machine travel distance per motor shaft revolution should be modified. Given optimum conditions, the machine travel distance per motor shaft revolution is set such that the motor’s rotor inertia equals the load inertia based on motor shaft conversion. For machines such as punch presses and PCB drilling machines, the machine’s travel distance per motor shaft revolution should be set so as to satisfy this optimum condition as far as possible, while also considering the rapid traverse rate and increment system.

4

SELECTING A MOTOR

When selecting an applicable motor, the load, rapid traverse feedrate, increment system, and other conditions must be considered. This section describes how to calculate the load and other conditions, showing an example of a table with a horizontal axis.

Motors are subjected to two types of torque: constant load torque (including friction), and cutting power and acceleration/deceleration torque. Calculate the two loads accurately and select a motor that satisfies the following conditions:

Condition 1

When the machine is operating without any load, the torque is within about 70% of the continuous torque rating.

When the machine tool is stopped, the motor is generating torque in a balanced state with the friction-induced load. If acceleration/deceleration torque required for actual operation is added when this value is close to the rated torque, the rated torque may be exceeded as the average torque, and the motor is more likely to overheat.

This figure of “within 70% of the continuous torque rating” is for reference only. Determine the appropriate torque based upon actual machine tool conditions.

Condition 2

Acceleration can be made with a desired time constant.

Generally, the load torque helps deceleration. If acceleration can be executed with a desired time constant, deceleration can be made with the same time constant. Calculate the acceleration torque and check that the torque required for acceleration is within the intermittent operating zone of the motor.

Condition 3

The frequency of positioning in rapid traverse is set to a desired value. The greater the frequency of positioning in rapid traverse, the greater the ratio of acceleration time to the entire operation time. This may overheat the motor. When the acceleration time constant is increased according to the rapid traverse feedrate and positioning frequency constant, the amount of produced heat decreases in inverse proportion to the acceleration time constant.

Condition 4

If the load condition varies during a single cycle, the root-mean-square value of the torques is smaller than or equal to the rated torque.


Condition 5

The time for which the table can be moved with the maximum cutting torque (percentage duty cycle and ON time) is within a desired range.

The procedure for selecting a motor is described below:

4.1 CALCULATING CONDITIONS FOR SELECTING A MOTOR

This section describes the procedure for selecting a servo motor best suited for a table with a horizontal axis (figure below).



Sample mechanical specifications of the table and workpiece

- W : Weight of movable parts (table and workpiece) = 1000 (kgf) = 98000 (N)
 w : Weight of movable parts (table and workpiece) = 1000 (kg)
 μ : Friction coefficient of the sliding surface = 0.05
 η : Efficiency of the driving system (including a ball screw) = 0.9
 fg : Gib fastening force (kgf) = 50 (kgf) = 490 (N)
 Fc : Thrust counter force caused by the cutting force (kgf) = 100 (kgf) = 980 (N)
 Fcf : Force by which the table is pressed against the sliding surface, caused by the moment of cutting force = 30 (kgf) = 294 (N)
 Z_1/Z_2 : Gear reduction ratio = 1/1

Sample specifications of the feed screw (ball screw)

- D_b : Shaft diameter = 32 (mm) = 32×10^{-3} (m)
 L_b : Shaft length = 1000 (mm) = 1 (m)
 P : Pitch = 8 (mm) = 8×10^{-3} (m)

Sample specifications of the operation of the motor shaft

- T_a : Acceleration torque (kgf·cm) (Nm)
 V_m : Motor speed in rapid traverse = 3000 (min^{-1}) = 50 (s^{-1})
 t_a : Acceleration time (s) = 0.10 (s)
 J_M : Motor inertia (kgf·cm·sec²) (kg·m²)
 J_L : Load inertia (kgf·cm·sec²) (kg·m²)
 ks : Servo position loop gain = 30 (s^{-1})

4.1.1 Calculating the Load Torque and Load Inertia

Calculating the load torque

The load torque applied to the motor shaft is generally given by the following equation:

$$T_m = \frac{F \times L}{2\pi\eta} + T_f$$

T_m : Load torque applied to the motor shaft

F : Force required to move a movable part (table or tool post) along the axis

L : Traveling distance of the machine tool per revolution of the motor = $P \times (Z1/Z2)$

T_f : Friction torque of the nut of the ball screw or bearing applied to the motor shaft (input if necessary)

F depends on the weight of the table, friction coefficient, whether cutting is in progress, and whether the axis is horizontal or vertical. If the axis is vertical, F also depends on the presence of a counterbalance. For a table with a horizontal axis, F is calculated as follows:

When $T_f = 2$ (kgf·cm) = 0.2 (Nm)

When cutting is not executed:

$$F = \mu (W + fg)$$

Example)

$$F = 0.05 \times (1000 + 50) = 52.5 \text{ (kgf)} = 514.5 \text{ (N)}$$

$$T_m = (52.5 \times 0.8) / (2 \times \pi \times 0.9) + 2 = 9.4 \text{ (kgf·cm)} = 0.92 \text{ (Nm)}$$

When cutting is in progress:

$$F = F_c + \mu (W + fg + F_c f)$$

Example)

$$F = 100 + 0.05 \times (1000 + 50 + 30) = 154 \text{ (kgf·cm)} = 1509 \text{ (N)}$$

$$T_{mc} = (154 \times 0.8) / (2 \times \pi \times 0.9) + 2 = 23.8 \text{ (kgf·cm)} = 2.3 \text{ (Nm)}$$


To satisfy condition 1, check the data sheet and select a motor whose load torque (rated torque at stall) when cutting is not executed is 0.92 (Nm) or higher and the maximum speed is 3000 (min^{-1}) or higher. Considering the acceleration/deceleration conditions, provisionally select $\alpha 2/3000$ (rated torque at stall is 2.0 (Nm)).

• Cautions

When calculating the torque, take the following precautions:

- Allow for the friction torque caused by the gib fastening force (fg). The torque calculated only from the weight of a movable part and the friction coefficient is generally quite small. The gib fastening force and precision of the sliding surface may have a great effect on the torque.
- The pre-load of the bearing or nut of the ball screw, pre-tension of the screw, and other factors may make T_c of the rolling contact considerable. In a small, lightweight machine tool, the friction torque will greatly affect the entire torque.

- Allow for an increase in friction on the sliding surface (F_{cf}) caused by the cutting resistance. The cutting resistance and the driving force generally do not act through a common point as illustrated below. When a large cutting resistance is applied, the moment increases the load on the sliding surface. When calculating the torque during cutting, allow for the friction torque caused by the load.




- The feedrate may cause the friction torque to vary greatly. Obtain an accurate value by closely examining variations in friction depending on variations in speed, the mechanism for supporting the table (sliding contact, rolling contact, static pressure, etc.), material of the sliding surface, lubricating system, and other factors.
- The friction torque of a single machine varies widely due to adjustment conditions, ambient temperature, and lubrication conditions. Collect a great amount of measurement data of identical models so that a correct load torque can be calculated. When adjusting the gib fastening force and backlash, monitor the friction torque. Avoid generating an unnecessarily great torque.

Calculating the load inertia

Unlike the load torque, an accurate load inertia can be obtained just by calculation. The inertia of all objects moved by the revolution of a driving motor forms the load inertia of the motor. It does not matter whether the object is rotated or moved along a straight line. Calculate the inertia values of individual moving objects separately, then add the values together, according to a rule, to obtain the load inertia. The inertia of almost all objects can be calculated according to the following basic rules:

- **Inertia of a cylindrical object (ball screw, gear, coupling, etc.)**



The inertia of a cylindrical object rotating about its central axis is calculated as follows:

$$J_b = \frac{\pi\gamma_b}{32 \times 980} D_b^4 L_b \text{ (kgf}\cdot\text{cm}\cdot\text{s}^2)$$

J_b : Inertia (kgf·cm·s²)

γ_b : Weight of the object per unit volume (kg/cm³)

D_b : Diameter of the object (cm)

L_b : Length of the object (cm)

SI unit

$$J_b = \frac{\pi\gamma_b}{32} D_b^4 L_b \text{ (kgf}\cdot\text{m}^2)$$

J_b : Inertia (kgf·m²)

γ_b : Weight of the object per unit volume (kg/cm³)

D_b : Diameter of the object (m)

L_b : Length of the object (m)

Example)

When the shaft of a ball screw is made of steel ($g = 7.8 \times 10^3$ (kg/m³)), inertia J_b of the shaft is calculated as follows:

$$J_b = 7.8 \times 10^3 \times \pi \div 32 \times 0.032^4 \times 1 = 0.0008 \text{ [kg}\cdot\text{m}^2] \\ (=0.0082 \text{ [kg}\cdot\text{cm}\cdot\text{s}^2])$$

- Inertia of a heavy object moving along a straight line (table, workpiece, etc.)

$$J = \frac{W}{980} \times \left(\frac{L}{2\pi}\right)^2 \text{ (kgf}\cdot\text{cm}\cdot\text{s}^2)$$

W : Weight of the object moving along a straight line (kg)

L : Traveling distance along a straight line per revolution of the motor (cm)

SI unit

$$J = W \times \left(\frac{L}{2\pi}\right)^2 \text{ (kgf}\cdot\text{cm}\cdot\text{s}^2)$$

W : Weight of the object moving along a straight line (kg)


L : Traveling distance along a straight line per revolution of the motor (cm)

Example)

When W is 1000(kg) and L is 8(mm), J_w of a table and workpiece is calculated as follows:

$$J_w = 1000 \times (0.008 \div 2 \div \pi)^2 = 0.00162 \text{ (kg}\cdot\text{m}^2) = 0.0165 \text{ (kgf}\cdot\text{cm}\cdot\text{s}^2)$$

- Inertia of an object whose speed is increased above or decreased below the speed of the motor shaft



The inertia applied to the motor shaft by inertia \$J_0\$ is calculated as follows:


$$J = \left(\frac{Z_1}{Z_2}\right)^2 \times J_0 \quad (Z_1, Z_2 : \text{Number of teeth when the gear connection})$$

or

$$J = \left(\frac{1}{Z}\right)^2 \times J_0 \quad \left(\frac{1}{Z} : \text{Deceleration ratio}\right)$$

\$J_0\$: Inertia before the speed is changed

- Inertia of a cylindrical object in which the center of rotation is displaced



$$J = J_0 + MR^2 \quad (\text{kgf}\cdot\text{cm}\cdot\text{s}^2)$$

\$J_0\$: Inertia around the center of the object
 \$M\$: Weight of the object
 \$R\$: Radius of rotation

The above equation is used to calculate the inertia of, for example, a large gear which is hollowed out in order to reduce the inertia and weight. The sum of the inertia values calculated above is \$J\$ (load inertia) for accelerating the motor.

In this example, the sum of \$J_b\$ and \$J_w\$ obtained in above is load inertia \$J_L\$.
 $J_L = 0.000803 + 0.00162 = 0.00242 \text{ (kgf}\cdot\text{m}^2)$

- **Note** **Limitations on load inertia**

The load inertia has a great effect on the controllability of the motor as well as the time for acceleration/deceleration in rapid traverse. When the load inertia is increased, the following two problems may occur: When a command is changed, it takes more time for the motor to reach the speed specified by the new command. When a machine tool is moved along two axes at a high speed to cut an arc or curve, a larger error occurs.

When the load inertia is smaller than or equal to the rotor inertia of the motor, those problems will not occur. When the load inertia is up to three times the rotor inertia, the controllability may have to be lowered a little. Actually, this will not adversely affect the operation of an ordinary metal cutting machine. If a router for woodworking or a machine to cut a curve at a high speed is used, it is recommended that the load inertia be smaller than or equal to the rotor inertia.

When the load inertia is greater than the rotor inertia by a factor of more than 3 to 5, the controllability of the motor will be adversely affected. If the load inertia much larger than three times the rotor inertia, an adjustment in the normal range may be insufficient. Avoid using a machine with such a great load inertia.


4.1.2 Calculating the Acceleration Torque

Calculating acceleration torque : Procedure 1

Following the procedure described below, calculate the torque required for acceleration:

Assuming that the motor shaft operates ideally in the acceleration/deceleration mode determined by the NC, calculate the acceleration. Multiply the acceleration by the entire inertia (motor inertia + load inertia). The product is the acceleration torque. The equation is given below.

- In linear acceleration/deceleration



$$T_a = V_m \times 2\pi \times \frac{1}{t_a} \times J_M \times (1 - e^{-k_s \cdot t_a})$$

$$+ V_m \times 2\pi \times \frac{1}{t_a} \times J_L \times (1 - e^{-k_s \cdot t_a}) \div \eta$$

$$V_r = V_m \times \left\{ 1 - \frac{1}{t_a \cdot k_s} (1 - e^{-k_s \cdot t_a}) \right\}$$

T_a : Acceleration torque

V_m : Motor speed in rapid traverse

t_a : Acceleration time

J_M : Motor inertia

J_L : Load inertia

V_r : Point from which the acceleration torque starts to decrease

k_s : Servo position loop gain

η : Machine tool efficiency

Example)

Try to perform linear acceleration/deceleration under the following condition.


$$V_m = 3000 \text{ (min}^{-1}\text{)} = 50 \text{ (s}^{-1}\text{)}, t_a = 0.1 \text{ (s)}, k_s = 30 \text{ (s}^{-1}\text{)},$$

$$J_L = 0.0247 \text{ (kgf}\cdot\text{cm}\cdot\text{s}^2\text{)}$$

Select $\alpha 2/3000$, and calculate its acceleration torque.

J_M motor inertia is 0.0056 (kgf·cm·s²) when $\alpha 2/3000$ is selected, so the load inertia is calculated as follows:

$$\begin{aligned} T_a &= 50 \times 2\pi \times 1/0.1 \times 0.0056 \times (1 - e^{-30 \times 0.1}) \\ &\quad + 50 \times 2\pi \times 1/0.1 \times 0.0247 \times (1 - e^{-30 \times 0.1}) \div 0.9 \\ &= 98.6 \text{ (kgf}\cdot\text{cm)} = 9.67 \text{ (Nm)} \end{aligned}$$



The speed–torque characteristics of $\alpha 2/3000$ show that the acceleration torque of 9.67 (Nm) is beyond the intermittent operating zone of $\alpha 2/3000$ (see the characteristic curve above and data sheet). (The torque is insufficient for $\alpha 2/3000$.)

If the operation specifications of the shaft (for instance, the acceleration time) cannot be changed, a larger motor must be selected. Select an $\alpha 3/3000$ (J_M is 0.014 (kgf·cm·s²)) and calculate the acceleration torque again.

$$T_a = 123.7 \text{ (kg}\cdot\text{cm)} = 12.1 \text{ (Nm)}$$

$$V_r = 2050 \text{ (min}^{-1}\text{)}$$

In acceleration, an acceleration torque of 12.1 (Nm) is required at 2050 (min⁻¹). The speed–torque characteristic curve shown above shows that the acceleration is possible with $\alpha 3/3000$.

As $\alpha 2/3000$ is changed to $\alpha 3/3000$, the size of the attachment flange is increased from 90 mm × 90 mm to 130 mm × 130 mm. If the machine tool does not allow a larger motor, the specifications must be changed. For example, the acceleration time must lengthen.

Calculating acceleration torque : Procedure 2

To obtain T (torque) required by the motor shaft, add T_m (friction torque) to T_a acceleration torque.

$$T = T_a + T_m$$

$$T = 12.1(\text{Nm}) + 0.9(\text{Nm}) = 13.0(\text{Nm})$$

Calculating acceleration torque : Procedure 3

Check that T obtained in Procedure 2 above is smaller than or equal to the maximum torque. Using the speed–torque characteristic curve on the data sheet of the corresponding motor, check that T obtained in Procedure 1 above is within the intermittent operating zone at V_r .


As V_r is $2050 (\text{min}^{-1})$ and T is $13.0 (\text{Nm})$, the acceleration is possible with the specified time constant (condition 2).

4.1.3 Calculating the Root-mean-square Value of the Torques

Calculating the frequency of positioning in rapid traverse

Generate an operation cycle which includes rapid traverse. Write the time-speed graph and time-torque graph as shown below.

In a common cutting machine, the frequency of positioning in rapid traverse will cause no problems. In a special machine tool which frequently executes rapid traverse, however, the motor must be checked to see whether it is overheated by the current required for acceleration or deceleration.



From the time-torque graph, obtain the root-mean-square value of torques applied to the motor during the single operation cycle. Check whether the value is smaller than or equal to the rated torque (condition 3).

$$Trms = \sqrt{\frac{(Ta + Tm)^2 t_1 + Tm^2 t_2 + (Ta - Tm)^2 t_1 + To^2 t_3}{t_o}}$$

Ta : Acceleration torque

Tm : Friction torque

To : Torque when stopped

If Trms is smaller than or equal to 90% of the rated torque at stall (Ts), the motor is judged to be usable.

(A margin including the overall thermal efficiency is considered.)

Example)


When an $\alpha 3/3000$ ($T_s = 31$ (kgf·cm) = 3.0 (Nm)) is used under the following conditions: $T_a = 12.1$ (Nm), $T_m = T_o = 0.9$ (Nm), $t_1 = 0.1$ (s), $t_2 = 1.8$ (s), $t_3 = 7.0$ (s)

$$\begin{aligned} Trms &= \sqrt{\frac{(12.1 + 0.9)^2 \times 0.1 + 0.9^2 \times 1.8 + (12.1 - 0.9)^2 \times 0.1 + 0.9^2 \times 7}{t_o}} \\ &= 20.2(\text{Nm}) < T_s \times 0.9 = 2.9 \times 0.9 = 2.61(\text{Nm}) \end{aligned}$$

The $\alpha 3/3000$ can be used for operation. (Condition 3)

Calculating the torque in a cycle in which the load varies

If the load conditions (cutting load, acceleration/deceleration conditions, etc.) vary widely in a single cycle, write a time-torque graph according to the operation cycle, as in above item. Obtain the root-mean-square value of the torques and check that the value is smaller than or equal to the rated torque (condition 4).



$$T_{rms} = \sqrt{\frac{T_1^2 t_1 + T_2^2 t_2 + T_3^2 t_3 + \dots + T_n^2 t_n}{t_o}}$$

t_o = t₁ + t₂ + ... + t_n

NOTE
 When the motor is being operated at high speed for a comparatively large proportion of the time, you must take the rotating speed of the motor into consideration and evaluate whether output can be specified in terms of a continuous operation torque.

4.1.4 Calculating the Percentage Duty Cycle with the Maximum Cutting Torque

Check that the time for which the table can be moved with the maximum cutting torque, T_{mc} , (percentage duty cycle and ON time) is within a desired range of cutting time. (Condition 5)

If T_{mc} (maximum load torque) applied to the motor shaft during cutting, which is obtained in Subsec. 4.1.1, is smaller than the product of rated torque at stall of the motor (T_c) and α (thermal efficiency), the motor can be used in continuous cutting. If T_{mc} is greater than the product ($T_{mc} > T_c \times \alpha$), follow the procedure below to calculate the percentage ratio of time (t_{ON}) T_{mc} can be applied to the motor to total time (t) of a single cutting cycle. (α is assumed to be 0.9. Calculate the percentage considering the specifications of the machine.)

$T_{mc} < T_c \times \alpha$... Operation can be continued with the maximum cutting torque. (The percentage duty cycle with the maximum cutting torque is 100%.)

$T_{mc} > T_c \times \alpha$... Calculate the percentage duty cycle, according to the following figure and expressions.

Example)

As calculated in Subsec. 4.1.1,


$T_{mc} = 21.8$ (kgf-cm) = 2.1 (Nm)

$\alpha_{3/3000}: T_c = 31$ (kgf-cm) = 3.0 (Nm)

$T_c \times \alpha = 3.0 \times 0.9 = 2.7$ (Nm) $> T_{mc} = 2.1$ (Nm)

No problems will occur in continuous cutting.

Calculating the percentage duty cycle with the maximum cutting torque



Calculate the root-mean-square value of torques applied in a single cutting cycle as described in Subsec 4.1.3. Specify t_{ON} and t_{OFF} so that the value does not exceed the product of rated torque at stall of the motor (T_c) and thermal efficiency (α). Then, calculate the percentage duty cycle with the maximum cutting torque as shown below.

Percentage duty cycle with the maximum cutting torque (T_{mc}) = $\frac{t_{ON}}{t_{ON} + t_{OFF}} \times 100(\%)$

Example)

Assume that T_{mc} is 4.0(Nm) ($T_m = 0.9(\text{Nm})$).

$$\sqrt{\frac{4.0^2 \times t_{ON} + 0.9^2 \times t_{OFF}}{t_{ON} + t_{OFF}}} < 2.7(\text{Nm}) \quad (90\% \text{ of rated torque of } \alpha 3/3000)$$

Therefore,

$$\frac{t_{ON}}{t_{OFF}} < \frac{1}{1.3}$$

The ratio of non-cutting time to cutting time must be 1.3 or greater.

The percentage duty cycle is calculated as follows:

$$\frac{t_{ON}}{t_{ON} + t_{OFF}} \times 100 = 43.5\%$$

Finally, the $\alpha 3/3000$ that satisfies conditions 1 to 5 is selected.


- **Limitations on ON time**

The period during which continuous operation under an overload is allowed is also restricted by the OVC alarm level and overload duty cycle characteristics.

4.2 PRECAUTIONS FOR USING LINEAR SCALE

Machine system natural frequency

In the case where the machine moves in a linear direction and movement is directly detected by linear scale such as inductosyn, magne-scale etc., special considerations are necessary in comparison with the method where feedback is produced by detecting the motor shaft rotation. This is because the machine movement now directly influences the characteristics of the control system.



This method is shown in the figure above by block diagram. The response of this control system is determined by the adjustment value (position loop gain) of the position control circuit. In other words, the position loop gain is determined by the specified response time of the control system. In the diagram above, the section enclosed by the broken line is called the velocity loop. Unless the response time of this section where position signal is detected is sufficiently shorter than the response time determined by the position loop gain, the system does not operate properly. In other words, when a command signal is put into point A, response time of the machine where position signals are detected must be sufficiently shorter than the response time defined by the position loop gain.

When the response of the detector section is slow, the position loop gain must be reduced to have the system operate normally, and as a result, the response of the whole system is slow. The same problem is caused when inertia is great (see Subsec. 4.1.1)).

The main causes for slow response are the mass of the machine and the elastic deformation of the machine system. The larger the volume, and the greater the elastic deformation, the slower the response becomes.

As an index for estimating the response of this machine system, the natural frequency of the machine is used, and this is briefly calculated by the following equation.

$$W_m = \frac{1}{2\pi} \times \sqrt{\frac{K_m}{JL}}$$

W_m : Natural frequency

JL : Load inertia reflected to motor shaft

K_m : Rigidity of machine system


(=Torque necessary to elastically deform 1 [rad] at the motor shaft when the machine table is clamped.)

The above values can be obtained by calculating the elastic deformation for each section of the driving system. If the value of this natural frequency (Hz) is more than the value of position loop gain (sec^{-1}), it operates normally in most cases. That is to say, when setting 20 (sec^{-1}) as the value of position loop gain, natural frequency of machine system must be more than 20 (Hz). In this case, attention must be paid to the fact that response becomes a problem for extremely small amounts of movement.

Consequently, the natural frequency should be calculated from the rigidity at extremely small displacement such as less than 10 μm .

Stick slip

If machine movement causes a stick slip, the control system does not operate normally. That is, it does not stop where it is supposed to, but a phenomenon occurs where it goes beyond and then back within an extremely small range (hunting). To avoid stick slip, the machine rigidity should be increased, or friction characteristics of the sliding surface should be improved. When the sliding surface friction characteristic is as in the figure below, stick slip occurs easily.



Value of machine overrun (Damping coefficient of machine system)

When the machine is floated by static pressure, etc., there are cases where the machine keeps on moving within the range of backlash although the motor shaft has stopped. If this amount is large, hunting will also occur. To avoid this, backlash should be reduced (especially the backlash of the last mass where position detector is mounted) and the appropriate damping should be considered.

4.3 HOW TO FILL IN THE SERVO MOTOR SELECTION DATA TABLE

Select a suitable motor according to load conditions, rapid traverse rate, increment system and other factors. To aid in selecting the correct motor, we recommend filling in the “Servo Motor Selection Data Table” on the following page.

This section describes the items to fill in the Servo Motor Selection Data Table.

Servo Motor Selection Data Table

| | | | |
|-----------------|---------------|----------------------|--|
| Machine | | Type | |
| NC model | FS Power Mate | Spindle motor | |

| Item | Axis | | | | |
|---|---|----|--|--|--|
| Specifications of moving object | | | | | |
| * Axis movement direction (horizontal, vertical, rotation, slant _ degree) | | | | | |
| * Weight of moving object (including workpiece, etc.) | kgf | | | | |
| * Counterbalance | kgf | | | | |
| * Table support (sliding, rolling, static pressure) or friction coefficient | | | | | |
| * Ball screw | Diameter | mm | | | |
| | Pitch | mm | | | |
| | Length | mm | | | |
| | Rack and pinion (diameter of pinion, traveling distance of the machine tool per revolution of the pinion) | | | | |
| | Other | | | | |
| * Total gear ratio | | | | | |
| Mechanical specifications | | | | | |
| Traveling distance of the machine tool per revolution of the motor | mm | | | | |
| Least input increment of NC (resolution) | mm | | | | |
| * Maximum rapid traverse feedrate | mm/min | | | | |
| Motor speed in rapid traverse | min ⁻¹ | | | | |
| * Cutting rapid traverse | mm/min | | | | |
| *1 Motor shaft converted load inertia | kgf·cm·s ² | | | | |
| Inertia of coupling, reduction gear and pulley | kgf·cm·s ² | | | | |
| *2 Steady-state load torque | kgf·cm | | | | |
| * Cutting thrust | kgf | | | | |
| Maximum cutting torque (including steady-state load) | kgf·cm | | | | |
| Maximum cutting duty/ON time | %/min | | | | |
| Positioning distance | mm | | | | |
| *3 Required positioning time | sec | | | | |
| In-position set value | μm | | | | |
| Rapid traverse positioning frequency (continuous, intermittent) | times/min | | | | |
| Machine tool efficiency | | | | | |

| Item | Axis | | | | |
|--|---|-------|--|--|--|
| Motor specifications and characteristics | | | | | |
| | Motor type (desired size and output) | | | | |
| | Feedback type (when an absolute, incremental or pulse position detector is required) | | | | |
| | Options (when a brake, non-standard shaft, etc. is required) | | | | |
| | Separate type pulse coder (yes/no) | | | | |
| | Acceleration/deceleration time in rapid traverse | msec | | | |
| | Acceleration/deceleration time in cutting feed | msec | | | |
| | Feed-forward during rapid traverse (yes/no) | | | | |
| | Position loop gain | 1/sec | | | |
| | Dynamic brake stop distance | mm | | | |
| | | | | | |
| | | | | | |
| Note | <p>Be sure to fill in units other than the above if used. (Sometimes "deg" is used instead of "mm" for the rotary axis.)</p> <p>* Note required values for selecting the motor.</p> <p>*1 If possible enter the total load inertia. If you enter the inertia of coupling, reduction gear and pulley (motor shaft conversion) in the next item, you can also calculate the total load inertia by adding the weight of the moving object and ball screw values by logical calculation in the case of a linear shaft.</p> <p>*2 Steady-state load torque refers to the steady-state components such as friction (holding torque is included in the case of a gravity shaft) when the motor is rotating at a fixed speed. Enter the state-state load torque as far as possible. If details are unknown, use a value calculated logically from the weight and friction coefficient. Enter the steady-state load torque of the rotary axis in the same way as for load inertia as it cannot be calculated logically. You need not enter the torque required for acceleration/deceleration.</p> <p>*3 Servo delay and setting times must also be taken into consideration in the positioning time.</p> | | | | |
| Operating patterns/Remarks | <p>Enter typical operating patterns (time in horizontal column and torque and speed in vertical column, etc.) if they are already known. In cases where the machine tool makes special movements or the motor is rotated continuously, enter as many details as possible. Feel free to enter any other comments.</p> | | | | |

4.3.1

Title

Kind of machine tool

Fill in this blank with a general name of machine tools, such as lathe, milling machine, machining center, and others.

Type of machine tool

Fill in this blank with the type of machine tool decided by machine tool builder.

CNC equipment

Fill in this blank with the name of CNC (16i-MA, 21i-TA, PMi-D, etc.) employed.

Spindle motor output

Enter the specifications and output of the spindle motor. (This item is needed when selecting PSM.)

Axis

Fill in this blank with names of axes practically employed in CNC command. If the number of axes exceeds 4 axes, enter them in the second sheet.

4.3.2

Data

Specifications of moving object

- **Axis movement direction**

Be sure to enter data in this row. Data entered here is needed for determining the approximate motor load conditions (inertia, load torque).

Enter the movement directions of driven parts such as the table and tool post (e.g. horizontal, vertical). Write their angle from the horizontal level if their movement directions are slant (e.g. slant 60°).

- **weight of driven parts**

Enter the weight of driven parts, such as table, tool post, etc. by the maximum value including the weight of workpiece, jig, and so on. Do not include the weight of the counter balance in the next item in this item.

- **Counter balance**

Enter the weight of the counter balance in the vertical axis, if provided. Enter whether the counter balance is made by a weight or force as this influences inertia.

- **Table support**

Enter the type of table slide (e.g. rolling, sliding or static pressure). Enter a special slide way material like Turcite, if used. Also enter the friction coefficient value. This item is significant in estimating the friction coefficient for calculating mainly the load torque.

- **Feed screw**

Enter the diameter, pitch, and axial length of the lead screw in order. If a rack and pinion or other mechanism is used, also enter the traveling distance of the machine tool per revolution of the pinion.

- **Total gear ratio**

Enter the gear ratio between the ball screw and the servo motor, gear ratio between the final stage pinion and the servo motor in case of the rack pinion drive, or gear ratio between the table and the motor in case of rotary table.

Mechanical specifications

Enter basic data that is required for selecting the motor.

For details on how to calculate each of the items, see 4.1 to 4.2.

Pay special attention to the unit for calculating and expressing torque.

- **Movement per rotation of motor**

Enter the movement of the machine tool when the motor rotates one turn.
Example

- When the pitch of ball screw is 12 mm and the gear ratio is $2/3$,
 $12 \times 2/3 = 8$ mm
- When the gear ratio is $1/72$ in rotary table ;
 $360 \times 1/72 = 5$ deg

- **Least input increment CNC**

Enter the least input increment of NC command. (The standard value is 0.001 mm.)

- **Rapid traverse rate**

Enter the rapid traverse rate required for machine tool specifications.

- **Motor speed in rapid traverse**

Enter the motor speed during rapid traverse.

- **Cutting rapid traverse**

Enter the rapid traverse rate required for machine tool specifications.

- **Motor shaft converted load inertia**

Enter a load inertia applied by the moving object reflected on the motor shaft. Do not include the inertia of the motor proper in this value. For details on this calculation, see 4.1.1.

In the case of a linear shaft, enter the load inertia calculated by logical calculation if you enter the next item. In the case of a rotary shaft, however, the load inertia cannot be calculated by logical calculation.

-
- **Inertia of coupling, reduction gear and pulley** Enter values to two digits past the decimal point. (e.g. 0.2865 → 0.29)

 - **Steady-state load torque** Enter load inertia applied on transfer mechanisms other than couplings, moving objects and ball screw.

Enter the torque obtained by calculating the force applied for moving the machine tool and state-state components such as friction (including holding torque in the case of a gravity shaft) reflected on the motor shaft when it is rotating at a fixed speed. (Do not include any torque required for acceleration/deceleration in this item.) If details are unknown, use a value calculated logically from the weight and friction coefficient. Enter the steady-state load torque of the rotary axis in the same way as for load inertia as it cannot be calculated logically.


If the load torque values differ during lifting and lowering in the vertical axis, enter both values. Also, if the load torque values differ during rapid traverse and cutting feed, enter a notice to that effect.
Since torque produced in low speed without cutting may be applied even when the motor has stopped, a sufficient allowance is necessary as compared with the continued rated torque of the motor. Suppress this load torque so that it is lower than 70% of the rated torque.

 - **Cutting thrust** Enter the maximum value of the force applied during cutting by the force in the feed axis direction.

 - **Maximum cutting torque** Enter the torque value on the motor shaft corresponding to the maximum value of the above cutting thrust. When you enter this value, add the steady-state load to the motor shaft converted value for the cutting thrust. Since the torque transfer efficiency may substantially deteriorate to a large extent due to the reaction from the slideway, etc. produced by the cutting thrust, obtain an accurate value by taking measured values in similar machine tools and other data into account.

- **Maximum cutting duty / ON time**

Enter the duty time and ON time with the maximum cutting torque in the above item applied.



- **Positioning distance**

Enter the distance as a condition required for calculating the rapid traverse positioning frequency.

When an exclusive positioning device is used, enter this value together with the desired positioning time below.

- **Required positioning time**

Enter the required positioning time when an exclusive positioning device is used.

When the device is actually attached on the machine tool, note that servo delay and setting times must also be taken into consideration in the positioning time.

- **In-position set value**

Enter the in-position set value as a condition required for calculating the above positioning times when an exclusive positioning device is used. Note that the positioning time changes according to this value.

- **Rapid traverse positioning frequency**

Enter the rapid traverse positioning frequency by the number of times per minute. Enter whether the value is for continuous positioning over a long period of time or for intermittent positioning within a fixed period of time. (This value is used to check the OVC alarm and whether the motor is overheated or not by a flowing current during acceleration/deceleration, or to check the regenerative capacity of the amplifier.)

- **Machine tool efficiency**

This value is used for calculating the transfer efficiency of motor output on a machine tool. (Standard value is 0.9.)

Generally, a drop in transfer efficiency is expected if a reduction gear having a large deceleration rate is used.

Motor specifications and characteristics

- **Motor type**

Enter the motor type, if desired.

- **Feedback type**

Enter the specifications (absolute/increment or number of pulses: 65,536 or 10,000) of the feedback detector (pulse coder) built into the motor.

- **Options**

Enter options such as a motor brake and non-standard shaft, if required.


- **Separate type pulse coder**

Enter the name of the separate type pulse coder, if used.

- **Acceleration / deceleration time constant at rapid traverse**


The acceleration/deceleration time is determined according to the load inertia, load torque, motor output torque, and working speed. For details of calculations, refer to Subsec. 4.1.2 and 4.1.3.

The acceleration/deceleration mode at rapid traverse is generally linear acceleration/deceleration in FANUC's CNC.



- **Acceleration/ deceleration time constant at cutting feed**

The acceleration/deceleration at cutting feed is exponential acceleration /deceleration in general. This blank is filled in with its time constant



- **Feed-forward during rapid traverse**

Enter whether or not feed-forward control is used.

Generally, feed-forward control can reduce the delay time in executing servo commands. However, overheating of the motor is more likely to occur as a higher torque is required for acceleration/deceleration. Since mechanical shock increases by only the No.1 time constant, generally also set the No.2 acceleration/deceleration time constant or FAD time constant when using feed-forward control.

- **Position loop gain**


Fill in this blank with a value which is considered to be settable judging it from the inertia value based on experiences.

Since this value is not always applicable due to rigidity, damping constant, and other factors of the machine tool, it is usually determined on the actual machine tool. If the position detector is mounted outside the motor, this value is affected by the machine tool rigidity, backlash amount, and friction torque value. Enter these values without fail.

• **Dynamic brake stop distance**

This is coasting distance when the machine tool is stopped by dynamic braking with both ends of the motor power line shorted, if the machine tool is in trouble.

There are two ways of shortening this dynamic brake stop distance, the emergency stop distance shortening function, and the emergency stop distance shortening function (additional hardware is required) effective during power interruptions.



Coasting distance(mm or deg)

$$= V_m \times (t_1 + t_2) + (J_m + J_1) \times (A \times N_o + B \times N_o^3) \times L$$

J_m : Motor inertia (kg·cm·s²)

J : Load inertia (kg·cm·s²)

N_o : Motor speed at rapid traverse (rpm)

L : Machine movement on one-rotation of motor (mm or deg)
 $(N_o \times L = V_m)$

A: Coefficient A for calculating the dynamic brake stop distance

B: Coefficient B for calculating the dynamic brake stop distance

For details, see the table on the following page.

**Coefficients for
calculating the dynamic
brake stopping distance**

| Model | A | B | Jm (kgf·cm·s ²) |
|-------------------------------------|----------------------|-----------------------|-----------------------------|
| α series | | | |
| $\alpha 1/3000$ | 4.4×10^{-2} | 1.7×10^{-8} | 0.0031 |
| $\alpha 2/2000$ | 1.5×10^{-2} | 6.6×10^{-9} | 0.0056 |
| $\alpha 2/3000$ | 1.5×10^{-2} | 6.5×10^{-9} | 0.0061 |
| $\alpha 3/3000$ | 3.1×10^{-2} | 3.3×10^{-9} | 0.014 |
| $\alpha 6/2000$ | 1.1×10^{-2} | 2.1×10^{-9} | 0.027 |
| $\alpha 6/3000$ | 2.4×10^{-2} | 1.0×10^{-9} | 0.027 |
| $\alpha 12/2000$ | 7.0×10^{-3} | 3.0×10^{-9} | 0.064 |
| $\alpha 12/3000$ | 1.4×10^{-2} | 1.5×10^{-9} | 0.064 |
| $\alpha 22/1500$ | 3.8×10^{-3} | 1.3×10^{-9} | 0.12 |
| $\alpha 22/2000$ | 6.1×10^{-3} | 8.1×10^{-10} | 0.12 |
| $\alpha 22/3000$ | 7.3×10^{-3} | 6.8×10^{-10} | 0.12 |
| $\alpha 30/1200$ | 1.6×10^{-3} | 1.3×10^{-9} | 0.17 |
| $\alpha 30/2000$ | 1.8×10^{-3} | 1.2×10^{-9} | 0.17 |
| $\alpha 30/3000$ | 4.3×10^{-3} | 4.9×10^{-10} | 0.17 |
| $\alpha 40/2000$ | 1.8×10^{-3} | 6.3×10^{-10} | 0.23 |
| $\alpha 65/2000$ | 1.7×10^{-3} | 4.2×10^{-10} | 0.19 |
| $\alpha 100/2000$ | 1.3×10^{-3} | 2.4×10^{-10} | 0.27 |
| $\alpha 150/2000$ | 1.0×10^{-3} | 1.7×10^{-10} | 0.35 |
| $\alpha 300/2000$ | 3.3×10^{-4} | 1.0×10^{-10} | 0.80 |
| $\alpha 400/2000$ | 1.9×10^{-4} | 1.0×10^{-10} | 1.05 |
| αM series | | | |
| $\alpha M3/3000$ | 2.0×10^{-2} | 7.8×10^{-9} | 0.0030 |
| $\alpha M2.5/3000$ | 7.0×10^{-3} | 4.8×10^{-9} | 0.0053 |
| $\alpha M3/3000$ | 4.4×10^{-2} | 3.7×10^{-9} | 0.008 |
| $\alpha M6/3000$ | 1.8×10^{-2} | 1.5×10^{-9} | 0.014 |
| $\alpha M9/3000$ | 1.2×10^{-2} | 4.8×10^{-10} | 0.026 |
| $\alpha M22/3000$ | 6.2×10^{-3} | 6.8×10^{-10} | 0.059 |
| $\alpha M30/3000$ | 3.0×10^{-3} | 3.2×10^{-10} | 0.11 |
| $\alpha M40/3000$ | 2.2×10^{-3} | 6.7×10^{-11} | 0.12 |
| $\alpha M40/3000$ (with fan) | 1.3×10^{-3} | 1.2×10^{-10} | 0.12 |
| αL series | | | |
| $\alpha L6/3000$ | 2.7×10^{-2} | 5.5×10^{-9} | 0.0050 |
| $\alpha L9/3000$ | 2.4×10^{-2} | 8.7×10^{-10} | 0.010 |
| $\alpha L25/3000$ | 6.3×10^{-3} | 9.1×10^{-10} | 0.055 |
| $\alpha L50/2000$ | 3.0×10^{-3} | 6.2×10^{-10} | 0.10 |
| αC series | | | |
| $\alpha C3/2000$ | 8.1×10^{-3} | 1.3×10^{-8} | 0.014 |
| $\alpha C6/2000$ | 2.9×10^{-3} | 8.2×10^{-9} | 0.027 |
| $\alpha C12/2000$ | 1.6×10^{-3} | 1.3×10^{-8} | 0.064 |
| $\alpha C22/2000$ | 3.8×10^{-3} | 1.3×10^{-9} | 0.12 |

| Model | A | B | Jm (kgf·cm·s ²) |
|--|----------------------|-----------------------|-----------------------------|
| α (HV) series | | | |
| $\alpha 3/3000\text{HV}$ | 3.4×10^{-2} | 3.0×10^{-9} | 0.014 |
| $\alpha 6/3000\text{HV}$ | 1.3×10^{-2} | 1.8×10^{-9} | 0.027 |
| $\alpha 12/3000\text{HV}$ | 1.4×10^{-2} | 1.5×10^{-9} | 0.064 |
| $\alpha 22/3000\text{HV}$ | 7.8×10^{-3} | 6.4×10^{-10} | 0.12 |
| $\alpha 30/3000\text{HV}$ | 4.3×10^{-3} | 5.0×10^{-10} | 0.17 |
| $\alpha 40/2000\text{HV}$ | 5.9×10^{-3} | 2.0×10^{-10} | 0.23 |
| $\alpha 1000/2000\text{HV}$ | 4.7×10^{-5} | 7.6×10^{-11} | 4.25 |
| αM (HV) series | | | |
| $\alpha\text{M}6/3000\text{HV}$ | 1.4×10^{-2} | 1.9×10^{-9} | 0.014 |
| $\alpha\text{M}9/3000\text{HV}$ | 1.1×10^{-2} | 5.2×10^{-10} | 0.026 |
| $\alpha\text{M}22/3000\text{HV}$ | 8.6×10^{-3} | 3.1×10^{-10} | 0.059 |
| $\alpha\text{M}30/3000\text{HV}$ | 6.8×10^{-3} | 6.4×10^{-11} | 0.11 |
| $\alpha\text{M}40/3000\text{HV}$ | 5.8×10^{-3} | 5.0×10^{-11} | 0.12 |

The values of A and B are calculated by assuming that the resistance of the power line is 0.05Ω per phase. The values will vary slightly according to the resistance value of the power line.

The coefficient above values are applicable when the α series servo amplifier is being used. The coefficient may change, depending on the type of the servo amplifier. Contact FANUC when using the C series amplifier.

4.4 CHARACTERISTIC CURVE AND DATA SHEET

Performance of each motor model is represented by characteristic curves and data sheet shown below.

4.4.1 Performance Curves

The typical characteristic curves consist of the following.

Speed–torque characteristics

These are known as operating curves and describe the relationship between the output torque and speed of the motor. The motor can be operated continuously at any combination of speed and torque within the prescribed continuous operating zone. Outside of this zone, the motor must be operated on an intermittent basis using the duty cycle curves. The limit of continuous operating zone is determined under the following conditions. And this zone may be limited by the thermal protection of mounted precision instrument. (pulse coder)

- The ambient temperature for the motor is 20°C.
- The drive current of the motor is pure sine wave.

The limit of intermittent operating zone is determined by input voltage to the motor.

Actual operation is limited by the current limit of servo unit.

Due to the negative temperature coefficient of the magnetic material, continuous operating zone must be derated at the rate of 0.19% per degree centigrade rise of magnets. (i.e. for ambient temperature above 20° derate 0.19% for each degree over)

Overload duty characteristic

These curves are known as duty cycle curves and provided very important information on how to determine the “ON” time for intermittent overload torque without overheating the motor. The curves shown in the following figures are ones determined by the limit of the temperature of the motors. When the motor is driven by some driving circuit having thermal protect devices such as thermal relay or fuse, the “ON” time may be limited by the characteristics of those elements.

4.4.2 Data Sheet

The data sheet gives the values of motor parameters relating to the performance.

The values of parameters are those under the following conditions.

- The ambient temperature for the motor is 20°C.
- The drive current of the motor is pure sine wave.

Important parameters on the data sheet are defined as follows :

Continuous RMS current at stall TENV : I_s (Arms)

Maximum effective current that allows continuous motor operation

Torque constant : K_t (kgf·cm/Arms) (Nm/Arms)

This is known as torque sensitivity and represents the torque developed per ampere of phase current. This value is a motor-specific constant, and is calculated by the flux distribution and location of coils in the armature, and the dimensions of the motor.

Back EMF (electromotive force) constant: K_v (Vrms·sec) (Vrms·sec/rad)

The back EMF constant indicates the strength of the permanent magnetic field. It is the value of the generated voltage at a specified speed when the rotor is rotated mechanically. Back EMF is a motor-specific constant, and is also calculated by the flux distribution and location of coils in the armature, and the dimensions of the motor. Expressed in [min^{-1}] units, back EMF has the dimensions of [$\text{Vrms}/\text{min}^{-1}$]. The relationship can be given as:

$$(\text{Vrms} \cdot \text{sec}^{-1}/\text{rad}) = (9.55 \times \text{Vrms}/\text{min}^{-1})$$

The back EMF constant is indicated as the RMS voltage per phase, so multiple by $\sqrt{3}$ to obtain the actual terminal voltage.

$$K_t (\text{kgf} \cdot \text{cm}/\text{Arms}) = 30.6K_v (\text{Vrms} \cdot \text{sec} / \text{rad})$$

SI unit

$$K_t (\text{Nm}/\text{Arms}) = 3K_v (\text{Vrms} \cdot \text{sec} / \text{rad})$$

For this reason, when back EMF constant drops lower than the demagnetization of the magnet, the torque constant also drops by the same ratio.

Mechanical time constant : t_m (sec)

This is a function of the initial rate of rise in velocity when a step voltage is applied. It is calculated from the following relationship.

$$t_m = \frac{J_m \cdot R_a}{K_t \cdot K_v}$$

J_m : Rotor inertia ($\text{kgf} \cdot \text{m}^2$)

R_a : Resistance of the armature (Ω)

Thermal time constant : t_t (min)

This is a function of the initial rate of rise of winding temperature at rated current. It is defined as the time required to attain 63.2 percent of the final temperature rise.

Static friction : T_f (kgf·cm) (Nm)

This is the no-load torque required just to rotate the rotor.

4.4.3 How to Use Duty Cycle Curves

Servo motors can be operated in the range exceeding continuous rated torque depending on thermal time constant. Duty characteristics shows the Duty (%) and the “ON” time in which motor can be operated under the given overload conditions. Calculation procedure is as follows.

- 1 Calculate Torque percent by formula (b) below.
- 2 Motor can be operated at any point on and inside the curve corresponding to the given over load conditions obtained form 1.
- 3 Calculate t_F by formula (a)

$$t_F = t_R \times \left(\frac{100}{\text{Duty percent}} - 1 \right) \quad \dots\dots\dots (a)$$

$$TMD = \frac{\text{Load torque}}{\text{Continuous rated torque}} \quad \dots\dots\dots (b)$$

t_F : “OFF” time

t_R : “ON” time

The values of t_R and t_F obtained from the above mentioned procedure shows the ones limited by motor thermal conditions.

Note that thermal protection devices such as a circuit breaker and thermal circuit are incorporated into the drive amplifier. These devices also impose a restriction on motor usage.

When the motor is overloaded, the software (OVC alarm) imposes an additional restriction on motor drive duration.

5

CONDITIONS FOR APPROVAL RELATED TO THE IEC34 STANDARD



5.1 APPLICABLE MOTORS

This chapter describes the conditions the following FANUC α , series AC servo motors must clear before they can be approved for the IEC34 standard.

For details on EMC compliance authorization, refer to the separate manual “Compliance with EMC Directives”

5.1.1 200 VAC Input Types

The following FANUC AC servo motor α series can comply with the IEC34 standard if you follow the descriptions in this chapter. The TÜV mark is printed on the nameplates of the following motors.

(α series motors produced before March 1995 comply with the IEC34 standard only on condition that “#T” or “#U” is designated at the end of the specification code indicated on the nameplate.)

α series

| Model name | Motor specification number |
|--------------------------------|----------------------------|
| α 1/3000 | A06B-0371-Bxxx |
| α 2/2000 | A06B-0372-Bxxx |
| α 2/3000 | A06B-0373-Bxxx |
| α 3/3000 | A06B-0123-Bxxx |
| α 6/2000 | A06B-0127-Bxxx |
| α 6/3000 | A06B-0128-Bxxx |
| α 12/2000 | A06B-0142-Bxxx |
| α 12/3000 | A06B-0143-Bxxx |
| α 22/1500 | A06B-0146-Bxxx |
| α 22/2000 | A06B-0147-Bxxx |
| α 22/3000 | A06B-0148-Bxxx |
| α 30/1200 | A06B-0151-Bxxx |
| α 30/2000 | A06B-0152-Bxxx |
| α 30/3000 | A06B-0153-Bxxx |
| α 40/2000 | A06B-0157-Bxxx |
| α 40/2000 (with fan) | A06B-0158-Bxxx |
| α 65/2000 | A06B-0331-Bxxx |
| α 100/2000 | A06B-0332-Bxxx |
| α 150/2000 | A06B-0333-Bxxx |
| α 300/2000 | A06B-0137-Bxxx |
| α 400/2000 | A06B-0138-Bxxx |

α M series

| Mode name | Motor specification number |
|-------------------------|----------------------------|
| α M2/3000 | A06B-0376-Bxxx |
| α M2.5/3000 | A06B-0377-Bxxx |
| α M6/3000 | A06B-0162-Bxxx |
| α M9/3000 | A06B-0163-Bxxx |
| α M22/3000 | A06B-0165-Bxxx |
| α M30/3000 | A06B-0166-Bxxx |
| α M40 | A06B-0169-Bxxx |
| α M40 (with fan) | A06B-0170-Bxxx |

α L series

| Model name | Motor specification number |
|-------------------|----------------------------|
| α L6/3000 | A06B-0562-Bxxx |
| α L9/3000 | A06B-0564-Bxxx |
| α L25/3000 | A06B-0571-Bxxx |
| α L50/3000 | A06B-0572-Bxxx |

α C series

| Mode name | Motor specification number |
|-------------------|----------------------------|
| α C3/2000 | A06B-0121-Bxxx |
| α C6/2000 | A06B-0126-Bxxx |
| α C12/2000 | A06B-0141-Bxxx |
| α C22/1500 | A06B-0145-Bxxx |

5.1.2 400 VAC Input Types

The following FANUC AC servo motor α HV series can comply with the IEC34 standard if you follow the descriptions in this chapter. The TÜV mark is printed on the nameplates of the following motors.

(α series motors produced before March 1995 comply with the IEC34 standard only on condition that “#T” or “#U” is designated at the end of the specification code indicated on the nameplate.)

α (HV) series

| Model name | Motor specification number |
|----------------------|----------------------------|
| α 3/3000HV | A06B-0171-Bxxx |
| α 6/3000HV | A06B-0172-Bxxx |
| α 12/3000HV | A06B-0176-Bxxx |
| α 22/3000HV | A06B-0177-Bxxx |
| α 30/3000HV | A06B-0178-Bxxx |
| α 40/2000HV | A06B-0179-Bxxx |
| α 1000/2000HV | A06B-0131-Bxxx |

α M(HV) series

| Model name | Motor specification number |
|---------------------|----------------------------|
| α M6/3000HV | A06B-0182-Bxxx |
| α M9/3000HV | A06B-0183-Bxxx |
| α M22/3000HV | A06B-0185-Bxxx |
| α M30/3000HV | A06B-0186-Bxxx |
| α M40/3000HV | A06B-0189-Bxxx |

5.2 DRIVES

5.2.1 200 VAC Input Types

The FANUC α , α M, α L, and α C series AC servo motors can be driven only by the FANUC servo amplifiers for 200 to 230 VAC.

5.2.2 400 VAC Input Types

The FANUC α (HV) series and α M(HV) series AC servo motors can be driven only by the FANUC servo amplifiers for 400 to 460 VAC.

5.3 POWER CABLE CONNECTORS

5.3.1 Models α1 and α2

The motor power cable must be connected using the following specified connectors.

| Model Name | Connector Kit Specification [FANUC Specification] | | Dedicated Tools Specification [FANUC Specification] |
|---|---|--|---|
| α1/3000 α2/2000 α2/3000 αM2/3000 αM2.5/3000 | Connector kit w/ contacts | 176346-8 (AMP Japan) [A06B-6050-K121] | Crimping tool 914596-3 (AMP Japan) [A97L-0200-0979/L] |
| | Connector kit w/out contacts | 176346-7 (AMP Japan) [contacts not provided] | Extractor 914677-1 (AMP Japan) [A97L-0200-0980/D3] |

* Also, see "8. Connectors."

Section 8.2.3 of IEC204-1 (EN60204-1), which must be met to acquire CE marking approval, stipulates that all exposed live conductors of electric equipment and machines be connected to a protection link circuit. In order to comply with this stipulation, sufficient care must be paid when using the above connector kits.

- When connecting the connector kit assembly, connect the metal shell of the connectors shown below to the protection link circuit.
- Use leads that meet the following specifications:


| Brake | Number of Cores | Cable Size | Insulation O.D. | Sheath O.D. (*) |
|-------------|-----------------|---|-----------------|------------------|
| W/out brake | 5 or more | AWG18 to 16 (0.85 to 1.25 mm ²) | φ1.8 to 2.8 mm | φ10.4 to 11.4 mm |
| W/ brake | 7 or more | | | |

(*) Note that water-proof performance may be impaired if a sheath of inappropriate O.D. is used.

- An earth lead for the connector shell is also required in addition to the motor earth. Connect each of these to the GND terminal on the amplifier.

FANUC can also provide cable assemblies that use IEC-compliant leads. The following are FANUC specifications:

- Cable assembly (14 m as standard)
 - Model with no brake: A06B-6080-K824
 - Model with built-in brake: A06B-6080-K825



5.3.2 Models $\alpha 3$ and Higher

The motor power cable and brake fan unit must be connected using the connectors and cable clamps specified below.

| Cable Type | Motor model name | Plug connector maker specification [FANUC specification] | | Cable clamp specification and connector maker name | |
|------------|---|--|--|---|---|
| For Power | $\alpha 3/3000$, $\alpha 6/2000$, $\alpha 6/3000$, $\alpha M6/3000$, $\alpha M9/3000$ $\alpha L6/3000$, $\alpha L9/3000$, $\alpha C3/2000$, $\alpha C6/2000$, $\alpha 3/3000HV$, $\alpha 6/3000HV$, $\alpha M6/3000HV$, $\alpha M9/3000HV$ | Straight type | H/MS3106A18-10S-D-T (10) [A63L-0001-0648/61810SH] | H/MS3057-10A (10) [A63L-0001-0592/10AK] Hirose Electric | |
| | | L-shape type | H/MS3108B18-10S-D-T (10) [A63L-0001-0648/81810SH] | | |
| | $\alpha 12/2000$, $\alpha 12/3000$, $\alpha 22/1500$, $\alpha 22/2000$, $\alpha 30/1200$, $\alpha C12/2000$, $\alpha C22/1500$, $\alpha 12/3000HV$, $\alpha 22/3000HV$, $\alpha 30/3000HV$, $\alpha M22/3000HV$, $\alpha M30/3000HV$ | Straight type | JL04V-6A22-22SE-EB [A63L-0001-0648/62222SJ] | JL04-2022CK-(14) [A63L-0001-0653/12A] Japan Aviation Electronics Industry | |
| | | L-shape type | JL04V-8A22-22SE-EB [A63L-0001-0648/82222SJ] | | |
| | $\alpha 22/3000$, $\alpha 30/2000$, $\alpha 30/3000$, $\alpha 40/2000$, $\alpha 40/2000FAN$ $\alpha M22/3000$, $\alpha M30/3000$, $\alpha L25/3000$, $\alpha L50/2000$ | Straight type | JL04V-6A24-10SE (G)-EB [A63L-0001-0648/62410SJ] | JL04-2428CK-(17) [A63L-0001-0653/16A] Japan Aviation Electronics Industry | |
| | | L-shape type | JL04V-8A24-10SE (G)-EB [A63L-0001-0648/82410SJ] | | |
| | 90V brake fan unit connection | Common to all models excluding α (HV) series | Straight type | JL04V-6A10SL-3SE-EB [A63L-0001-0648/610SL3SJ] | JL04-1012CK-(05) [A63L-0001-0653/04A] Japan Aviation Electronics Industry |
| | | | L-shape type | JL04V-8A10SL-3SE-EB [A63L-0001-0648/810SL3SJ] | |

- Also see Section 8.
- The power cable for the $\alpha 22/3000$, $\alpha 30/2000$, $\alpha 30/3000$, $\alpha 40/2000$, $\alpha 40/2000\text{FAN}$, $\alpha \text{M}22/3000$, $\alpha \text{M}30/3000$, $\alpha \text{L}25/3000$, and $\alpha \text{L}50/2000$ has 7 conductors. Its grounding wire (one conductor) must have a cross section not less than that for the U, V, or W line (two conductors). For the grounding wire for the other connectors, its cross section must not be less than that for the U, V, or W line.
- TUV have certified that the plug connector and cable clamp mentioned above, when combined with the FANUC α series servo motors, satisfy the VDE0627 safety standard. As indicated in the table below, several manufacturers offer other plug connectors. For information about whether the plug connectors satisfy the safety standard when combined with the FANUC α series servo motors, contact the corresponding manufacturer. Contact the manufacturers if you require details of their products.

| Manufacturer | Product series name |
|---|-------------------------------|
| Hirose Electric (HRS) | H/MS310 TUV-conforming series |
| Japan Aviation Electronics Industry (JAE) | JL04V series |
| DDK Ltd. (DDK) | CE05 series |

- If a cable or conduit hose seal adapter is used, consult an appropriate connector maker.

5.4 APPROVED SPECIFICATIONS

The following specifications are approved for the IEC34 standard.

5.4.1 Motor Speed (IEC34-1)

The allowable maximum speeds of motors are as listed below.

The allowable maximum speeds are specified in such a way that the approval conditions of the IEC34 standard, as they relate to rotational speed, are satisfied. When the allowable maximum speeds are used, the characteristics are not guaranteed. For the maximum speed that each motor can support, refer to the respective data sheet.

| Motor model | Rated-output speed [min ⁻¹] | Allowable maximum speed [min ⁻¹] |
|--|---|--|
| α 1/3000, α 2/3000, α 3/3000, α 6/3000, α M2/3000, α M2.5/3000 α M6/3000, α M9/3000, α L6/3000, α L9/3000 α 3/3000HV, α 6/3000HV α M6/3000HV, α M9/3000HV α 12/3000, α 22/3000, α 30/3000, α M30/3000 α L25/3000, α 22/3000HV, α 12/3000HV, α 30/3000HV, α M22/3000HV, α M30/3000HV | 3000 | 4000 |
| α 2/2000, α 6/2000, α 12/2000, α 22/2000, α 30/2000, α 40/2000, α C3/2000, α C6/2000, α C12/2000, α L50/2000 | 2000 | 2500 |
| α 22/1500, α C22/1500 | 1500 | 2000 |
| α 30/1200 | 1200 | 1500 |
| α 65/2000, α 100/2000, α 150/2000 | 2000 | 2500 |
| α M40/3000 | 1000 | 3000 |
| α M40/3000 (with fan) | 3000 | 3000 |
| α M40/2000HV, α 300/2000, α 400/2000, α 1000/2000HV | 2000 | 2000 |
| α M40/3000HV | 1000 | 3000 |

5.4.2 Output (IEC34-1)

The rated output is guaranteed as continuous output only for the rated-output speed. The output in an intermittent operation range is not specified. When rated output increases due the use of an external fan (excluding models with cooling fan), the servo motor does not comply with the IEC34 standard. Note, however, that this poses no problem if the fan is used for the purpose of cooling, and the motor is used with output held at the current output rating. The approved output of each model is as listed in II to VII.3, “Specifications and Characteristics” (described later).

5.4.3 Protection Type (IEC34-5)

Motor protection confirms to IP65.

Note that on models with built-in fan, the fan connector is IP00. On models where the power cable is connected to the terminal box, you must pay attention to the cable routing port, for example, by using a conduit that complies with IP65.

IP6x: Completely dust-proof machine

This structure completely prevents dust from entering the machine.

IPx5: Sprinkle-proof machines

A sprinkle-proof machine shall not suffer inadvertent influence when they are exposed to water sprinkled from nozzles at any angle to the machine.

The conditions of the IPx5 type test are as follows:

| | |
|---|----------------------|
| Nozzle inside diameter: | 6.3 (mm) |
| Amount of sprinkled water: | 12.5 (liters/minute) |
| Water pressure at the nozzle: | 30 (kPa) |
| Sprinkle time per a surface of 1 m ² : | 1 (minute) |
| Minimum required time: | 3 (minutes) |
| Distance between the nozzle and machine: | Approximately 3 m |

CAUTION

IPx5 evaluates machines for waterproofness in a short-term test as described above, allowing chances that the machines may get dry after the test. If a machine is exposed to liquids other than water or so continuously to water that it cannot get dry, it may suffer inadvertent influence even if the degree of exposure is low.

5.4.4 Cooling Method (ICE34-6)

The motor cooling methods are as listed below.

| Motor model | IC code | Method |
|---------------------------|---------|---|
| α 40/2000 with fan | IC416 | Fully closed; cooled by an external independent fan |
| Other models | IC410 | Fully closed; cooled by a natural air flow |

5.4.5
Mounting Method
(IEC34-7)

The motors can be mounted by the following methods.

- IMB5: Flange mounting with the shaft facing sideways (from the rear)
 - IMV1: Flange mounting with the shaft facing upward (from the rear)
 - IMV3: Flange mounting with the shaft facing downward (from the rear)
-

5.4.6
Heat Protection
(IEC34-11)

The heat protection type is as listed below:

- T P 2 1 1
- 1: Temperature rise limit category 1 for heat protection
 - 2: Stop only at stage 1 (no warning)
 - 2: Protection for gradual and abrupt overload
-

Remarks

For details on EMC compliance authorization, refer to the separate manual "Compliance with EMC Directives"

6

FEEDBACK DETECTOR



6.1 BUILT-IN DETECTOR

All AC servo motors feature a pulse coder (optical encoder). The pulse coder outputs position information and an alarm signal. The following lists the available pulse coders are compatible.

| Pulse coder type | Resolution Division/rev | Absolute/ incremental | Applicable motor |
|----------------------------|------------------------------------|----------------------------------|-------------------------------------|
| Pulse coder α A64 | 65,536 | Absolute | All models |
| Pulse coder α I64 | 65,536 | Incremental | All models |
| Pulse coder α A1000 | 1,000,000 | Absolute | All models except α C series |

6.2 PULSE CODER RESOLUTION AND CONTROL RESOLUTION

**65,536
divisions/revolution**

With the NC's flexible feed gear function, 1- μ m control can be performed for feed pitches of up to 30 mm per motor revolution.

**1,000,000
divisions/revolution**

With the NC's flexible feed gear function 0.1- μ m control (up to 100 mm/revolution) and 0.01- μ m control (up to 10 mm/revolution) can be performed.

Increasing the speed loop gain as far as possible is effective. This can be easily achieved by increasing the resolution

6.3 ABSOLUTE-TYPE PULSE CODER

When the NC is turned off, the pulse coder position detection function is backed up by battery. So, when the NC is next turned on, the operator does not have to perform reference position return.

For backup, a battery unit must be installed in the NC or servo amplifier. If a low-battery indication appears on the NC, renew the battery as soon as possible.


Replace the battery while the NC is turned on.

6.4 DETECTOR INPUT/OUTPUT SIGNALS

The α -type pulse coders signals are inputted or outputted as shown below. The pin assignments of the signals for the connector used for each model are also shown.

Models

α 1/3000, α 2/2000,
 α 2/3000, α M2/3000,
 α M2.5/3000




D-SUB 15P

| Signal name | Pin No. | |
|-------------|--------------------------------|--------------|
| | α A64 α A1000 | α I64 |
| SD | 12 | 12 |
| *SD | 13 | 13 |
| REQ | 5 | 5 |
| *REQ | 6 | 6 |
| +5V | 8, 15 | 8, 15 |
| 0V | 1, 2, 3 | 1, 2, 3 |
| Shield | 4 | 4 |
| +6VA | 14 | - |
| 0VA | 10 | - |

Models

α 3/3000 to α 400/1200
 α 3/3000HV to
 α 1000/2000HV
 α C3/2000 to α C22/1500
 α M3/3000 to α M40/3000,
 α M40/3000 (with fan)
 α M6/3000HV to
 α M40/3000HV
 α L3/3000 to α L50/3000



3102A 20-29PW

| Signal name | Pin No. | |
|-------------|--------------------------------|-----------------------------|
| | α A64 α A1000 | α I64 α I8 |
| SD | A | A |
| *SD | D | D |
| REQ | F | F |
| *REQ | G | G |
| +5V | J, K | J, K |
| 0V | N, T | N, T |
| Shield | H | H |
| +6VA | R | - |
| 0VA | S | - |

6.5 SEPARATE TYPE POSITION DETECTOR

For detecting a position by attaching directly to a ball screw or a machine, use a separate type position detector. Pay attention to the following items when using the separate type position detector.

- Increase the machine rigidity between the servo motor and the position detector to minimize mechanical vibration. If the machine rigidity is low or the structure vibrates, poor performance, over shoot is likely to occur.
- Generally, when the separate type detector is used, the influence of gear, ball screw pitch error or table inclination is decreased and the positioning accuracy and geometrical accuracy (roundness, etc.) are increased, but the smoothness may deteriorate due to the elasticity in the machine between the servo motor and the position detector.
- It is necessary to use the built-in pulse coder with a resolution equal to or finer than that of the separate type position detector.

To connect the separate type position detector to the NC, connect only the signals described in the connecting manual. (A, B, Z, 0V, 5V and REQ if necessary)

When the other signal is connected, the unit may malfunction.

Do not connect the C1, C2, C4, and C8 signals output from the separate type pulse coder unit.

FANUC provides the following external position (rotary) detector.

6.5.1 Separate Type Pulse Coder Type and Specifications

Four types of separate type pulse coder are available. Features and rapid traverse-related limitations are the same as the built-in pulse coder.

- Pulse coder α A1000S

A860-0372-T001

1,000,000 P/rev (Up to 4000 min⁻¹)

- Incremental pulse coder unit

A860-0301-T0□□

□□

01 : 2000P/rev (Up to 3000min⁻¹)

02 : 2500P/rev (Up to 2400min⁻¹)

03 : 3000P/rev (Up to 2000min⁻¹)

04 : 4000P/rev (Up to 1500min⁻¹)

- Absolute pulse coder unit

A860-0324-T1□□

□□

01 : 2000P/rev (Up to 3000min⁻¹)

02 : 2500P/rev (Up to 2400min⁻¹)

03 : 3000P/rev (Up to 2000min⁻¹)

04 : 4000P/rev (Up to 1500min⁻¹)

• **High-speed high resolution pulse coder unit**

A860-0314-T1□□

□□

11 : 2000P/rev (Up to 3000min⁻¹)

12 : 2500P/rev (Up to 2400min⁻¹)

13 : 3000P/rev (Up to 2000min⁻¹)

The following signal conversion circuits are required for connecting high-speed high resolution pulse coder units to the NC.

Signal conversion circuit: **A06B-6061-J0**□□

□□

01 : For two systems

02 : For four systems

6.5.2 Separate Type Pulse Coder Specifications

Pulse coder α A1000S

| Item | | Specification |
|-----------------------------------|--------|---|
| Power voltage | | 5 (V) \pm 5% |
| Current consumption | | Up to 0.3 (A) |
| Working temperature range | | 0 to +60 (°C) |
| Resolution | | 1,000,000 (/rev.) |
| Maximum speed of rotation | | 4000 (min ⁻¹) |
| Input shaft inertia | | Up to 1×10^{-4} (kg·m ²) |
| Input shaft startup torque | | Up to 0.1 (Nm) |
| Rated loads | Radial | 2.0 (N) |
| | Axial | 1.0 (N) |
| Shaft diameter runout | | 0.02×10^{-3} (m) |
| Structure | | Dust-proof, drip-proof (IP55 or equivalent: when water-proof connector is fitted) |
| Vibration resistance acceleration | | 5 (G) (50 to 2,000 (Hz)) |
| Weight | | Approx. 0.75 (kg) |

Incremental pulse coder unit

Absolute pulse coder unit


High-speed and high-resolution pulse coder unit

| Item | | Specification |
|----------------------------|--------|---|
| Power voltage | | 5 (V) \pm 5% |
| Current consumption | | Up to 0.35 (A) |
| Working temperature range | | 0 to +60 ($^{\circ}$ C) |
| Maximum response frequency | | 100×10^3 (Hz) |
| Input shaft inertia | | Up to 5×10^{-3} (kg·m ²) |
| Input shaft startup torque | | Up to 0.8 (Nm) |
| Rated loads | Radial | 20 (N) |
| | Axial | 10 (N) |
| Shaft diameter runout | | 0.02×10^{-3} (m) |
| Weight | | Approx. 2.0 (kg) |

6.5.3

Input Signals and Layout of Connector Pins of Separate Type Pulse Coder

Pulse coder α A1000S




3102A20-29PW


| Signal name | Pin No. |
|-------------|--------------------------------|
| | α A1000S 3102A20-29P |
| SD | A |
| *SD | D |
| REQ | F |
| *REQ | G |
| +5V | J, K |
| 0V | N, T |
| Shield | H |
| +6VA | R |
| 0VA | S |

Incremental pulse coder unit

Absolute pulse coder unit




Incremental
3102A20-29P



Absolute
3102A22-14P

| Signal name | Pin No. | |
|-------------|---------------------------|-------------------------|
| | Incremental 310A20-29P | Absolute 3102A22-14P |
| A | A | A |
| *A | D | B |
| B | B | C |
| *B | E | D |
| Z | F | E |
| *Z | G | F |
| C1 | — | G |
| C2 | — | H |
| C4 | — | J |
| C8 | — | K |
| +5V | C, J, K | L |
| 0V | N, P, T | M |
| Shield | H | N |
| OH1 | | — |
| OH2 | | — |
| REQ | | S |
| +6VA | | T |
| 0VA | | U |

High-speed and high-resolution pulse coder unit




3102A22-14P

| Signal name | Pin No |
|-------------|---|
| | High-speed and high-resolution 3102A22-14P |
| A | A |
| *A | B |
| B | C |
| *B | D |
| Z | E |
| *Z | F |
| C1 | G |
| C2 | H |
| C4 | J |
| C8 | K |
| +5V | L, T |
| 0V | M, U |
| Shield | N |
| OH1 | — |
| OH2 | — |

6.5.4 External Dimensions of Separate Type Pulse Coder

| Separate Type Pulse Coder Name | Dwg. No. |
|--|----------------|
| Pulse coder α A1000S | Fig. 6.5.4 (a) |
| Incremental pulse coder unit | Fig. 6.5.4 (b) |
| Absolute pulse coder unit High-speed and high-resolution pulse coder unit | Fig. 6.5.4 (c) |

Fig. 6.5.4 (b) Incremental pulse coder unit



7

BUILT-IN BRAKE



Some of the α , α (HV), α C, α M, and α L series Models use motors that contain a holding brake to prevent falling along a vertical axis. Motors with a built-in brake have different outlines and weight from other types of motors. For their outlines, refer to appropriate outline drawings.

7.1 BRAKE SPECIFICATIONS

The specifications of built-in brakes are listed below.

| Motor model | Unit | $\alpha 1$ $\alpha 2$ $\alpha M2$ $\alpha M2.5$ | $\alpha 3$ $\alpha 6$ $\alpha M6$ $\alpha M9$ $\alpha C3$ $\alpha C6$ | $\alpha 12$ $\alpha 22$ $\alpha 30$ $\alpha C12$ $\alpha C22$ $\alpha M22$ $\alpha M30$ $\alpha M40$ $\alpha M40$ (with fan) | $\alpha 40$ | $\alpha 65$ $\alpha 100$ $\alpha 150$ |
|-------------------------|--|--|--|---|-----------------|---|
| Brake torque | Nm kgf-cm | 2 20 | 8 82 | 35 357 | 35 357 | 100 1020 |
| Response time | Release | msec | 60 | 70 | 120 | 180 |
| | Brake | msec | 20 | 30 | 30 | 60 |
| Supply voltage | VDC ($\pm 10\%$) | 90 | 90 | 90 | 90 | 90 |
| Current | A | 0.2 or less | 0.4 or less | 0.5 or less | 0.6 or less | 1.0 or less |
| Weight increase | kg | Approx. 1.3 | Approx. 2.3 | Approx. 6.3 | Approx. 10 | Approx. 15 |
| Inertia increase | kg·m ² kgf-cm·s ² | 0.00002 0.0002 | 0.00007 0.0007 | 0.0006 0.006 | 0.0010 0.010 | 0.0010 0.010 |
| Resistance value | Ω | 516 | 295 | 220 | 220 | 99 |

| Motor model | Unit | $\alpha L6$ $\alpha L9$ | $\alpha L25$ $\alpha L50$ |
|-------------------------|--|----------------------------|------------------------------|
| Brake torque | Nm kgf-cm | 8 82 | 18 184 40 408 |
| Response time | Release | msec | 70 100 |
| | Brake | msec | 30 70 |
| Supply voltage | VDC ($\pm 10\%$) | 90 | 90 |
| Current | A | 0.4 or less | 0.5 or less |
| Weight increase | kg | Approx. 2.3 | Approx. 6.0 |
| Inertia increase | kg·m ² kgf-cm·s ² | 0.00007 0.0007 | 0.0006 0.006 |
| Resistance value | Ω | 295 | 220 |

| Motor model | Unit | $\alpha 3HV$ $\alpha 6HV$ $\alpha M6HV$ $\alpha M9HV$ | $\alpha 12HV$ $\alpha 22HV$ $\alpha 30HV$ $\alpha 40HV$ $\alpha M22HV$ $\alpha M30HV$ $\alpha M40HV$ |
|-------------------------|--|--|--|
| Brake torque | Nm kgf-cm | 8 82 | 35 357 |
| Response time | Release | msec | 70 120 |
| | Brake | msec | 30 30 |
| Supply voltage | VDC ($\pm 10\%$) | 24 | 24 |
| Current | A | 1.5 or less | 2.0 or less |
| Weight increase | kg | Approx. 2.3 | Approx. 6.3 |
| Inertia increase | kg·m ² kgf-cm·s ² | 0.00007 0.0007 | 0.0006 0.006 |
| Resistance value | Ω | 21 | 16 |

The values shown above are standard values at 20°C.

7.2 CAUTIONS

CAUTION


Pay attention to the following points when motors with brakes are used.

- 1 Configure the brake circuit referring to the brake wiring diagrams and recommended parts described in the following items.
- 2 For the α , αM , αL and αC brake power supplies, use the full-wave rectified 100 VAC or 90 VDC power supplies. The allowable voltage fluctuation for both of these power supplies is $\pm 10\%$. Do not use a half-wave rectified 200 VAC power supply. Doing so will damage the surge absorber.
- 3 For the $\alpha(HV)$ and $\alpha M(HV)$, use the 24 VDC power supply. The allowable voltage fluctuation for this power supply is $\pm 10\%$.
- 4 The brake in the motor is used to hold the machine when the servo motor control is OFF. It is possible to brake the machine by turning OFF the brake power in an emergency stop or during a power interruption. However, it is impossible to use this brake to reduce the stop distance in normal operation.
- 5 Allow sufficient time to start the servo motor before releasing the brake. Don't use the brake as an aid for the axis to stop at the same position for a long time, such as an index table. Turn the servo off when holding the axis by the built-in brake or another holding means. At this time, allow sufficient time to set the brake before turning off the servo.
- 6 Models $\alpha 40/2000$ are longer because they contain a brake. If an excessive load is applied to the opposite side of the flange, the flange may be damaged. Do not apply any load to the opposite side of the flange. Do not subject the motor to excessive force.
- 7 Motor brake connectors do not have polarity.


7.3 CONNECTOR SHAPES

The following shows the shape and pin arrangement of the brake connectors.


Models $\alpha 1$, $\alpha 2$, $\alpha M2$, $\alpha M2.5$



Models $\alpha 3$ to $\alpha 150$, αM , αL , αC



Models $\alpha(HV)$, $\alpha M(HV)$




* “BK” stands for the brake signal.

7.4 CONNECTION OF THE BRAKES

The following shows example of brake connections.


Models

α , αM , αL , αC



Models

$\alpha(HV)$ and $\alpha M(HV)$



7.5 RECOMMENDED PARTS IN BRAKE CIRCUITS

| Name | Model No. | Name of Manufacturer | Q'ty | Required Specifications | Order Dwg. No. (FANUC Procurement Dwg. No.) |
|----------------|------------|--|------|---|---|
| Rectifier | D3SB60 | SHINDENGEN ELECTRIC MFG. CO., LTD. | 1 | Withstand voltage 400 V min. | A06B-6050-K112 |
| Switch | — | — | 1 | Rated control capacity 500VAC, 5A | — |
| Spark killer | S2-A-0 | OKAYA ELECTRIC IND. CO., LTD. | 1 | 500 Ω /0.2 μ F Withstand voltage 400 V min. | — |
| Surge absorber | ERZV20D221 | Matsushita Electric Industrial Co., Ltd. | 1 | Varister voltage 220V Max. allowable circuit voltage 140VAC | A06B-6050-K113 |

7.6 BRAKE CABLE (TUV/EMC COMPATIBLE)

| Motor Type | Brake Power Voltage | Connector Shape | Cable Dwg. No. | |
|--|---------------------|---------------------------------|----------------|----------------|
| | | | Straight | Elbow |
| α 1, α 2 α M2, α 2.5 | 90VDC | Packaged inside power connector | A06B-6080-K825 | — |
| α 3 to α 150 α M3 to α 30 α L, α C | 90VDC | 3 pins | — | A06B-6080-K806 |
| α (HV) α M(HV) | 24VDC | 2 pins | — | A06B-6080-K807 |


Use a cable of maximum length 14 m and minimum conductor cross-section area of 0.5 mm² per lead.

7.7 REDUCING THE BRAKE SHAFT FALL AMOUNT

When a motor with brake is applied to gravity shafts, the fall amount of the shaft in a power interruption or an emergency stop, or when the CNC is turned OFF may be a problem. The following describes an effective way of minimizing this fall amount.

- (1) Provide a control switch or relay on the DC side (see position in figure below) of the brake circuit to quickly activate the brake.
- (2) It is essential that this switch or relay be disconnected as quickly as possible to shorten the fall amount in the vertical axis.
- (3) Taking the power supply for actuating the relay directly from the mains power supply (mainly 200 VAC in Japan) is effective for quickly disconnecting the relay in a power interruption.
- (4) To prevent the shaft from falling during an emergency stop, it is sometimes effective to use the “brake control function” in the servo software. This function enables continuous excitation of the motor until the motor built-in brake operates.

For details, see Parameter Manual B-65150E.



8

CONNECTORS



8.1 CONNECTOR ON THE MOTOR SIDE

The FANUC α series AC servo motors use TÜV-approved connectors on the power cable and brake/fan unit in order to comply with the IEC34 standard. Dripproof receptacle connectors are used as standard for all cables including those for signals (except for the $\alpha 1$, and $\alpha 2$ series). These connectors are dripproof even when not engaged.

Strictly speaking, the IEC34 for connectors is different from the MS standard with respect to the connector disengaged-state waterproof function and appearance (black in color). However, the TÜV-approved connectors are compatible with the MS-standard round connectors in size and shape. So, MS-standard plug connectors other than those recommended below are also usable. (The waterproof plug connectors recommended in Sections 8.3.1 and 8.3.2 should be used if it is necessary to keep the whole system waterproof.)

8.1.1 Specifications of Connectors on the Motor Side

Connectors for $\alpha 1$ and $\alpha 2$

| Motor Type | For Power | For Signal | For Brake |
|--|-------------------------|-------------------------------|--|
| $\alpha 1/3000$ $\alpha 2/2000$, $\alpha 2/3000$ $\alpha M2/3000$ $\alpha M2.5/3000$ | 176339-2 (AMP Japan) | SDAB-15P (Hirose Electric) | Power connectors are used. For details, see chapter "7. Brakes." |

Connectors for $\alpha 3$ to $\alpha 40$

| Motor Type | For Power | For Signal | For Brake |
|--|---|--|---|
| $\alpha 3/3000$, $\alpha 6/2000$ $\alpha 6/3000$ $\alpha M6/3000$, $\alpha M9/3000$, $\alpha L6/3000$, $\alpha L9/3000$, $\alpha C3/2000$, $\alpha C6/2000$ | H/MS3102A18-10P-D-T (10) (Hirose Electric) | H/MS3102A20-29PCW4 (10) (Hirose Electric) | JL04V-2E10SL-3PE-B (Japan Aviation Electronics Industry) |
| $\alpha 3/3000HV$ $\alpha 6/3000HV$ $\alpha M6/3000HV$ $\alpha M9/3000HV$ | | | H/MS3102A10SL-4P (Hirose Electric) |
| $\alpha 12/2000$, $\alpha 12/3000$ $\alpha 22/1500$, $\alpha 22/2000$ $\alpha 30/1200$ $\alpha C12/2000$, $\alpha C22/1500$ | JL04HV-2E22-22PE-B (Japan Aviation Electronics Industry) | | JL04V-2E10SL-3PE-B (Japan Aviation Electronics Industry) |
| $\alpha 12/3000HV$, $\alpha 22/3000HV$ $\alpha 30/3000HV$ $\alpha 40/2000HV$ $\alpha M22/3000HV$ $\alpha M30/3000HV$ $\alpha M40/3000HV$ | | | H/MS3102A10SL-4P (Hirose Electric) |
| $\alpha 22/3000$, $\alpha 30/2000$ $\alpha 30/3000$, $\alpha 40/2000$ $\alpha 40/2000FAN$ $\alpha M22/3000$, $\alpha M30/3000$, $\alpha M40/3000$, $\alpha M40/3000FAN$, $\alpha L25/3000$, $\alpha L50/2000$ | JL04V-2E24-10PE(G)-B (Japan Aviation Electronics Industry) | | JL04V-2E10SL-3PE-B (Japan Aviation Electronics Industry) |

Fan connectors

| Motor Type | For Fan |
|---|---|
| $\alpha 40/2000FAN$ $\alpha M40/3000FAN$ | JL04V-2E10SL-3PE-B (Japan Aviation Electronics Industry) |
| $\alpha 300$, $\alpha 400$ | H/MS3102A18-10P-D-T(10) (Hirose Electric) |

CAUTION

- 1 The motors should be installed with their connector facing downward as long as possible. When it is impossible to install a motor in this position, allow slack in the cable to keep liquids such as a dielectric fluid from going along the cable into the cable or motor. If there is a possibility that the motors and connectors get wet, provide a cover to protect them.
- 2 If a motor is not connected to the earth ground through the machine (frame), connect the motor grounding point and the amplifier grounding point to absorb noise using a 1.25 mm² or larger conductor other than the grounding conductor in the power cable. Keep the grounding conductor as far from the power cable as possible.

8.2 CONNECTORS ON THE CABLE SIDE (MODELS $\alpha 1$ AND $\alpha 2$)

FANUC can provide TÜV-approved connectors for models $\alpha 1$, and $\alpha 2$. The table below lists the specifications of connector kits. The connectors used in models $\alpha 1$ and $\alpha 2$ are dripproof in an engaged position.

8.2.1 Connector Kit Specifications

| Motor model | Power cable | Signal cable (straight type) | |
|---------------------------------------|---|--|---------------------------------------|
| Connector kit specifications | 176346-8 (AMP Japan) A06B-6050-K121 (FANUC specification) | HDAB-15S [connector] HDAW-15-CV [waterproof cover] (Hirose Electric) A06B-6050-K115 (FANUC specification) | |
| Applicable wire size (Note1) | AWG#18 to AWG#16 | AWG#20 (maximum) | |
| Insulation external diameter (Note 2) | $\phi 1.8$ to 2.8 | Not specified | |
| Compatible cable O.D. | $\phi 10.4$ to 11.4 | $\phi 8.4$ to 9.2 | Water proof: $\phi 10.4$ to 11.2 |

CAUTION

1 AMP Japan connector contacts used in the power cable for the $\alpha 1$ and $\alpha 2$ are crimp type. Be careful about the applicable wire. The size of conductors used must meet the following requirements so that they carry the required current.

$\alpha 1$ and 2 power cables: AWG#18 to 16
 $\alpha 1$ and $\alpha 2$ signal cables: AWG#20 for +5V, 0V, 6VA,
and 0VA, and AWG#24 or
greater for the others

2 For $\alpha 1$ and $\alpha 2$ power cables, select the external diameter that matches the cable clamp applicable range (10.4 to 11.4 mm²) in order to secure TÜV approval and waterproof performance. (See above table)

NOTE

For crimp contacts, insulations as well as wires are crimped. So, they must meet the size requirements listed above. An insulation smaller than those listed here may also be used depending on the wire and tool used. Contact AMP Japan for details.

The following dedicated tools are required to insert and remove the contacts. They should be prepared separately from the connector kit.

Crimping tool specification (power connector for $\alpha 1$ and $\alpha 2$):

914596-3 (AMP Japan)

A97L-0200-0979/L

(FANUC)

Extractor specification (power connector for $\alpha 1$, and $\alpha 2$):

914677-1 (AMP Japan)

A97L-0200-0980/D3 (FANUC)

8.2.2 Cable Assembly Specifications (14m Standard) (for $\alpha 1$ and $\alpha 2$)

The following cables for $\alpha 1$ and 2 are provided by FANUC.

| Motor Type | For Power | For Power (for model with brake) | For Signal |
|---|---------------------------------------|---------------------------------------|---|
| $\alpha 1/3000$ $\alpha 2/2000$ $\alpha 2/3000$ $\alpha M2/3000$ $\alpha M2.5/2000$ | A06B-6080-K824 (w/ shielded leads) | A06B-6080-K825 (w/ shielded leads) | A06B-6080-K841 (w/ double-shielded leads) |

* All cables in the above table are EMC-compliant.

* The cable assembly for signals is usable when the NC is Series 16, Series 18-A, Series 15-B, Series 21-TA, Power Mate MODEL D, F (TYPE A I/F), Series 16-B, Series 18-B, Series 20, Series 21-GA, Series 21-TB, or Power Mate MODEL H (TYPE B I/F).


8.3 SPECIFICATIONS OF THE CONNECTORS ON THE CABLE SIDE (MODELS α 3 AND HIGHER)

To meet the IEC34 standard, TÜV-approved plug connectors and cable clamps should be used in connecting the power cable and brake/fan unit. To meet the IEC34 standard by using a cable or conduit hose seal adaptor, contact the manufacturer for details.

FANUC can provide TÜV-approved types (waterproof) and waterproof types as plug connectors on the cable side for the FANUC α series AC servo motors; all these connectors are black. Of course, conventional plug connectors may be used, because they are MS-compatible.

The specifications of each connector are explained based on the examples shown below.

Example of connector connection



8.3.1 Specifications of Plug Connectors on the Cable Side (Waterproof TÜV-approved Type)

| Model Name | [A] Straight Type Plug Connector | [B] Elbow Type Plug Connector | [C] Cable Clamp | [D] Single Block Type Plug Connector |
|---|---|--|---|---|
| For Power | | | | |
| α 3/3000, α 6/2000 α 6/3000, α M6/3000, α M9/3000 α L6/3000, α L9/3000 α C3/2000, α C6/2000 α 3/3000HV α 6/3000HV α M6/3000HV α M9/3000HV | H/MS3106A18-10S-D-T(10) (Hirose Electric) | H/MS3108A18-10S-D-T(10) (Hirose Electric) | H/MS3057-10A(10) (Hirose Electric) | H/MS3106A18-10S-D-T(13) (Hirose Electric) |
| α 12/2000, α 12/3000 α 22/1500, α 22/2000 α 30/1200 α C12/2000, α C22/1500 α 12/3000HV α 22/3000HV α 30/3000HV α 40/2000HV α M22/3000HV α M30/3000HV α M40/3000HV | JL04V-6A22-22SE-EB (Japan Aviation Electronics Industry) | JL04V-8A22-22SE-EB (Japan Aviation Electronics Industry) | JL04-2022CK-(14) (Japan Aviation Electronics Industry) | JL04V-6A22-22SE (Japan Aviation Electronics Industry) |
| α 22/3000, α 30/2000 α 30/3000, α 40/2000 α 40/2000FAN (*1) α M22/3000 α M30/3000 α M40/3000 α M40/3000FAN (*1) α L25/3000 α L50/2000 | JL04V-6A24-10SE(G)-EB (Japan Aviation Electronics Industry) | JL04V-8A24-10SE(G)-EB (Japan Aviation Electronics Industry) | JL04-2428CK-(17) (Japan Aviation Electronics Industry) | JL04V-6A24-10SE(G) (Japan Aviation Electronics Industry) |
| For Signal | | | | |
| Common to all models | Not subject to IEC34 standard (Select from the water-proof connectors in the following item.) | | | |
| For Brake | | | | |
| Common to all models (excluding α HV series) (*1) | JL04V-6A10SL-3SE-EB (Japan Aviation Electronics Industry) | JL04V-8A10SL-3SE-EB (Japan Aviation Electronics Industry) | JL04-1012CK-(05) (Japan Aviation Electronics Industry) | JL04V-6A10SL-3SE (Japan Aviation Electronics Industry) |
| α HV series | Not subject to IEC34 standard (Select from the water-proof connectors in the following item.) | | | |

*1 The connector for the α 40 fan and α M40 fan is the same connector used on a standard brake.

NOTE

- 1 You must pay attention when selecting connectors made by manufacturers not listed in the table above. For details, "5. IEC34 Standard Compliance Authorization Conditions."
- 2 When connector type [D] is used, and a seal adapter must be used for compliance with the IEC34 standard, consult the contact manufacturer separately.
- 3 Signal connectors and brake connectors for the α HV series are not subject to the IEC34 standard. Select from the water-proof connectors in the following item.

8.3.2 Specifications of Plug Connectors on the Cable Side (Waterproof Type)

| Model Name | [A] Straight Type Plug Connector | [B] Elbow Type Plug Connector | [C] Cable Clamp | [D] Single Block Type Plug Connector |
|---|---|---|---|--|
| For Power | | | | |
| α 3/3000, α 6/2000 α 6/3000, α M6/3000, α M9/3000 α L6/3000, α L9/3000 α C3/2000, α C6/2000 α 3/3000HV α 6/3000HV α M6/3000HV α M9/3000HV | JA06A-18-10S-J1-EB (Japan Aviation Electronics Industry) H/MS3106A18-10S(10) (Hirose Electric) MS3106A18-10S-B-BSS (DDK Ltd.) | JA08A-18-10S-J1-EB (Japan Aviation Electronics Industry) H/MS3108A18-10S(10) (Hirose Electric) MS3108A18-10S-B-BAS (DDK Ltd.) | JL04-18CK(13) (Japan Aviation Electronics Industry) H/MS3057-10A(10) (Hirose Electric) CE3057-10A-1(D265) (DDK Ltd.) | JA06A-18-10S-J1-(A72) (Japan Aviation Electronics Industry) H/MS3106A18-10S(13) (Hirose Electric) MS3106A18-10S-B (D190) (DDK Ltd.) |
| α 12/2000, α 12/3000 α 22/1500, α 22/2000 α 30/1200 α C12/2000, α C22/1500 α 12/3000HV α 22/3000HV α 30/3000HV α 40/2000HV α M22/3000HV α M30/3000HV α M40/3000HV | JA06A-22-22S-J1-EB (Japan Aviation Electronics Industry) H/MS3106A22-22S(10) (Hirose Electric) MS3106A22-22S-B-BSS (DDK Ltd.) | JA08A-22-22S-J1-EB (Japan Aviation Electronics Industry) H/MS3108B22-22S(10) (Hirose Electric) MS3108A22-22S-B-BAS (DDK Ltd.) | JL04-2022CK-(14) (Japan Aviation Electronics Industry) H/MS3057-12A(10) (Hirose Electric) CE3057-12A-1(D265) (DDK Ltd.) | JA06A-22-22S-J1-(A72) (Japan Aviation Electronics Industry) H/MS3106A22-22S(13) (Hirose Electric) MS3106A22-22S-B (D190) (DDK Ltd.) |
| α 22/3000, α 30/2000 α 30/3000, α 40/2000 α 40/2000FAN (*1) α M22/3000 α M30/3000 α M40/3000 α M40/3000HV FAN (*1) α L25/3000 α L50/2000 | JA06A-24-10S-J1-EB (Japan Aviation Electronics Industry) H/MS3106A24-10S(10) (Hirose Electric) MS3106A24-10S-B-BSS (DDK Ltd.) | JA08A-24-10S-J1-EB (Japan Aviation Electronics Industry) H/MS3108B24-10S(10) (Hirose Electric) MS3108A24-10S-B-BAS (DDK Ltd.) | JL04-2428CK-(17) (Japan Aviation Electronics Industry) H/MS3057-16A(10) (Hirose Electric) CE3057-16A-1(D265) (DDK Ltd.) | JA06A-24-10S-J1-(A72) (Japan Aviation Electronics Industry) H/MS3106A24-10S(13) (Hirose Electric) MS3106A24-10S-B (D190) (DDK Ltd.) |

| Model Name | [A] Straight Type Plug Connector | [B] Elbow Type Plug Connector | [C] Cable Clamp | [D] Single Block Type Plug Connector |
|---|---|---|--|---|
| For Signal | | | | |
| Common to all models | JA06A-20-29SW-J1-EB (Japan Aviation Electronics Industry) H/MS3106A20-29SW(11) (Hirose Electric) MS3106A20-29SW-B-BSS (DDK Ltd.) | JA08A-20-29SW-J1-EB (Japan Aviation Electronics Industry) H/MS3108B20-29SW(11) (Hirose Electric) MS3108A20-29SW-B-BAS (DDK Ltd.) | JL04-2022CK-(14) (Japan Aviation Electronics Industry) H/MS3057-12A(10) (Hirose Electric) CE3057-12A-1(D265) (DDK Ltd.) | JA06A-20-29SW-JA-(A72) (Japan Aviation Electronics Industry) H/MS3106A20-29SW(14) (Hirose Electric) MS3106A20-29SW-B(D190) (DDK Ltd.) |
| For Brake | | | | |
| Common to all models (excluding α HV series)*1 | JA06A-10SL-3S-J1-EB (Japan Aviation Electronics Industry) H/MS3106A10SL-3S(10) (Hirose Electric) MS3106A10SL-3S-B-BSS (DDK Ltd.) | JA08A-10SL-3S-J1-EB (Japan Aviation Electronics Industry) H/MS3108B10SL-3S(10) (Hirose Electric) MS3108A10SL-3S-B-BAS (DDK Ltd.) | JA04-1012CK-(06) (Japan Aviation Electronics Industry) H/MS3057-4A1(10) (Hirose Electric) CE3057-4A-1(D265) (DDK Ltd.) | JA06A-10SL-3S-J1-(A72) (Japan Aviation Electronics Industry) H/MS3106A10SL-3S(13) (Hirose Electric) MS3106A10SL-3S-B-(D190) (DDK Ltd.) |
| α HV series | JA06A-10SL-4S-J1-EB (Japan Aviation Electronics Industry) H/MS310610SL-4S(10) (Hirose Electric) MS3106A10SL-4S-B-BSS (DDK Ltd.) | JA08A-10SL-4S-J1-EB (Japan Aviation Electronics Industry) H/MS3108B10SL-4S(10) (Hirose Electric) MS3108A10SL-4S-B-BAS (DDK Ltd.) | JL04-1012CK-(06) (Japan Aviation Electronics Industry) H/MS3057-4A1(10) (Hirose Electric) CE3057-4A-1(D265) (DDK Ltd.) | JA06A-10SL-4S-J1-(A72) (Japan Aviation Electronics Industry) H/MS3106A10SL-4S(13) (Hirose Electric) MS3106A10SL-4S-B-(D190) (DDK Ltd.) |

*1 The connector for the α 40 fan or α M40 fan is the same connector used on a standard brake.

Cable-side plug connector specification (waterproof/seal adapter specification)

| Model Name | [E] Cable Seal Adapter Straight Type | [F] Cable Seal Adapter Elbow Type | [G] Conduit Hose Seal Adapter Straight Type | [H] Conduit Hose Seal Adapter Elbow Type |
|---|--|--|--|--|
| For Power | | | | |
| α 3/3000, α 6/2000 α 6/3000, α M6/3000, α M9/3000 α L6/3000, α L9/3000 α C3/2000, α C6/2000 α 3/3000HV α 6/3000HV α M6/3000HV α M9/3000HV | YSO 18-12-14 (DAIWA DENGYOU CO., LTD.) ACS-12RL-MS18F (NIPPON FLEX CO., LTD.) CKD12-18 (SANKEI MANUFACTURING CO., LTD.) | YLO 18-12-14 (DAIWA DENGYOU CO., LTD.) ACA-12RL-MS18F (NIPPON FLEX CO., LTD.) C90° KD12-18 (SANKEI MANUFACTURING CO., LTD.) | MSA 16-18 (DAIWA DENGYOU CO., LTD.) RCC-104RL-MS18F (NIPPON FLEX CO., LTD.) KKD16-18 (SANKEI MANUFACTURING CO., LTD.) | MAA 16-18 (DAIWA DENGYOU CO., LTD.) RCC-304RL-MS18F (NIPPON FLEX CO., LTD.) K90° KD16-18 (SANKEI MANUFACTURING CO., LTD.) |
| α 12/2000, α 12/3000 α 22/1500, α 22/2000 α 30/1200 α C12/2000, α C22/1500 α 12/3000HV α 22/3000HV α 30/3000HV α 40/2000HV α M22/3000HV α M30/3000HV α M40/3000HV | YSO 22-12-14 (DAIWA DENGYOU CO., LTD.) ACS-16RL-MS22F (NIPPON FLEX CO., LTD.) CKD16-22 (SANKEI MANUFACTURING CO., LTD.) | YLO 22-12-14 (DAIWA DENGYOU CO., LTD.) ACA-16RL-MS22F (NIPPON FLEX CO., LTD.) C90° KD16-22 (SANKEI MANUFACTURING CO., LTD.) | MSA 22-22 (DAIWA DENGYOU CO., LTD.) RCC-106RL-MS22F (NIPPON FLEX CO., LTD.) KKD22-22 (SANKEI MANUFACTURING CO., LTD.) | MAA 22-22 (DAIWA DENGYOU CO., LTD.) RCC-306RL-MS22F (NIPPON FLEX CO., LTD.) K90° KD22-22 (SANKEI MANUFACTURING CO., LTD.) |

| Model Name | [E] Cable Seal Adapter Straight Type | [F] Cable Seal Adapter Elbow Type | [G] Conduit Hose Seal Adapter Straight Type | [H] Conduit Hose Seal Adapter Elbow Type |
|--|--|--|--|--|
| α 22/3000, α 30/2000 α 30/3000, α 40/2000 α 40/2000FAN (*1) α M22/3000 α M30/3000 α M40/3000 α M40/3000FAN (*1) α L25/3000 α L50/2000 | YSO 24-15-17 (DAIWA DENGYOU CO., LTD.) ACS-20RL-MS24F (NIPPON FLEX CO., LTD.) CKD20-24 (SANKEI MANUFACTURING CO., LTD.) | YLO 24-15-17 (DAIWA DENGYOU CO., LTD.) ACS-20RL-MS24F (NIPPON FLEX CO., LTD.) C90° KD20-24 (SANKEI MANUFACTURING CO., LTD.) | MSA 22-24 (DAIWA DENGYOU CO., LTD.) RCC-106RL-MS24F (NIPPON FLEX CO., LTD.) KKD22-24 (SANKEI MANUFACTURING CO., LTD.) | MAA 22-24 (DAIWA DENGYOU CO., LTD.) RCC-306RL-MS24F (NIPPON FLEX CO., LTD.) K90° KD22-24 (SANKEI MANUFACTURING CO., LTD.) |
| For Signal | | | | |
| Common to all models | YSO 20-9-11 (DAIWA DENGYOU CO., LTD.) ACS-12RL-MS20F (NIPPON FLEX CO., LTD.) CKD12-20 (SANKEI MANUFACTURING CO., LTD.) | YLO 20-9-11 (DAIWA DENGYOU CO., LTD.) ACA-12RL-MS20F (NIPPON FLEX CO., LTD.) C90° KD12-20 (SANKEI MANUFACTURING CO., LTD.) | MSA 16-20 (DAIWA DENGYOU CO., LTD.) RCC-104RL-MS20F (NIPPON FLEX CO., LTD.) KKD16-20 (SANKEI MANUFACTURING CO., LTD.) | MAA 16-20 (DAIWA DENGYOU CO., LTD.) RCC-304RL-MS20F (NIPPON FLEX CO., LTD.) K90° KD16-20 (SANKEI MANUFACTURING CO., LTD.) |
| For Brake | | | | |
| Common to all models (*1) | YSO 10-5-8 (DAIWA DENGYOU CO., LTD.) CKD8-10 (SANKEI MANUFACTURING CO., LTD.) | YLO 10-5-8 (DAIWA DENGYOU CO., LTD.) C90° KD8-10 (SANKEI MANUFACTURING CO., LTD.) | MSA 10-10 (DAIWA DENGYOU CO., LTD.) KKD10-10 (SANKEI MANUFACTURING CO., LTD.) | MAA 10-10 (DAIWA DENGYOU CO., LTD.) K90° KD10-10 (SANKEI MANUFACTURING CO., LTD.) |

*1 The connector for the α 40 fan or α M40 fan is the same connector used on a standard brake.

Water-proofing performance can be improved by using a [D] single block type connector in combination with an [E] to [H] seal adapter. The above table is for reference only. Consult the respective manufacturer for details.

8.3.3 Specifications of Plug Connectors on the Cable Side (Non-waterproof Type)

| Model Name | [A] Straight Type Plug Connector | [B] Elbow Type Plug Connector | [C] Cable Clamp |
|--|--|--|---|
| For Power | | | |
| α 3/3000, α 6/2000 α 6/3000, α M6/3000, α M9/3000 α L6/3000, α L9/3000 α C3/2000, α C6/2000 α 3/3000HV α 6/3000HV α M6/3000HV α M9/3000HV | MS3106B18-10S-(A72) (Japan Aviation Electronics Industry) H/MSA3106A18-10S(10) (Hirose Electric) MS3106B18-10S-B (DDK Ltd.) | MS3108B18-10S-(A72) (Japan Aviation Electronics Industry) H/MSA3108B18-10S(10) (Hirose Electric) MS3108B18-10S-B (DDK Ltd.) | MS3057-10A-(A72) (Japan Aviation Electronics Industry) H/MSA3057-10A(10) (Hirose Electric) MS3057-10A(D265) (DDK Ltd.) |

| Model Name | [A] Straight Type Plug Connector | [B] Elbow Type Plug Connector | [C] Cable Clamp |
|---|---|---|---|
| α 12/2000, α 12/3000 α 22/1500, α 22/2000 α 30/1200 α C12/2000, α C22/1500 α 12/3000HV α 22/3000HV α 30/3000HV α 40/2000HV α M22/3000HV α M30/3000HV α M40/3000HV | MS3106B22-22S-(A72) (Japan Aviation Electronics Industry) H/MSA3106A22-22S(10) (Hirose Electric) MS3106B22-22S-B (DDK Ltd.) | MS3108B22-22S-(A72) (Japan Aviation Electronics Industry) H/MSA3108B22-22S(10) (Hirose Electric) MS3108B22-22S-B (DDK Ltd.) | MS3057-12A-(A72) (Japan Aviation Electronics Industry) H/MSA3057-12A(10) (Hirose Electric) MS3057-12A(D265) (DDK Ltd.) |
| α 22/3000, α 30/2000 α 30/3000, α 40/2000 α 40/2000FAN (*1) α M22/3000 α M30/3000 α M40/3000 α M40/3000FAN (*1) α L25/3000 α L50/2000 | MS3106B24-10S-(A72) (Japan Aviation Electronics Industry) H/MSA3106A24-10S(10) (Hirose Electric) MS3106A24-10S-B (DDK Ltd.) | MS3108B24-10S-(A72) (Japan Aviation Electronics Industry) H/MSA3108B24-10S(10) (Hirose Electric) MS3108B24-10S-B (DDK Ltd.) | MS3057-16A-(A72) (Japan Aviation Electronics Industry) H/MSA3057-16A(10) (Hirose Electric) MS3057-16A(D265) (DDK Ltd.) |
| For Signal | | | |
| Common to all models | MS3106B20-29SW-(A72) (Japan Aviation Electronics Industry) H/MSA3106A20-29SW(11) (Hirose Electric) MS3106A20-29SW-B (DDK Ltd.) | MS3108B20-29SW-(A72) (Japan Aviation Electronics Industry) H/MSA3108B20-29SW(11) (Hirose Electric) MS3108B20-29SW-B (DDK Ltd.) | MS3057-12A-(A72) (Japan Aviation Electronics Industry) H/MSA3057-12A(10) (Hirose Electric) MS3057-12A(D265) (DDK Ltd.) |
| For Brake | | | |
| Common to all models (excluding α HV series)*1 | MS3106B10SL-3S-(A72) (Japan Aviation Electronics Industry) H/MSA3106A10SL-3S(10) (Hirose Electric) MS3106A10SL-3S-B (DDK Ltd.) | MS3108B10SL-3S-(A72) (Japan Aviation Electronics Industry) H/MSA3108B10SL-3S(10) (Hirose Electric) MS3108A10SL-3S-B (DDK Ltd.) | MS3057-4A-(A72) (Japan Aviation Electronics Industry) H/MSA3057-4A(10) (Hirose Electric) MS3057-4A(D265) (DDK Ltd.) |
| α HV series | MS3106B10SL-4S-(A72) (Japan Aviation Electronics Industry) H/MSA3106A10SL-4S(10) (Hirose Electric) MS3106A10SL-4S-B (DDK Ltd.) | MS3108B10SL-4S-(A72) (Japan Aviation Electronics Industry) H/MSA3108B10SL-4S(10) (Hirose Electric) MS3108A10SL-4S-B (DDK Ltd.) | MS3057-4A-(A72) (Japan Aviation Electronics Industry) H/MSA3057-4A(10) (Hirose Electric) MS3057-4A(D265) (DDK Ltd.) |

*1 The connector for the α 40 fan or α M40 fan is the same connector used on a standard brake.

The table only examples. Contact each manufacturer for details.

8.3.4 Cable Assembly Specifications (α 3 or Above) (14m Standard)

The following cables for α 3 and above are provided by FANUC.

| Motor Type | For Power (top row: straight type, bottom row: elbow type) | For Signal (top row: straight type, bottom row: elbow type) | For Brake and Fan (elbow type only) |
|--|--|---|-------------------------------------|
| α 3/3000, α 6/2000 α 6/3000, α M6/3000, α M9/3000 α L6/3000, α L9/3000 α C3/2000, α C6/2000 | A06B-6080-K800 A06B-6080-K801 | | A06B-6080-K806 |
| α 3/3000HV α 6/3000HV α M6/3000HV α M9/3000HV | | | A06B-6080-K807 |
| α 12/2000, α 12/3000 α 22/1500, α 22/2000 α 30/1200 α C12/2000, α C22/1500 | | | A06B-6080-K806 |
| α 12/3000HV α 22/3000HV α 30/3000HV α 40/2000HV α M22/3000HV α M30/3000HV α M40/3000HV | A06B-6080-K802 A06B-6080-K803 | A06B-6080-K842 A06B-6080-K843 | A06B-6080-K807 |
| α 22/3000, α 30/2000 α 30/3000, α 40/2000 α 40/2000FAN (*2) α M22/3000 α M30/3000 α M40/3000 α M40/3000FAN (*2) α L25/3000 α L50/2000 | A06B-6080-K804 A06B-6080-K805 | | A06B-6080-K806 |

*1 All cables in the above table are EMC-compliant.

*2 Cable for fan of the α 40/2000 fan and α M40/3000 fan is A06B-6080-K806.

9

COOLING FAN



Models α 40, α M40, α 300, α 400, and α 1000 can be fitted with an optional cooling fan. The cooling fan requires a single-phase 200 VAC or three-phase 200VAC power supply.

The specifications and connection diagram are given below. Use fuses or a circuit breaker in the power magnetics cabinet.

9.1 COOLING FAN SPECIFICATIONS

| Motor Type | α 40 with Fan | |
|--|-------------------------|-------------------------|
| Input Voltage [V] | Single-phase 200 VAC | Single-phase 230 VAC |
| Rated Current [A] | 0.64 ± 0.06 | 0.74 ± 0.06 |
| Surge Current [A] | 1.06 ± 0.1 | 1.22 ± 0.1 |
| Protection Circuit Setting Temperature [°C] | 135 | |
| Protection Type (IEC34-5) | IP00 | |

| Motor Type | Input voltage | Rated current(Arms) | |
|--|---------------------|---------------------|----------|
| | | 50Hz | 60Hz |
| α M40/3000 (with fan) | 200V (Single-phase) | 0.25 Arms | 0.23Arms |
| α 300/2000 α 400/2000 | 200V (Three-phase) | 0.25 Arms | 0.35Arms |
| α 1000/2000HV | 200V (Three-phase) | 0.75 Arms | 0.75Arms |

9.2 MOTOR CONNECTOR SPECIFICATIONS

| Motor Type | Receptacle Connector |
|----------------------------|---|
| α 40 with Fan | JL04V-2E10SL-3PE-B (Japan Aviation Electronics Industry) |
| α 300, α 400 | H/MS3102A18-10P-D-T(10) (Hirose Electric) |

* 1 Standard brake connectors are used as fan connectors for the α 40/ α M40.

* 2 α 3-class power connectors are used as fan connectors for the α 300/ α 400.

9.3 ABOUT CONNECTOR CABLES

α 40/2000 with fan,
 α M40/3000 with fan,
 α 300/2000, α 400/2000,
 α 1000/2000HV


The user must prepare connector cables referring to the following specifications.

| Item | Specification |
|--|--|
| Cable plug connector | For details, see the brake and fan connector specifications in "8.3 Cable Connector Specifications." |
| Recommend Lead Diameter (conductor diameter) | 1 mm ² (AWG18 or equivalent) max. |


9.4 WIRING DIAGRAM

α40/2000 with fan
αM40/3000 with fan


The following shows the wiring diagram for connection to the fan unit.



α300/2000
α400/2000



α1000/2000HV



II. FANUC AC SERVO MOTOR α series

1 GENERAL

The FANUC AC servo motor α series consists of a range of servo motors that are suitable for the feed axes of machine tools. They have the following features:

Excellent acceleration characteristics

The rotor inertia has been reduced without sacrificing maximum output torque. As a result, the motors offer excellent acceleration characteristics.

Compact

The use of the latest ferrite magnet, combined with an optimized mechanical design, reduces both the overall length and weight. The result is compact, lightweight servo motors.

Excellent waterproofing

The use of waterproof connectors and FANUC's unique stator seal provide excellent waterproofing, ensuring that no liquid, such as coolant, can enter the motor.

Extended continuous-operation

The use of the latest servo software minimizes the heat generated by high-speed rotation, allowing continuous operation over a wide range.

Smooth rotation

Further improvements have been made to the unique magnetic pole shape to minimize torque ripple. The result is extremely smooth rotation.

Controllability

The use of the latest servo software maintains controllability even when a disturbance occurs.

High-performance detector

The high-resolution pulse coder model α A1000, α A64 or α I64 is provided as standard. This pulse coder allows precise positioning.

Powerful brake

A powerful brake with an increased holding torque is available as an option. The brake uses an asbestos-free design.

2 TYPES OF MOTORS AND DESIGNATION

The types and specifications of α series servo motors are described as follows.

Models

$\alpha 1/3000$, $\alpha 2/2000$,
and $\alpha 2/3000$

A06B-03□□-B☆○○

□□

71 : Model $\alpha 1/3000$

72 : Model $\alpha 2/2000$

73 : Model $\alpha 2/3000$

☆

0 : Taper shaft (standard)

1 : Taper shaft with the brake (2Nm)

5 : Straight shaft

6 : Straight shaft with the brake (2Nm)

○○

75 : Pulse coder $\alpha A64$

77 : Pulse coder $\alpha I64$

88 : Pulse coder $\alpha A1000$

The standard shafts used for models $\alpha 1/3000$, $\alpha 2/2000$, and $\alpha 2/3000$ are taper shafts. Use a taper shaft as far as circumstances, such as the delivery time and maintenance, permit.

Models

$\alpha 3/3000$, $\alpha 6/2000$,
and $\alpha 6/3000$

A06B-01□□-B☆○○

□□

23 : Model $\alpha 3/3000$

27 : Model $\alpha 6/2000$

28 : Model $\alpha 6/3000$

☆

0 : Taper shaft (standard)

1 : Taper shaft with the brake (8Nm)

5 : Straight shaft

6 : Straight shaft with the brake (8Nm)

○○

75 : Pulse coder $\alpha A64$

77 : Pulse coder $\alpha I64$

88 : Pulse coder $\alpha A1000$

The standard shafts used for models $\alpha 3/3000$, $\alpha 6/2000$, and $\alpha 6/3000$ are taper shafts. Use a taper shaft as far as circumstances, such as the delivery time and maintenance, permit.

Models

α 12/2000, α 12/3000,
 α 22/1500, α 22/2000,
 α 22/3000, α 30/1200,
 α 30/2000, α 30/3000,
 α 40/2000, and
 α 40/2000 (with fan)

A06B-01□□-B☆○○

□□

- 42 : Model α 12/2000
- 43 : Model α 12/3000
- 46 : Model α 22/1500
- 47 : Model α 22/2000
- 48 : Model α 22/3000
- 51 : Model α 30/1200
- 52 : Model α 30/2000
- 53 : Model α 30/3000
- 57 : Model α 40/2000
- 58 : Model α 40/2000 (with fan)

☆

- 0 : Straight shaft (standard)
- 1 : Straight shaft with the brake (35Nm)
- 5 : Taper shaft
- 6 : Taper shaft with the brake (35Nm)

○○

- 75 : Pulse coder α A64
- 77 : Pulse coder α I64
- 88 : Pulse coder α A1000

A straight shaft is fitted as the standard shaft for models α 12 to α 40. When early delivery and case-of-maintenance are important, a straight shaft should be used. For model α 40, a tapered shaft is not available.

Models

α 65/2000, α 100/2000,
and α 150/2000

A06B-03□□-B☆○○

□□

- 31 : Model α 65/2000
- 32 : Model α 100/2000
- 33 ; Model α 150/2000

☆

- 0 : Taper shaft (standard)
- 2 : Taper shaft with the brake (100Nm)

○○

- 75 ; Pulse coder α A64
- 77 : Pulse coder α I64
- 88 : Pulse coder α A1000

Models

α 300/2000,
 α 400/2000

A06B-013**-B0**

7 : Model α 300/2000

8 : Model α 400/2000

75 ; With the pulse coder α A64

77 : With the pulse coder α I64

88 : With the pulse coder α A1000

- For these models, a tapered shaft is standard. a straight shaft is not available.
- For these models, a brake option is not available.

3

SPECIFICATIONS AND CHARACTERISTICS



3.1 TYPE OF MOTORS AND SPECIFICATIONS

| Item | Unit | $\alpha 1/3000$ | $\alpha 2/2000$ $\alpha 2/3000$ |
|----------------------------|-----------------------|-----------------|------------------------------------|
| Output | kw | 0.3 | 0.4 0.5 |
| | HP | 0.4 | 0.5 0.6 |
| Rated torque at stall | Nm | 1.0 | 2.0 |
| | kgf·cm | 10 | 20 |
| Rating rota- tion speed | min ⁻¹ | 3000 | 2000 3000 |
| Rotor inertia | kg·m ² | 0.00030 | 0.00055 |
| | kgf·cm·s ² | 0.0031 | 0.0056 |
| Mass | kg | 2.8 | 4.3 |

The above values are under the condition at 20°C.

| Item | Unit | $\alpha 3/3000$ | $\alpha 6/2000$ $\alpha 6/3000$ |
|----------------------------|-----------------------|-----------------|------------------------------------|
| Output | kw | 0.9 | 1.0 1.4 |
| | HP | 1.3 | 1.4 1.9 |
| Rated torque at stall | Nm | 3.0 | 6.0 |
| | kgf·cm | 31 | 61 |
| Rating rota- tion speed | min ⁻¹ | 3000 | 2000 3000 |
| Rotor inertia | kg·m ² | 0.0014 | 0.0026 |
| | kgf·cm·s ² | 0.014 | 0.027 |
| Mass | kg | 8 | 13 |

The above values are under the condition at 20°C.

| Item | Unit | α 12/2000 α 12/3000 | α 22/1500 α 22/2000 α 22/3000 | α 30/1200 α 30/2000 α 30/3000 | α 40/2000 | α 40/2000 (with fan) |
|----------------------------|-----------------------|--------------------------------------|--|--|------------------|--------------------------------|
| Output | kw | 2.1 2.8 | 3.0 3.8 4.4 | 3.3 4.5 4.8 | 5.9 | 7.3 |
| | HP | 2.8 3.8 | 4.0 5.0 5.9 | 4.4 6.0 6.4 | 7.8 | 9.8 |
| Rated torque at stall | Nm | 12 | 22 | 30 | 38 | 56 |
| | kgf·cm | 122 | 225 | 306 | 387 | 571 |
| Rating rota- tion speed | min ⁻¹ | 2000 3000 | 1500 2000 3000 | 1200 2000 3000 | 2000 | 2000 |
| Rotor inertia | kg·m ² | 0.0062 | 0.012 | 0.017 | 0.022 | 0.022 |
| | kgf·cm·s ² | 0.064 | 0.12 | 0.17 | 0.23 | 0.23 |
| Mass | kg | 18 | 29 | 41 | 52 | 55 |

The above values are under the condition at 20°C.

| Item | Unit | α 65/2000 | α 100/2000 | α 150/2000 | α 40/2000HV | α M40/3000HV |
|----------------------------|-----------------------|------------------|-------------------|-------------------|--------------------|---------------------|
| Output | kw | 8.2 | 10 | 12 | 37 | 40 |
| | HP | 11 | 14 | 16 | 50 | 54 |
| Rated torque at stall | Nm | 65 | 100 | 150 | 300 | 390 |
| | kgf·cm | 663 | 1019 | 1529 | 3060 | 3980 |
| Rating rota- tion speed | min ⁻¹ | 2000 | 2000 | 2000 | 2000 | 2000 |
| Rotor inertia | kg·m ² | 0.019 | 0.026 | 0.034 | 0.079 | 0.103 |
| | kgf·cm·s ² | 0.19 | 0.27 | 0.35 | 0.80 | 1.05 |
| Mass | kg | 80 | 100 | 120 | 180 | 220 |

The above values are under the condition at 20°C.

3.2 CHARACTERISTIC CURVE AND DATA SHEET

Speed-torque characteristics

The intermittent operation zone is determined by the input voltage applied to the drive amplifier. The curve shown is the value for the rated input voltage (200V).

On models $\alpha 1$ to 6, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item.

Overload duty characteristic

The overload duty characteristic curves are determined based on the temperature restriction for the single motor unit (the temperature is restricted by means of a thermal trip built into the motor). The curves are determined by assuming that the temperature increases gradually under certain overload conditions. Therefore, the curves do not apply to the rapid temperature rise which occurs, for example, when the motor shaft is locked. (An overcurrent flows in the motor windings until the thermal trip operates. The temperature rises momentarily.)

To detect such an abrupt temperature rise, the FANUC digital servo system provides a software thermal function that uses servo software to observe the current. During operation that is characterized by frequent acceleration/deceleration cycles, control is imposed by the software thermal function.

Driving units (such as amplifiers) and built-in detectors contain their own overheating protection devices. Therefore, note that control may be imposed according to how the equipment is being used.

Data sheet

The parameters given in the data sheet are representative values for an ambient temperature of 20°C. They are subject to an error of +10%.

The indicated logical values are threshold values for the single motor unit (when the motor is not restricted by the control system).

The maximum torque that can be produced during acceleration or deceleration in actual use is calculated as the approximate product of the motor torque constant and the current limit value of the amplifier.

Example : $\alpha 3/3000$


- Motor torque constant = 0.65 (Nm/Arms)
- Amplifier limit value = 40 A_{peak}
- Maximum torque value
= $40 \times 0.707 \times 0.65$
(Converted to an effective value)
= 18.4 Nm

This value is for reference only. The actual value will vary depending on changes in the power supply, as well as variations in motor parameters and amplifier limit values.

In some models, if the maximum current flows in the motor, the actual maximum torque is affected by, for example, magnetic saturation. As a result, the actual maximum torque will be lower than the calculated value. The intermittent operation area (maximum torque value) indicated in the speed to torque characteristics is the effective value, determined according to the combination with the amplifier.

Model $\alpha 1/3000$

Specification : A06B-0371-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|---------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 1.0 | | Nm |
| | | 10 | | kgfcm |
| Rotor inertia | Jm | 0.00030 | | kgm ² |
| | | 0.0031 | | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 2.3 | | A (rms) |
| Torque constant (*) | Kt | 0.44 | | Nm/A (rms) |
| | | 4.5 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 15.5 | | V (rms)/1000min ⁻¹ |
| | | 0.15 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 1.73 | | Ω |
| Mechanical time constant (*) | tm | 0.010 | | s |
| Thermal time constant | tt | 15 | | min |
| Static friction | Tf | 0.10 | | Nm |
| | | 1 | | kgfcm |
| Mass | | 2.8 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.


On model $\alpha 1$, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item.

Model α 2/2000

Specification : A06B-0372-B□□□

Model α 2/3000

Specification : A06B-0373-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|---------|---------|-------------------------------|
| Rating rotation speed | Nmax | 2000 | 3000 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 2.0 | 2.0 | Nm |
| | | 20 | 20 | kgfcm |
| Rotor inertia | Jm | 0.00055 | 0.00055 | kgm ² |
| | | 0.0056 | 0.0056 | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 2.2 | 3.0 | A (rms) |
| Torque constant (*) | Kt | 0.90 | 0.67 | Nm/A (rms) |
| | | 9.2 | 6.9 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 31.3 | 23.5 | V (rms)/1000min ⁻¹ |
| | | Kv | 0.30 | 0.22 |
| Armature resistance (1-phase) (*) | Ra | 2.44 | 1.38 | Ω |
| Mechanical time constant (*) | tm | 0.005 | 0.005 | s |
| Thermal time constant | tt | 20 | 20 | min |
| Static friction | Tf | 0.15 | 0.15 | Nm |
| | | 1.5 | 1.5 | kgfcm |
| Mass | | 4.3 | 4.3 | kg |


(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model α 2, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item.

Model $\alpha 3/3000$

Specification : A06B-0123-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 3.0 | | Nm |
| | | 31 | | kgfcm |
| Rotor inertia | Jm | 0.0014 | | kgm ² |
| | | 0.014 | | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 4.6 | | A (rms) |
| Torque constant (*) | Kt | 0.65 | | Nm/A (rms) |
| | | 6.6 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 23 | | V (rms)/1000min ⁻¹ |
| | | 0.22 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.57 | | Ω |
| Mechanical time constant (*) | tm | 0.006 | | s |
| Thermal time constant | tt | 45 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Mass | | 8.0 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.


On model $\alpha 3$, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item.

Model α 6/2000

Specification : A06B-0127-B□□□

Model α 6/3000

Specification : A06B-0128-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--------|-------------------------------|
| Rating rotation speed | Nmax | 2000 | 3000 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 6.0 | 6.0 | Nm |
| | | 61 | 61 | kgfcm |
| Rotor inertia | Jm | 0.0026 | 0.0026 | kgm ² |
| | | 0.027 | 0.027 | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 5.6 | 10.0 | A (rms) |
| Torque constant (*) | Kt | 1.08 | 0.60 | Nm/A (rms) |
| | | 11.0 | 6.1 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 38 | 21 | V (rms)/1000min ⁻¹ |
| | | 0.36 | 0.20 | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.65 | 0.18 | Ω |
| Mechanical time constant (*) | tm | 0.004 | 0.004 | s |
| Thermal time constant | tt | 50 | 50 | min |
| Static friction | Tf | 0.3 | 0.3 | Nm |
| | | 3 | 3 | kgfcm |
| Mass | | 13 | 13 | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.


On model α 6, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item.

Model $\alpha 12/2000$

Specification : A06B-0142-B□□□

Model $\alpha 12/3000$

Specification : A06B-0143-B□□□

**Data sheet**

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--------|-------------------------------|
| Rating rotation speed | Nmax | 2000 | 3000 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 12 | 12 | Nm |
| | | 122 | 122 | kgfcm |
| Rotor inertia | Jm | 0.0062 | 0.0062 | kgm ² |
| | | 0.064 | 0.064 | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 8.8 | 15.5 | A (rms) |
| Torque constant (*) | Kt | 1.36 | 0.77 | Nm/A (rms) |
| | | 13.8 | 7.9 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 47 | 27 | V (rms)/1000min ⁻¹ |
| | | Kv | 0.45 | 0.26 |
| Armature resistance (1-phase) (*) | Ra | 0.49 | 0.17 | Ω |
| Mechanical time constant (*) | tm | 0.005 | 0.005 | s |
| Thermal time constant | tt | 60 | 60 | min |
| Static friction | Tf | 0.8 | 0.8 | Nm |
| | | 8 | 8 | kgfcm |
| Mass | | 18 | 18 | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α 22/1500


Specification : A06B-0146-B□□□

Model α 22/2000

Specification : A06B-0147-B□□□

Model α 22/3000

Specification : A06B-0148-B□□□



Data sheet

| Parameter | Symbol | Value | | | Unit |
|-------------------------------------|--------|-------|-------|-------|-------------------------------|
| Rating rotation speed | Nmax | 1500 | 2000 | 3000 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 22 | 22 | 22 | Nm |
| | | 224 | 224 | 224 | kgfcm |
| Rotor inertia | Jm | 0.012 | 0.012 | 0.012 | kgm ² |
| | | 0.12 | 0.12 | 0.12 | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 12.5 | 18.7 | 32.1 | A (rms) |
| Torque constant (*) | Kt | 1.76 | 1.17 | 0.68 | Nm/A (rms) |
| | | 18.0 | 12.0 | 7.0 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 62 | 41 | 24 | V (rms)/1000min ⁻¹ |
| | | 0.59 | 0.39 | 0.23 | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.315 | 0.140 | 0.049 | Ω |
| Mechanical time constant (*) | tm | 0.004 | 0.004 | 0.004 | s |
| Thermal time constant | tt | 65 | 65 | 65 | min |
| Static friction | Tf | 1.2 | 1.2 | 1.2 | Nm |
| | | 12 | 12 | 12 | kgfcm |
| Mass | | 29 | 29 | 29 | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α 30/1200


Specification : A06B-0151-B□□□

Model α 30/2000

Specification : A06B-0152-B□□□

Model α 30/3000

Specification : A06B-0153-B□□□

**Data sheet**

| Parameter | Symbol | Value | | | Unit |
|-------------------------------------|--------|-------|-------|-------|-------------------------------|
| Rating rotation speed | Nmax | 1200 | 2000 | 3000 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 30 | 30 | 30 | Nm |
| | | 306 | 306 | 306 | kgfcm |
| Rotor inertia | Jm | 0.017 | 0.017 | 0.017 | kgm ² |
| | | 0.17 | 0.17 | 0.17 | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 12.6 | 20.2 | 33.7 | A (rms) |
| Torque constant (*) | Kt | 2.37 | 1.48 | 0.89 | Nm/A (rms) |
| | | 24.2 | 15.1 | 9.1 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 83 | 52 | 31 | V (rms)/1000min ⁻¹ |
| | | 0.79 | 0.49 | 0.30 | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.34 | 0.13 | 0.046 | Ω |
| Mechanical time constant (*) | tm | 0.003 | 0.003 | 0.003 | s |
| Thermal time constant | tt | 70 | 70 | 70 | min |
| Static friction | Tf | 1.8 | 1.8 | 1.8 | Nm |
| | | 18 | 18 | 18 | kgfcm |
| Mass | | 41 | 41 | 41 | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α 40/2000

Specification : A06B-0157-B0□□

Model α 40/2000(with fan)

Specification : A06B-0158-B0□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|-----------------|-------------------------------|
| Rating rotation speed | Nmax | 2000 | 2000 (with fan) | min ⁻¹ |
| Rated torque at stall (*) | Ts | 38 | 56 | Nm |
| | | 390 | 570 | kgfcm |
| Rotor inertia | Jm | 0.022 | 0.022 | kgm ² |
| | | 0.23 | 0.23 | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 27.0 | 40.1 | A (rms) |
| Torque constant (*) | Kt | 1.40 | 1.40 | Nm/A (rms) |
| | | 14.3 | 14.3 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 49 | 49 | V (rms)/1000min ⁻¹ |
| | | Kv | 0.47 | 0.47 |
| Armature resistance (1-phase) (*) | Ra | 0.080 | 0.080 | Ω |
| Mechanical time constant (*) | tm | 0.003 | 0.003 | s |
| Thermal time constant | tt | 75 | 30 | min |
| Static friction | Tf | 1.8 | 1.8 | Nm |
| | | 18 | 18 | kgfcm |
| Mass | | 52 | 55 | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model $\alpha 65/2000$

Specification : A06B-0331-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|--|-------------------------------|
| Rating rotation speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 65 | | Nm |
| | | 660 | | kgfcm |
| Rotor inertia | Jm | 0.019 | | kgm ² |
| | | 0.19 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 62 | | A (rms) |
| Torque constant (*) | Kt | 1.04 | | Nm/A (rms) |
| | | 10.6 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 36 | | V (rms)/1000min ⁻¹ |
| | | 0.35 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.020 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 70 | | min |
| Static friction | Tf | 3.7 | | Nm |
| | | 38 | | kgfcm |
| Mass | | 80 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α 100/2000

Specification : A06B-0332-B□□□



Data sheet


| Parameter | Symbol | Value | Unit |
|-------------------------------------|--------|-------|-------------------------------|
| Rating rotation speed | Nmax | 2000 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 100 | Nm |
| | | 1020 | kgfcm |
| Rotor inertia | Jm | 0.026 | kgm ² |
| | | 0.27 | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 85 | A (rms) |
| Torque constant (*) | Kt | 1.17 | Nm/A (rms) |
| | | 12.0 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 41 | V (rms)/1000min ⁻¹ |
| | | Kv | 0.39 |
| Armature resistance (1-phase) (*) | Ra | 0.014 | Ω |
| Mechanical time constant (*) | tm | 0.001 | s |
| Thermal time constant | tt | 80 | min |
| Static friction | Tf | 5.5 | Nm |
| | | 56 | kgfcm |
| Mass | | 100 | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α 150/2000

Specification : A06B-0333-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|------|-------------------------------|
| Rating rotation speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 150 | | Nm |
| | | 1530 | | kgfcm |
| Rotor inertia | Jm | 0.034 | | kgm ² |
| | | 0.35 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 113 | | A (rms) |
| Torque constant (*) | Kt | 1.31 | | Nm/A (rms) |
| | | 13.3 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 46 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.44 | |
| Armature resistance (1-phase) (*) | Ra | 0.011 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 90 | | min |
| Static friction | Tf | 7.4 | | Nm |
| | | 75 | | kgfcm |
| Mass | | 120 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α 300/2000

Specification : A06B-0137-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|--|--------------------------------|
| Rating rotation speed | Nmax | 2000 | | min^{-1} |
| Rated torque at stall (*) | Ts | 300 | | Nm |
| | | 3060 | | kgfcm |
| Rotor inertia | Jm | 0.079 | | kgm^2 |
| | | 0.80 | | kgfcm s^2 |
| Continuous RMS current at stall (*) | Is | 187 | | A (rms) |
| Torque constant (*) | Kt | 1.55 | | Nm/A (rms) |
| | | 15.9 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 54 | | V (rms)/1000 min^{-1} |
| | | 0.52 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.012 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 150 | | min |
| Static friction | Tf | 2 | | Nm |
| | | 20 | | kgfcm |
| Weight | | 180 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.)

Model α400/2000

Specification : A06B-0138-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|--|-------------------------------|
| Rating rotation speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 390 | | Nm |
| | | 3980 | | kgfcm |
| Rotor inertia | Jm | 0.103 | | kgm ² |
| | | 1.05 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 183 | | A (rms) |
| Torque constant (*) | Kt | 2.07 | | Nm/A (rms) |
| | | 21.2 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 72 | | V (rms)/1000min ⁻¹ |
| | | 0.69 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.014 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 180 | | min |
| Static friction | Tf | 2 | | Nm |
| | | 20 | | kgfcm |
| Weight | | 220 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.)


Speed-torque characteristics (HRV control)

- $\alpha 1/3000$

On the following models, the intermittent operating zone can be extended by using HRV control.




- $\alpha 2/2000$ and $\alpha 2/3000$




NOTE

HRV control sometimes cannot be used depending on the CNC system. Using HRV control increases the intermittent operating zone at high motor operating speeds. The continuous operating zone, however, is the same as when conventional control methods are used.

- $\alpha 3/3000$



- $\alpha 6/2000$ and $\alpha 6/3000$

**NOTE**

HRV control sometimes cannot be used depending on the CNC system. Using HRV control increases the intermittent operating zone at high motor operating speeds. The continuous operating zone, however, is the same as when conventional control methods are used.

3.3 OUTLINE DRAWINGS

| Model | Fig. No. |
|---|-----------------|
| Models $\alpha 1$ and $\alpha 2$ | Fig. 3.3(a) |
| Models $\alpha 1$ and $\alpha 2$ (with the brake) | Fig. 3.3(b) |
| Models $\alpha 1$ and $\alpha 2$ (shaft option) | Fig. 3.3(c) |
| Models $\alpha 3$ and $\alpha 6$ | Fig. 3.3(d) |
| Models $\alpha 3$ and $\alpha 6$ (with the brake) | Fig. 3.3(e) |
| Models $\alpha 3$ and $\alpha 6$ (shaft option) | Fig. 3.3(f) |
| Models $\alpha 12$, $\alpha 22$, $\alpha 30$ and $\alpha 40$ | Fig. 3.3(g) |
| Models $\alpha 12$, $\alpha 22$, $\alpha 30$ and $\alpha 40$ (with the brake) | Fig. 3.3(h) |
| Models $\alpha 12$, $\alpha 22$, $\alpha 30$ and $\alpha 40$ (shaft option) | Fig. 3.3(i) |
| Model $\alpha 40$ (with fan) | Fig. 3.3(j) |
| Model $\alpha 40$ (with fan) (with the brake) | Fig. 3.3(k) |
| Models $\alpha 65$, $\alpha 100$ and $\alpha 150$ | Fig. 3.3(l) |
| Models $\alpha 65$, $\alpha 100$ and $\alpha 150$ (with the brake) | Fig. 3.3(m) |
| Models $\alpha 300$ and $\alpha 400$ | Fig. 3.3(n) (o) |

Fig. 3.3 (a) Models $\alpha 1$ and $\alpha 2$




Fig. 3.3 (d) Models $\alpha 3$ and $\alpha 6$




Fig. 3.3 (e) Models $\alpha 3$ and $\alpha 6$ (with the brake)




Fig. 3.3 (f) Models $\alpha 3$ and $\alpha 6$ (shaft option)




Fig. 3.3 (g) Models $\alpha 12$, $\alpha 22$, $\alpha 30$, and $\alpha 40$




Fig. 3.3 (h) Models $\alpha 12$, $\alpha 22$, $\alpha 30$, and $\alpha 40$ (with the brake)




Fig. 3.3 (i) Models $\alpha 12$, $\alpha 22$, $\alpha 30$, and $\alpha 40$ (shaft option)





Fig. 3.3 (j) Model $\alpha 40$ (with fan)



- Notes)
- Shaft diameter runout Max 0.05mm
 - Ratchet dia. eccentricity Max 0.07mm
 - Mounting face runout Max 0.10mm
 - Rated load 4410N(450kgf)
 - Taps for eyebolt : M8 depth 15+1
 - Eyebolts are not attached
 - No weight more than 100kg
 - No acceleration more than 1G
 - Direction of the air flow is downward only

Fan Motor Specification

| | |
|---------------|---|
| Input Voltage | 200 V |
| Frequency | 50 Hz 60 Hz |
| Input | 40 W 40 W |
| Speed | 2700min ⁻¹ 2900min ⁻¹ |

This chart is spec. for one fan motor.
Prepare a protect fuse in power supply.

Fan Connector

| | |
|-----|---|
| Pin | Note |
| A | Single phase 200Vac 2 fans in parallel |
| B | |
| C | |

Fig. 3.3 (k) Model α40 (with fan) (with the brake)




Fig. 3.3 (I) Models $\alpha 65$, $\alpha 100$, and $\alpha 150$






Fig. 3.3 (o) Models α 300/2000 and α 400/2000 (terminal box)



3.4 CONNECTION OF POWER LINE


Models

α 1/3000, α 2/2000, and α 2/3000




Models

α 3/3000, α 6/2000, and α 6/3000




Models

α 12/2000, α 12/3000, α 22/1500, α 22/2000, and α 30/1200




Models

$\alpha 22/3000$, $\alpha 30/2000$,
 $\alpha 30/3000$, and $\alpha 40/2000$




Models

$\alpha 65/2000$, $\alpha 100/2000$,
and $\alpha 150/2000$



Models

$\alpha 40/2000$ and $\alpha 400/2000$



CAUTION

- 1 The motors should be installed with their connector facing downward as long as possible. When it is impossible to install a motor in this position, allow slack in the cable to keep liquids such as a dielectric fluid from going along the cable into the cable or motor. If there is a possibility that the motors and connectors get wet, provide a cover to protect them.
- 2 If a motor is not connected to the earth ground through the machine (frame), connect the motor grounding point and the amplifier grounding point to absorb noise using a 1.25 mm² or larger conductor other than the grounding conductor in the power cable. Keep the grounding conductor as far from the power cable as possible.

III. FANUC AC SERVO MOTOR α M series

1 GENERAL

The FANUC AC servo motor α M series is suitable for application to the feed axes of small machine tools. It has the following features:

Excellent acceleration characteristics

A high maximum output torque and intermediate rotor inertia result in excellent acceleration characteristics.

Compact

The use of the latest neodymium ferrite magnet further reduces the size and weight of the servo motors. This produces a servo motor that is sufficiently compact to allow its use in small machine tools.

Excellent waterproofing

The use of waterproof connectors and FANUC's unique stator seal provide excellent waterproofing, ensuring that no liquid, such as coolant, can enter the motor.

Extended continuous-operation

The use of the latest servo software minimizes the heat generated by high-speed rotation, allowing continuous operation over a wide range.

Smooth rotation

Further improvements have been made to the unique magnetic pole shape to minimize torque ripple. The result is extremely smooth rotation.

Controllability

The use of the latest servo software maintains controllability even when a disturbance occurs.

High-performance detector

High-resolution pulse coder α A1000, α A64, α I64 is used in the standard configuration, enabling precise positioning.

Powerful brake

A powerful brake with an increased holding torque is available as an option. The brake uses an asbestos-free design.

The types and specifications of α M series servo motors are described as follows.

The α M series includes the following models:

- Models α M2 and α M2.5 (excluding shaft type models) that are compatible with the installation dimensions of the α series models α 1 and 2.
- Models α M3, α M6, and α M9 that are compatible with the installation dimensions of the α series models α 3 and 6.
- Models α M22 and α M30 that are compatible with the installation dimensions of the α series models α 12, 22, and 30.

2 TYPES OF MOTORS AND DESIGNATION

Models

αM2/3000, αM2.5/3000

A06B-03□□-B☆○○

□□

76 : Model αM2/3000

77 : Model αM2.5/3000

☆

0 : Taper shaft (standard)

1 : Taper shaft with the brake (2Nm)

5 : Straight shaft

6 : Straight shaft with the brake (2Nm)

○○

75 : Pulse coder αA64

77 : Pulse coder αI64

88 : Pulse coder αA1000

The standard shafts used for αM2/3000 and αM2.5/3000 are taper shafts. Use a taper shaft as far as circumstances, such as the delivery time and maintenance, permit.

Models

αM6/3000, αM9/3000

A06B-01□□-B☆○○

□□

62 : Model αM6/3000

63 : Model αM9/3000

☆

0 : Taper shaft (standard)

1 : Taper shaft with the brake (8Nm)

5 : Straight shaft

6 : Straight shaft with the brake (8Nm)

○○

75 : Pulse coder αA64

77 : Pulse coder αI64

88 : Pulse coder αA1000

The standard shafts used for αM series are taper shafts. Use a taper shaft as far as circumstances, such as the delivery time and maintenance, permit.

Models **α M22/3000, α M30/3000****A06B-01**□□-B☆○○

□□

65 : Model α M22/3000**66** : Model α M30/3000

☆

0 : Taper shaft (standard)**1** : Taper shaft with the brake (35Nm)**5** : Straight shaft**6** : Straight shaft with the brake (35Nm)

○○

75 : Pulse coder α A64**77** : Pulse coder α I64**88** : Pulse coder α A1000

The standard shafts used for α M22/3000 and α M30/3000 are straight shafts. Use a taper shaft as far as circumstances, such as the delivery time and maintenance, permit.

Models **α M40/3000 and
 α M40/3000 with FAN****A06B-01**□□-B☆○○

□□

69 : Model α M40/3000**70** : Model α M40/3000 with fan

☆

0 : Straight shaft (standard)**1** : Straight shaft with the brake (35Nm)

○○

75 : With the pulse coder α A64**77** : With the pulse coder α I64**88** : With the pulse coder α A1000

For these models, a tapered shaft is not available.

3

SPECIFICATIONS AND CHARACTERISTICS



3.1 TYPES OF MOTORS AND SPECIFICATIONS

| Item | Unit | α M2/3000 | α M2.5/3000 | α M6/3000 |
|-----------------------|-----------------------|------------------|--------------------|------------------|
| Output | kw | 0.5 | 0.5 | 1.4 |
| | HP | 0.7 | 0.7 | 1.9 |
| Rated torque at stall | Nm | 2 | 2.5 | 6.0 |
| | kgf·cm | 20 | 26 | 61 |
| Rating rotation speed | min ⁻¹ | 3000 | 3000 | 3000 |
| Rotor inertia | kg·m ² | 0.00026 | 0.00051 | 0.0013 |
| | kgf·cm·s ² | 0.0027 | 0.0052 | 0.014 |
| Mass | kg | 2.8 | 4.3 | 8 |

The above values are under the condition at 20°C.

| Item | Unit | α M9/3000 | α M22/3000 | α M30/3000 | α M40/3000 | α M40/3000 with fan |
|-----------------------|-----------------------|------------------|-------------------|-------------------------------|-------------------|-------------------------------|
| Output | kw | 1.8 | 3.8 | 3.8 | 3.0 | 10 |
| | HP | 2.4 | 5.1 | 5.1 | 4.1 | 14 |
| Rated torque at stall | Nm | 9.0 | 20 | 30 | 40 | 70 |
| | kgf·cm | 92 | 204 | 306 | 408 | 714 |
| Rating rotation speed | min ⁻¹ | 3000 | 3000 | 2000 (S1) 3000 (S3-60%) | 1000 | 2000 |
| Rotor inertia | kg·m ² | 0.0025 | 0.0058 | 0.011 | 0.012 | 0.012 |
| | kgf·cm·s ² | 0.026 | 0.059 | 0.11 | 0.12 | 0.12 |
| Mass | kg | 12 | 18 | 30 | 41 | 43 |

The above values are under the condition at 20°C.

3.2 CHARACTERISTIC CURVE AND DATA SHEET

Speed-torque characteristics

The intermittent operation zone is determined by the input voltage applied to the drive amplifier. The curve shown is the value for the rated input voltage (200V).

“Intermittent operating zone (S3)” in the speed-torque characteristics refers to the intermittent cycle operating zone in the IEC34-1 standard. In this zone, ON operation of six minutes and OFF operation of four minutes in a 10-minute cycle is possible.

On models α M40/3000 and α M40/3000 with fan “Intermittent operating (S3-25%)” in the “Speed-torque characteristics is permitting operating zone in IEC34-1, and it enables to operate 2.5min ON and 7.5min OFF in 10min cycle time.

Equally, (S3-60%)” in the “Speed-torque characteristics enables to operate 6min ON and 4min OFF in 10min cycle time.

On models α M2 to M9, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item.

Overload duty characteristic

The overload duty characteristic curves are determined based on the temperature restriction for the single motor unit (the temperature is restricted by means of a thermal trip built into the motor). The curves are determined by assuming that the temperature increases gradually under certain overload conditions. Therefore, the curves do not apply to the rapid temperature rise which occurs, for example, when the motor shaft is locked. (An overcurrent flows in the motor windings until the thermal trip operates. The temperature rises momentarily.)

To detect such an abrupt temperature rise, the FANUC digital servo system provides a software thermal function that uses servo software to observe the current. During operation that is characterized by frequent acceleration/deceleration cycles, control is imposed by the software thermal function.

Driving units (such as amplifiers) and built-in detectors contain their own overheating protection devices. Therefore, note that control may be imposed according to how the equipment is being used.

Data sheet

The parameters given in the data sheet are representative values for an ambient temperature of 20°C. They are subject to an error of $\pm 10\%$.

The indicated logical values are threshold values for the single motor unit (when the motor is not restricted by the control system).


The maximum torque that can be produced during acceleration or deceleration in actual use is calculated as the approximate product of the motor torque constant and the current limit value of the amplifier.

This value is for reference only. The actual value will vary depending on changes in the power supply, as well as variations in motor parameters and amplifier limit values.

In some models, if the maximum current flows in the motor, the actual maximum torque is affected by, for example, magnetic saturation. As a result, the actual maximum torque will be lower than the calculated value. The intermittent operation area (maximum torque value) indicated in the speed to torque characteristics is the effective value, determined according to the combination with the amplifier.

Model αM2/3000

Specification : A06B-0376-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|---------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 2.0 | | Nm |
| | | 20 | | kgfcm |
| Rotor inertia | Jm | 0.00027 | | kgm ² |
| | | 0.0028 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 3.0 | | A (rms) |
| Torque constant (*) | Kt | 0.67 | | Nm/A (rms) |
| | | 6.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 23 | | V (rms)/1000min ⁻¹ |
| | | 0.22 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 1.73 | | Ω |
| Mechanical time constant (*) | tm | 0.003 | | s |
| Thermal time constant | tt | 15 | | min |
| Static friction | Tf | 0.15 | | Nm |
| | | 1.5 | | kgfcm |
| Mass | | 2.8 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model αM2, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Model α M2.5/3000

Specification : A06B-0377-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|---------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 2.5 | | Nm |
| | | 26 | | kgfcm |
| Rotor inertia | Jm | 0.00052 | | kgm ² |
| | | 0.0053 | | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 3.7 | | A (rms) |
| Torque constant (*) | Kt | 0.67 | | Nm/A (rms) |
| | | 6.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 23 | | V (rms)/1000min ⁻¹ |
| | | 0.22 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.59 | | Ω |
| Mechanical time constant (*) | tm | 0.002 | | s |
| Thermal time constant | tt | 20 | | min |
| Static friction | Tf | 0.2 | | Nm |
| | | 2 | | kgfcm |
| Mass | | 4.3 | | kg |


(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model α M2.5, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Model αM6/3000

Specification : A06B-0162-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 6.0 | | Nm |
| | | 61 | | kgfcm |
| Rotor inertia | Jm | 0.0013 | | kgm ² |
| | | 0.014 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 8.0 | | A (rms) |
| Torque constant (*) | Kt | 0.75 | | Nm/A (rms) |
| | | 7.6 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 26 | | V (rms)/1000min ⁻¹ |
| | | 0.25 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.463 | | Ω |
| Mechanical time constant (*) | tm | 0.003 | | s |
| Thermal time constant | tt | 45 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Mass | | 8 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α M9/3000

Specification : A06B-0163-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|------|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 9.0 | | Nm |
| | | 92 | | kgfcm |
| Rotor inertia | Jm | 0.0025 | | kgm ² |
| | | 0.026 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 10.4 | | A (rms) |
| Torque constant (*) | Kt | 0.86 | | Nm/A (rms) |
| | | 8.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 30 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.29 | |
| Armature resistance (1-phase) (*) | Ra | 0.181 | | Ω |
| Mechanical time constant (*) | tm | 0.002 | | s |
| Thermal time constant | tt | 50 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Mass | | 12 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model αM22/3000

Specification : A06B-0165-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|------|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 20 | | Nm |
| | | 204 | | kgfcm |
| Rotor inertia | Jm | 0.0058 | | kgm ² |
| | | 0.059 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 26.5 | | A (rms) |
| Torque constant (*) | Kt | 0.75 | | Nm/A (rms) |
| | | 7.7 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 26 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.25 | |
| Armature resistance (1-phase) (*) | Ra | 0.07 | | Ω |
| Mechanical time constant (*) | tm | 0.002 | | s |
| Thermal time constant | tt | 60 | | min |
| Static friction | Tf | 0.8 | | Nm |
| | | 8 | | kgfcm |
| Mass | | 18 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α M30/3000

Specification : A06B-0166-B□□□



Data sheet

| Parameter | Symbol | Value | Unit |
|-------------------------------------|--------|----------------------------|--|
| Rating rotation speed | Nmax | 2000 (S1) 3000 (S3-60%) | min ⁻¹ |
| Rated torque at stall (*) | Ts | 30 306 | Nm kgfcm |
| Rotor inertia | Jm | 0.011 0.11 | kgm ² kgfcm ² |
| Continuous RMS current at stall (*) | Is | 27.9 | A (rms) |
| Torque constant (*) | Kt | 1.08 11.0 | Nm/A (rms) kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 38 | V (rms)/1000min ⁻¹ |
| | Kv | 0.36 | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.05 | Ω |
| Mechanical time constant (*) | tm | 0.001 | s |
| Thermal time constant | tt | 65 | min |
| Static friction | Tf | 1.2 12 | Nm kgfcm |
| Mass | | 30 | kg |


(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

The 2000 to 3000 rpm range of this servo motor is the intermittent operation range, and is used mainly for positioning. In the intermittent operation range (S3 to 60%), ON operation of six minutes and OFF operation of four minutes in a 10-minute cycle is possible.

Model αM40/3000

Specification : A06B-0169-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|------|-------------------------------|
| Rating rotation speed | Nmax | 1000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 40 | | Nm |
| | | 408 | | kgfcm |
| Rotor inertia | Jm | 0.012 | | kgm ² |
| | | 0.12 | | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 32.3 | | A (rms) |
| Torque constant (*) | Kt | 1.24 | | Nm/A (rms) |
| | | 12.6 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 43 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.41 | |
| Armature resistance (1-phase) (*) | Ra | 0.05 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 70 | | min |
| Static friction | Tf | 1.8 | | Nm |
| | | 18 | | kgfcm |
| Weight | | 41 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.)

S3 to 25% intermittent operating zone shows 2.5 min continuous operating zone in 10 min cycle.

Model αM40/3000FAN

Specification : A06B-0170-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|------|-------------------------------|
| Rating rotation speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 70 | | Nm |
| | | 714 | | kgfcm |
| Rotor inertia | Jm | 0.012 | | kgm ² |
| | | 0.12 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 56.5 | | A (rms) |
| Torque constant (*) | Kt | 1.24 | | Nm/A (rms) |
| | | 12.6 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 43 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.41 | |
| Armature resistance (1-phase) (*) | Ra | 0.05 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 30 | | min |
| Static friction | Tf | 1.8 | | Nm |
| | | 18 | | kgfcm |
| Weight | | 43 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.)

S3 to 60% intermitting operating zone shows 6 min continuous operating zone in 10 min cycle.


Speed-torque characteristics (HRV control)

On the following models, the intermittent operating zone can be extended by using HRV control.

- α M2/3000




- α M2.5/3000




NOTE

HRV control sometimes cannot be used depending on the CNC system. Using HRV control increases the intermittent operating zone at high motor operating speeds. The continuous operating zone, however, is the same as when conventional control methods are used.

- α M6/3000



- α M9/3000

**NOTE**

HRV control sometimes cannot be used depending on the CNC system. Using HRV control increases the intermittent operating zone at high motor operating speeds. The continuous operating zone, however, is the same as when conventional control methods are used.

3.3 OUTLINE DRAWINGS

| Model | Fig. No. |
|---|--------------|
| Models α M2/3000 and α M2.5/3000 (standard) | Fig. 3.3 (a) |
| Models α M2/3000 and α M2.5/3000 (with the brake) | Fig. 3.3 (b) |
| Model α M2/3000 (shaft option) | Fig. 3.3 (c) |
| Model α M2.5/3000 (shaft option) | Fig. 3.3 (d) |
| Models α M6/3000 and α M9/3000 (standard) | Fig. 3.3 (e) |
| Models α M6/3000 and α M9/3000 (with the brake) | Fig. 3.3 (f) |
| Model α M6/3000 (shaft option) | Fig. 3.3 (g) |
| Model α M9/3000 (shaft option) | Fig. 3.3 (h) |
| Models α M22/3000 to α M40/3000 (standard) | Fig. 3.3 (i) |
| Models α M22/3000 to α M40/3000 (with the brake) | Fig. 3.3 (j) |
| Models α M22/3000 to α M40/3000 (shaft option) | Fig. 3.3 (k) |
| Model α M40/3000 (with fan) | Fig. 3.3 (l) |
| Model α M40/3000 (with fan) (with the brake) | Fig. 3.3 (m) |

Fig. 3.3 (a) Models αM2/3000 and αM2.5/3000 (standard)




Fig. 3.3 (b) Models αM2/3000 and αM2.5/3000 (with the brake)




Fig. 3.3 (c) Model αM2/3000 (shaft option)




Fig. 3.3 (e) Models αM6/3000 and αM9/3000 (standard)




Fig. 3.3 (f) Models αM6/3000 and αM9/3000 (with the brake)




Fig. 3.3 (g) Models αM6/3000 (shaft option)




Fig. 3.3 (h) Model αM9/3000 (shaft option)




Fig. 3.3 (i) Models αM22/3000 to αM40/3000 (standard)




Fig. 3.3 (j) Models αM22/3000 to αM40/3000 (with the brake)





Fig. 3.3 (I) Model αM40/3000 (with fan)



- Notes)
- Shaft diameter runout Max 0.05mm
 - Rabbit dia. eccentricity Max 0.07mm
 - Mounting face runout Max 0.10mm
 - Rated load 4410N(450kgf)
 - Taps for eyebolt : M8 depth 15⁺¹
 - Eyebolts are not attached
 - No weight more than 100kg
 - No acceleration more than 1G
 - Direction of the air flow is downward only

Fan Motor Specification


| | |
|---------------|--|
| Input Voltage | 200 V |
| Frequency | 50 Hz 60 Hz |
| Input | 40 W 40 W |
| Speed | 2700 min ⁻¹ 2900 min ⁻¹ |

This chart is spec. for one fan motor.
Prepare a protect fuse in power supply.

Fan Connector

| Pin | Note |
|-----|---------------------|
| A | Single phase 200VAC |
| B | |
| C | Earth |


Fig. 3.3 (m) Models αM40/3000 (with fan) (with the brake)



3.4 CONNECTION OF POWER LINE


Models

αM2/3000, αM2.5/3000




Models

αM6/3000, αM9/3000



Models

αM22/3000, αM30/3000,
αM40/3000,
αM40/3000 (with fan)



IV. FANUC AC SERVO MOTOR α L series

1 GENERAL

The FANUC AC servo motor α L series is suitable for high-speed positioning. It has the following features:

Excellent acceleration characteristics

The latest neodymium ferrite magnet is employed, and the rotor inertia is minimized. The result is a motor that offers excellent acceleration.

Excellent waterproofing

The use of waterproof connectors and FANUC's unique stator seal provide excellent waterproofing, ensuring that no liquid, such as coolant, can enter the motor.

Extended continuous-operation

The use of the latest servo software minimizes the heat generated by high-speed rotation, allowing continuous operation over a wide range.

Smooth rotation

Further improvements have been made to the unique magnetic pole shape to minimize torque ripple. The result is extremely smooth rotation.

Controllability

The use of the latest servo software maintains controllability even when a disturbance occurs.

High-performance detector

High-resolution pulse coder α A1000, α A64, α I64 is used in the standard configuration, enabling precise positioning.

Powerful brake

A powerful brake with an increased holding torque is available as an option. The brake uses an asbestos-free design.

The L series models α L6, and α L9, all of which are compatible with series models α 3 and α 6 in their installation size, and models α L25 and α L50, which are compatible with series models α 12 and α 22 in their installation size. All these α L series models are compatible with the conventional FANUC AC servo motor α L series in their installation size.

2

TYPES OF MOTORS AND DESIGNATION

The types and specifications of α L series servo motors are described as follows.

Models

α L3/3000, α L6/3000, and
 α L9/3000

A06B-05 $\square\square$ -**B** \star $\circ\circ$

$\square\square$

62 : Model α L6/3000

64 : Model α L9/3000

\star

0 : Taper shaft (standard)

1 : Taper shaft with the brake (8Nm)

$\circ\circ$

75 : Pulse coder α A64

77 : Pulse coder α I64

88 : Pulse coder α A1000

Models

α L25/3000 and
 α L50/2000

A06B-05 $\square\square$ -**B** \star $\circ\circ$

$\square\square$

71 : Model α L25/3000

72 : Model α L50/2000

\star

0 : Taper shaft (standard)

2 : Taper shaft with the brake (18Nm)

3 : Taper shaft with the brake (40Nm)

$\circ\circ$

75 : Pulse coder α A64

77 : Pulse coder α I64

88 : Pulse coder α A1000

3

SPECIFICATIONS AND CHARACTERISTICS



3.1 TYPES OF MOTORS AND SPECIFICATIONS

| Item | Unit | α L6/3000 | α L9/3000 | α L25/3000 | α L50/2000 |
|----------------------------|-----------------------|------------------|------------------|-------------------|-------------------|
| Output | kw | 1.4 | 2.0 | 3.5 | 6.0 |
| | HP | 1.8 | 2.7 | 4.7 | 8.0 |
| Rated torque at stall | Nm | 6.0 | 9.0 | 25 | 50 |
| | kgf·cm | 61 | 92 | 255 | 510 |
| Rating rota- tion speed | min ⁻¹ | 3000 | 3000 | 3000 | 2000 |
| Rotor inertia | kg·m ² | 0.00049 | 0.00098 | 0.0054 | 0.0098 |
| | kgf·cm·s ² | 0.0050 | 0.010 | 0.055 | 0.10 |
| Mass | kg | 11 | 17 | 25 | 42 |

The above values are under the condition at 20°C.

3.2 CHARACTERISTIC CURVE AND DATA SHEET

Speed-torque characteristics

The intermittent operation zone is determined by the input voltage applied to the drive amplifier. The curve shown is the value for the rated input voltage (200V).

On models α L6 to α L9, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Overload duty characteristic

The overload duty characteristic curves are determined based on the temperature restriction for the single motor unit (the temperature is restricted by means of a thermal trip built into the motor). The curves are determined by assuming that the temperature increases gradually under certain overload conditions. Therefore, the curves do not apply to the rapid temperature rise which occurs, for example, when the motor shaft is locked. (An overcurrent flows in the motor windings until the thermal trip operates. The temperature rises momentarily.)

To detect such an abrupt temperature rise, the FANUC digital servo system provides a software thermal function that uses servo software to observe the current. During operation that is characterized by frequent acceleration/deceleration cycles, control is imposed by the software thermal function.

Driving units (such as amplifiers) and built-in detectors contain their own overheating protection devices. Therefore, note that control may be imposed according to how the equipment is being used.

Data sheet

The parameters given in the data sheet are representative values for an ambient temperature of 20°C. They are subject to an error of $\pm 10\%$.

The indicated logical values are threshold values for the single motor unit (when the motor is not restricted by the control system).


The maximum torque that can be produced during acceleration or deceleration in actual use is calculated as the approximate product of the motor torque constant and the current limit value of the amplifier.

This value is for reference only. The actual value will vary depending on changes in the power supply, as well as variations in motor parameters and amplifier limit values.

In some models, if the maximum current flows in the motor, the actual maximum torque is affected by, for example, magnetic saturation. As a result, the actual maximum torque will be lower than the calculated value. The intermittent operation area (maximum torque value) indicated in the speed to torque characteristics is the effective value, determined according to the combination with the amplifier.

Model αL6/3000

Specification : A06B-0562-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|---------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 6.0 | | Nm |
| | | 61 | | kgfcm |
| Rotor inertia | Jm | 0.00049 | | kgm ² |
| | | 0.0050 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 11.4 | | A (rms) |
| Torque constant (*) | Kt | 0.52 | | Nm/A (rms) |
| | | 5.3 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 18 | | V (rms)/1000min ⁻¹ |
| | | 0.17 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.275 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 25 | | min |
| Static friction | Tf | 0.5 | | Nm |
| | | 5 | | kgfcm |
| Mass | | 11 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model αL6, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Model αL9/3000

Specification : A06B-0564-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|---------|------|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 9.0 | | Nm |
| | | 92 | | kgfcm |
| Rotor inertia | Jm | 0.00098 | | kgm ² |
| | | 0.010 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 16.9 | | A (rms) |
| Torque constant (*) | Kt | 0.52 | | Nm/A (rms) |
| | | 5.3 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 18 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.17 | |
| Armature resistance (1-phase) (*) | Ra | 0.110 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 45 | | min |
| Static friction | Tf | 0.9 | | Nm |
| | | 9 | | kgfcm |
| Mass | | 17 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model αL9, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Model α L25/3000

Specification : A06B-0571-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|------|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 25 | | Nm |
| | | 255 | | kgfcm |
| Rotor inertia | Jm | 0.0054 | | kgm ² |
| | | 0.055 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 37 | | A (rms) |
| Torque constant (*) | Kt | 0.66 | | Nm/A (rms) |
| | | 6.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 23 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.22 | |
| Armature resistance (1-phase) (*) | Ra | 0.049 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 45 | | min |
| Static friction | Tf | 1.2 | | Nm |
| | | 12 | | kgfcm |
| Mass | | 25 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α L50/2000

Specification : A06B-0572-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|------|-------------------------------|
| Rating rotation speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 50 | | Nm |
| | | 510 | | kgfcm |
| Rotor inertia | Jm | 0.0098 | | kgm ² |
| | | 0.10 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 51 | | A (rms) |
| Torque constant (*) | Kt | 0.96 | | Nm/A (rms) |
| | | 9.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 33 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.32 | |
| Armature resistance (1-phase) (*) | Ra | 0.038 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 70 | | min |
| Static friction | Tf | 1.8 | | Nm |
| | | 18 | | kgfcm |
| Mass | | 42 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.


(Remarks)
Speed-torque characteristics (HRV control)

On the following models, the intermittent operating zone can be extended by using HRV control.

• α L6/3000



• α L9/3000



NOTE

HRV control sometimes cannot be used depending on the CNC system. Using HRV control increases the intermittent operating zone at high motor operating speeds. The continuous operating zone, however, is the same as when conventional control methods are used.

3.3 OUTLINE DRAWINGS

| Model | Fig. No. |
|---|--------------|
| Models α L6/3000 and α L9/3000 | Fig. 3.3 (a) |
| Models α L6/3000 and α L9/3000 (with the brake) | Fig. 3.3 (b) |
| Models α L25/3000 and α L50/2000 | Fig. 3.3 (c) |
| Models α L25/3000 and α L50/2000 (with the brake) | Fig. 3.3 (d) |

Fig. 3.3 (a) Models αL6/3000 and αL9/3000




Fig. 3.3 (b) Models αL6/3000 and αL9/3000 (with the brake)






Fig. 3.3 (c) Models αL25/3000 and αL50/2000




3.4 CONNECTION OF POWER LINE

Models α L6/3000 and α L9/3000



Models α L25/3000 and α L50/2000



V. FANUC AC SERVO MOTOR α C series

1

GENERAL

The FANUC AC servo motor α C series is suitable for application to the feed axes of machine tools. These motors have the following features:

High cost-effectiveness

High cost-effectiveness has been achieved. Although a low-power amplifier is used, high acceleration is offered.

Compact

The use of the latest ferrite magnet, combined with an optimized mechanical design, reduces both the overall length and weight. The result is compact, lightweight servo motors.

Excellent waterproofing

The use of waterproof connectors and FANUC's unique stator seal provide excellent waterproofing, ensuring that no liquid, such as coolant, can enter the motor.

Smooth rotation

Further improvements have been made to the unique magnetic pole shape to minimize torque ripple. The result is extremely smooth rotation.

Controllability

The use of the latest servo software maintains controllability even when a disturbance occurs.

High-performance detector

High-resolution pulse coder α A1000, α A64, α I64 is used in the standard configuration, enabling precise positioning.

Powerful brake

A powerful brake with an increased holding torque is available as an option. The brake uses an asbestos-free design.

The α C series includes models α C3 and α C6, both of which are compatible with α series models α 3 and α 6 in their installation size, and models α C12 and α C22, which are compatible with α series models α 12 and α 22 in their installation size.

2 TYPES OF MOTORS AND DESIGNATION

The types and specifications of αC series servo motors are described as follows.

Models αC3/2000 and αC6/2000

A06B-01 □□ -B ☆ ○○

□□

21 : Model αC3/2000

26 : Model αC6/2000

☆

0 : Taper shaft (standard)

1 : Taper shaft with the brake (8Nm)

5 : Straight shaft

6 : Straight shaft with the brake (8Nm)

○○

75 : Pulse coder αA64

77 : Pulse coder αI64

The standard shafts used for models αC3/2000 and αC6/2000 are taper shafts. Use a taper shaft as far as circumstances, such as the delivery time and maintenance, permit.

Models αC12/2000 and αC22/1500

A06B-01 □□ -B ☆ ○○

□□

41 : Model αC12/2000

45 : Model αC22/1500

☆

0 : Straight shaft (standard)

1 : Straight shaft with the brake (35Nm)

5 : Taper shaft

6 : Taper shaft with the brake (35Nm)

○○

75 : Pulse coder αA64

77 : Pulse coder αI64

A straight shaft is fitted as the standard shaft for models αC12/2000 and αC22/1500. When early delivery and case-of-maintenance are important, a straight shaft should be used.

NOTE

For the αC series, pulse coder αA1000 cannot be used.

3

SPECIFICATIONS AND CHARACTERISTICS



3.1 TYPES OF MOTORS AND SPECIFICATIONS

| Item | Unit | α C3/2000 | α C6/2000 | α C12/2000 | α C22/1500 |
|----------------------------|-----------------------|------------------|------------------|-------------------|-------------------|
| Output | kw | 0.3 | 0.6 | 1.0 | 1.5 |
| | HP | 0.4 | 0.8 | 1.4 | 2.1 |
| Rated torque at stall | Nm | 3.0 | 6.0 | 12 | 22 |
| | kgf·cm | 31 | 61 | 122 | 224 |
| Rating rota- tion speed | min ⁻¹ | 2000 | 2000 | 2000 | 1500 |
| Rotor inertia | kg·m ² | 0.0014 | 0.0026 | 0.0062 | 0.012 |
| | kgf·cm·s ² | 0.014 | 0.027 | 0.064 | 0.12 |
| Mass | kg | 8 | 13 | 18 | 29 |

The above values are under the condition at 20°C.

3.2 CHARACTERISTIC CURVE AND DATA SHEET

Speed-torque characteristics

The intermittent operation zone is determined by the input voltage applied to the drive amplifier. The curve shown is the value for the rated input voltage (200V).

Overload duty characteristic

The overload duty characteristic curves are determined based on the temperature restriction for the single motor unit (the temperature is restricted by means of a thermal trip built into the motor). The curves are determined by assuming that the temperature increases gradually under certain overload conditions. Therefore, the curves do not apply to the rapid temperature rise which occurs, for example, when the motor shaft is locked. (An overcurrent flows in the motor windings until the thermal trip operates. The temperature rises momentarily.)

To detect such an abrupt temperature rise, the FANUC digital servo system provides a software thermal function that uses servo software to observe the current. During operation that is characterized by frequent acceleration/deceleration cycles, control is imposed by the software thermal function.

Driving units (such as amplifiers) and built-in detectors contain their own overheating protection devices. Therefore, note that control may be imposed according to how the equipment is being used.

Data sheet

The parameters given in the data sheet are representative values for an ambient temperature of 20°C. They are subject to an error of +10%.

The indicated logical values are threshold values for the single motor unit (when the motor is not restricted by the control system).

The maximum torque that can be produced during acceleration or deceleration in actual use is calculated as the approximate product of the motor torque constant and the current limit value of the amplifier.

Example : α C3/2000


- Motor torque constant = 1.06 (Nm/Arms)
- Amplifier limit value = 20 A_{peak}
- Maximum torque value
= $20 \times 0.707 \times 1.06$
(Converted to an effective value)
= 14.9 Nm

This value is for reference only. The actual value will vary depending on changes in the power supply, as well as variations in motor parameters and amplifier limit values.

In some models, if the maximum current flows in the motor, the actual maximum torque is affected by, for example, magnetic saturation. As a result, the actual maximum torque will be lower than the calculated value. The intermittent operation area (maximum torque value) indicated in the speed to torque characteristics is the effective value, determined according to the combination with the amplifier.

Model α C3/2000

Specification : A06B-0121-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 3.0 | | Nm |
| | | 31 | | kgfcm |
| Rotor inertia | Jm | 0.0014 | | kgm ² |
| | | 0.014 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 2.8 | | A (rms) |
| Torque constant (*) | Kt | 1.06 | | Nm/A (rms) |
| | | 10.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 37 | | V (rms)/1000min ⁻¹ |
| | | 0.35 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 1.85 | | Ω |
| Mechanical time constant (*) | tm | 0.006 | | s |
| Thermal time constant | tt | 45 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Mass | | 8 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α C6/2000

Specification : A06B-0126-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 6.0 | | Nm |
| | | 61 | | kgfcm |
| Rotor inertia | Jm | 0.0026 | | kgm ² |
| | | 0.027 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 3.6 | | A (rms) |
| Torque constant (*) | Kt | 1.68 | | Nm/A (rms) |
| | | 17.1 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 59 | | V (rms)/1000min ⁻¹ |
| | | 0.56 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 1.52 | | Ω |
| Mechanical time constant (*) | tm | 0.004 | | s |
| Thermal time constant | tt | 50 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Mass | | 13 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α C12/2000

Specification : A06B-0141-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 12 | | Nm |
| | | 122 | | kgfcm |
| Rotor inertia | Jm | 0.0062 | | kgm ² |
| | | 0.064 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 5.9 | | A (rms) |
| Torque constant (*) | Kt | 2.04 | | Nm/A (rms) |
| | | 20.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 71 | | V (rms)/1000min ⁻¹ |
| | | 0.68 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 1.10 | | Ω |
| Mechanical time constant (*) | tm | 0.005 | | s |
| Thermal time constant | tt | 60 | | min |
| Static friction | Tf | 0.8 | | Nm |
| | | 8 | | kgfcm |
| Mass | | 18 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model αC22/1500

Specification : A06B-0145-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|------|-------------------------------|
| Rating rotation speed | Nmax | 1500 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 22 | | Nm |
| | | 224 | | kgfcm |
| Rotor inertia | Jm | 0.012 | | kgm ² |
| | | 0.12 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 12.5 | | A (rms) |
| Torque constant (*) | Kt | 1.76 | | Nm/A (rms) |
| | | 18.0 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 62 | | V (rms)/1000min ⁻¹ |
| | | Kv | 0.59 | |
| Armature resistance (1-phase) (*) | Ra | 0.32 | | Ω |
| Mechanical time constant (*) | tm | 0.003 | | s |
| Thermal time constant | tt | 65 | | min |
| Static friction | Tf | 1.2 | | Nm |
| | | 12 | | kgfcm |
| Mass | | 29 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

3.3 OUTLINE DRAWINGS

| Model | Fig. No. |
|---|-------------|
| Models α C3/2000 and α C6/2000 | Fig. 3.3(a) |
| Models α C3/2000 and α C6/2000 (with the brake) | Fig. 3.3(b) |
| Models α C3/2000 and α C6/2000 (shaft option) | Fig. 3.3(c) |
| Models α C12/2000 and α C22/1500 | Fig. 3.3(d) |
| Models α C12/2000 and α C22/1500 (with the brake) | Fig. 3.3(e) |
| Models α C12/2000 and α C22/1500 (shaft option) | Fig. 3.3(f) |

Fig. 3.3 (a) Models αC3/2000 and αC6/2000




Fig. 3.3 (c) Models αC3/2000 and αC6/2000 (shaft option)





Fig. 3.3 (d) Models αC12/2000 and αC22/1500




- Notes)
- Shaft diameter runout Max 0.05mm
 - Rabbit diameter eccentricity Max 0.07mm
 - Mounting face runout Max 0.10mm
 - Rated load 4410N(450kgf)

Taps for eyebolt : M8 depth 15+1
 Eyebolts are not attached

| MODEL | A | B | C |
|-------|-----|-----|----|
| αC12 | 240 | 166 | 49 |
| αC22 | 314 | 240 | |


Fig. 3.3 (e) Models αC12/2000 and αC22/1500 (with the brake)



3.4 CONNECTION OF POWER LINE


Models

α C3/2000 and α C6/2000



Models

α C12/2000 and
 α C22/1500



CAUTION

- 1 The motors should be installed with their connector facing downward as long as possible. When it is impossible to install a motor in this position, allow slack in the cable to keep liquids such as a dielectric fluid from going along the cable into the cable or motor. If there is a possibility that the motors and connectors get wet, provide a cover to protect them.
- 2 If a motor is not connected to the earth ground through the machine (frame), connect the motor grounding point and the amplifier grounding point to absorb noise using a 1.25 mm² or larger conductor other than the grounding conductor in the power cable. Keep the grounding conductor as far from the power cable as possible.

VI. FANUC AC SERVO MOTOR

α (HV) series

1 GENERAL

The FANUC AC servo motor α (HV) series is suitable for application to the feed axes of machine tools. These motors have the following features:

Direct connection to a 400V power source

A 400V power source can be connected directly without using a transformer.

Compact

The use of the latest ferrite magnet, combined with an optimized mechanical design, reduces both the overall length and weight. The result is compact, lightweight servo motors.

Excellent waterproofing

The use of waterproof connectors and FANUC's unique stator seal provide excellent waterproofing, ensuring that no liquid, such as coolant, can enter the motor.

Smooth rotation

Further improvements have been made to the unique magnetic pole shape to minimize torque ripple. The result is extremely smooth rotation.

Controllability

The use of the latest servo software maintains controllability even when a disturbance occurs.

Built-in high-performance detector

A high-resolution pulse coder α A1000, α A64, α I64 is provided as standard, assuring accurate positioning.

Powerful brake

A powerful brake with an increased holding torque is available as an option. The brake uses an asbestos-free design.

The α (HV) series includes models α 3HV and α 6HV, both of which are compatible with α series models α 3 and α 6 in their installation size, and models α 12HV, α 22HV, α 30HV, and α 40HV, which are compatible with series models α 12, α 22, α 30 and α 40 in their installation size.

2 TYPES OF MOTORS AND DESIGNATION

The types and specifications of α (HV) series servo motors are described as follows.

Models α 3/3000HV and α 6/3000HV

A06B-01 □□ -B ☆ ○○

□□

71 : Model α 3/3000HV

72 : Model α 6/3000HV

☆

0 : Taper shaft (standard)

2 : Taper shaft with the brake (8Nm/24VDC)

5 : Straight shaft

7 : Straight shaft with the brake (8Nm/24VDC)

○○

75 : Pulse coder α A64

77 : Pulse coder α I64

88 : Pulse coder α A1000

The standard shafts used for models α 3/3000HV and α 6/3000HV are taper shafts. Use a taper shaft as far as circumstances, such as the delivery time and maintenance, permit.

Models α 12/3000HV, α 22/3000HV and α 30/3000HV

A06B-01 □□ -B ☆ ○○

□□

76 : Model α 12/3000HV

77 : Model α 22/3000HV

78 : Model α 30/3000HV

☆

0 : Straight shaft (standard)

2 : Straight shaft with the brake (35Nm/24VDC)

5 : Taper shaft

7 : Taper shaft with the brake (35Nm/24VDC)

○○

75 : Pulse coder α A64

77 : Pulse coder α I64

88 : Pulse coder α A1000

A straight shaft is fitted as the standard shaft for models α 12/3000HV, α 22/3000HV and α 30/3000HV. When early delivery and case-of-maintenance are important, a straight shaft should be used.

Models
 α 40/2000HV**A06B-0179-B** ☆ ○ ○

☆

0 : Straight shaft (standard)**2** : Straight shaft with the brake (35Nm 24VDC)

○ ○

75 : With the pulse coder α A64**77** : With the pulse coder α I64**88** : With the pulse coder α A1000

This model, a tapered shaft is not available.

Models
 α 1000/2000HV**A06B-0131-B0** ○ ○

○ ○

75 : With the pulse coder α A64**77** : With the pulse coder α I64**88** : With the pulse coder α A1000

This model, a tapered shaft is standard, a straight shaft is not available.

This model, a brake option is not available.

3

SPECIFICATIONS AND CHARACTERISTICS



3.1 TYPES OF MOTORS AND SPECIFICATIONS

| Item | Unit | $\alpha 3/3000HV$ | $\alpha 6/3000HV$ |
|-----------------------|-----------------------|-------------------|-------------------|
| Output | kw | 0.9 | 1.4 |
| | HP | 1.3 | 1.9 |
| Rated torque at stall | Nm | 3.0 | 6.0 |
| | kgf·cm | 31 | 61 |
| Rating rotation speed | min ⁻¹ | 3000 | 3000 |
| Rotor inertia | kg·m ² | 0.0014 | 0.0026 |
| | kgf·cm·s ² | 0.014 | 0.027 |
| Mass | kg | 8 | 13 |

The above values are under the condition at 20°C.

| Item | Unit | $\alpha 12/3000HV$ | $\alpha 22/3000HV$ | $\alpha 30/3000HV$ | $\alpha 40/2000HV$ | $\alpha 1000/2000HV$ |
|-----------------------|-----------------------|--------------------|--------------------|--------------------|--------------------|----------------------|
| Output | kw | 2.8 | 4.4 | 4.8 | 5.9 | 100 |
| | HP | 3.8 | 5.9 | 6.4 | 7.9 | 136 |
| Rated torque at stall | Nm | 12 | 22 | 30 | 38 | 900 |
| | kgf·cm | 122 | 224 | 306 | 390 | 9180 |
| Rating rotation speed | min ⁻¹ | 3000 | 3000 | 3000 | 2000 | 2000 |
| Rotor inertia | kg·m ² | 0.0062 | 0.012 | 0.017 | 0.022 | 0.417 |
| | kgf·cm·s ² | 0.064 | 0.12 | 0.17 | 0.23 | 4.25 |
| Mass | kg | 18 | 29 | 41 | 52 | 470 |

The above values are under the condition at 20°C.

3.2 CHARACTERISTIC CURVE AND DATA SHEET

Speed-torque characteristics

The intermittent operation zone is determined by the input voltage applied to the drive amplifier. The curve shown is the value for the rated input voltage (400V).

On models α 3HV to α 6HV, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Overload duty characteristic

The overload duty characteristic curves are determined based on the temperature restriction for the single motor unit (the temperature is restricted by means of a thermal trip built into the motor). The curves are determined by assuming that the temperature increases gradually under certain overload conditions. Therefore, the curves do not apply to the rapid temperature rise which occurs, for example, when the motor shaft is locked. (An overcurrent flows in the motor windings until the thermal trip operates. The temperature rises momentarily.)

To detect such an abrupt temperature rise, the FANUC digital servo system provides a software thermal function that uses servo software to observe the current. During operation that is characterized by frequent acceleration/deceleration cycles, control is imposed by the software thermal function.

Driving units (such as amplifiers) and built-in detectors contain their own overheating protection devices. Therefore, note that control may be imposed according to how the equipment is being used.

Data sheet

The parameters given in the data sheet are representative values for an ambient temperature of 20°C. They are subject to an error of +10%.

The indicated logical values are threshold values for the single motor unit (when the motor is not restricted by the control system).

The maximum torque that can be produced during acceleration or deceleration in actual use is calculated as the approximate product of the motor torque constant and the current limit value of the amplifier.

Example : α 3/3000HV


- Motor torque constant = 1.06 (Nm/Arms)
- Amplifier limit value = 20 A_{peak}
- Maximum torque value
= $20 \times 0.707 \times 1.06$
(Converted to an effective value)
= 14.9 Nm

This value is for reference only. The actual value will vary depending on changes in the power supply, as well as variations in motor parameters and amplifier limit values.

In some models, if the maximum current flows in the motor, the actual maximum torque is affected by, for example, magnetic saturation. As a result, the actual maximum torque will be lower than the calculated value. The intermittent operation area (maximum torque value) indicated in the speed to torque characteristics is the effective value, determined according to the combination with the amplifier.

Model α 3/3000HV

Specification : A06B-0171-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 3.0 | | Nm |
| | | 31 | | kgfcm |
| Rotor inertia | Jm | 0.0014 | | kgm ² |
| | | 0.014 | | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 2.8 | | A (rms) |
| Torque constant (*) | Kt | 1.06 | | Nm/A (rms) |
| | | 10.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 37 | | V (rms)/1000min ⁻¹ |
| | | 0.35 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 1.85 | | Ω |
| Mechanical time constant (*) | tm | 0.006 | | s |
| Thermal time constant | tt | 45 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Mass | | 8 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model α 3HV, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Model α 6/3000HV

Specification : A06B-0172-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 6.0 | | Nm |
| | | 61 | | kgfcm |
| Rotor inertia | Jm | 0.0026 | | kgm ² |
| | | 0.027 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 3.6 | | A (rms) |
| Torque constant (*) | Kt | 1.68 | | Nm/A (rms) |
| | | 17.1 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 59 | | V (rms)/1000min ⁻¹ |
| | | 0.56 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 1.52 | | Ω |
| Mechanical time constant (*) | tm | 0.004 | | s |
| Thermal time constant | tt | 50 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Mass | | 13 | | kg |


(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model α 6HV, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Model α 12/3000HV

Specification : A06B-0176-B□□□



Data sheet


| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 12 | | Nm |
| | | 122 | | kgfcm |
| Rotor inertia | Jm | 0.0062 | | kgm ² |
| | | 0.064 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 8.8 | | A (rms) |
| Torque constant (*) | Kt | 1.36 | | Nm/A (rms) |
| | | 13.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 47 | | V (rms)/1000min ⁻¹ |
| | | 0.45 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.49 | | Ω |
| Mechanical time constant (*) | tm | 0.005 | | s |
| Thermal time constant | tt | 60 | | min |
| Static friction | Tf | 0.8 | | Nm |
| | | 8 | | kgfcm |
| Mass | | 18 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model α 22/3000HV

Specification : A06B-0177-B□□□

**Data sheet**

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 22 | | Nm |
| | | 224 | | kgfcm |
| Rotor inertia | Jm | 0.012 | | kgm ² |
| | | 0.12 | | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 12.5 | | A (rms) |
| Torque constant (*) | Kt | 1.76 | | Nm/A (rms) |
| | | 18.0 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 62 | | V (rms)/1000min ⁻¹ |
| | | 0.59 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.32 | | Ω |
| Mechanical time constant (*) | tm | 0.003 | | s |
| Thermal time constant | tt | 65 | | min |
| Static friction | Tf | 1.2 | | Nm |
| | | 12 | | kgfcm |
| Mass | | 29 | | kg |


(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

The characteristics graphs above show the characteristics of the motor when combined with the 60HV servo amplifier. (For the specification of the servo amplifier, see Section 2.1 in Chapter 1.)

Model α30/3000HV

Specification : A06B-0178-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 30 | | Nm |
| | | 306 | | kgfcm |
| Rotor inertia | Jm | 0.017 | | kgm ² |
| | | 0.17 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 12.6 | | A (rms) |
| Torque constant (*) | Kt | 2.37 | | Nm/A (rms) |
| | | 24.2 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 83 | | V (rms)/1000min ⁻¹ |
| | | 0.79 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.34 | | Ω |
| Mechanical time constant (*) | tm | 0.003 | | s |
| Thermal time constant | tt | 70 | | min |
| Static friction | Tf | 1.8 | | Nm |
| | | 18 | | kgfcm |
| Mass | | 41 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

The characteristics graphs above show the characteristics of the motor when combined with the 60HV servo amplifier. (For the specification of the servo amplifier, see Section 2.1 in Chapter 1.)

Model α 40/2000HV

Specification : A06B-0179-B□□□

**Data sheet**

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|--|-------------------------------|
| Rating speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 38 | | Nm |
| | | 390 | | kgfcm |
| Rotor inertia | Jm | 0.022 | | kgm ² |
| | | 0.23 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 19.2 | | A (rms) |
| Torque constant (*) | Kt | 1.98 | | Nm/A (rms) |
| | | 20.2 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 69 | | V (rms)/1000min ⁻¹ |
| | | 0.66 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.16 | | Ω |
| Mechanical time constant (*) | tm | 0.003 | | s |
| Thermal time constant | tt | 75 | | min |
| Static friction | Tf | 1.8 | | Nm |
| | | 18 | | kgfcm |
| Weight | | 52 | | kg |


(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.)

These values may be changed without prior notice.

Model α 1000/2000HV

Specification : A06B-0131-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|------|-------------------------------|
| Rating speed | Nmax | 2000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 900 | | Nm |
| | | 9180 | | kgfcm |
| Rotor inertia | Jm | 0.417 | | kgm ² |
| | | 4.25 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 220 | | A (rms) |
| Torque constant (*) | Kt | 4.09 | | Nm/A (rms) |
| | | 41.7 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 142.7 | | V (rms)/1000min ⁻¹ |
| | | Kv | 1.36 | |
| Armature resistance (1-phase) (*) | Ra | 0.011 | | Ω |
| Mechanical time constant (*) | tm | 0.0008 | | s |
| Thermal time constant | tt | 100 | | min |
| Static friction | Tf | 4 | | Nm |
| | | 40 | | kgfcm |
| Weight | | 470 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.)


(Remarks)
Speed-torque characteristics (HRV control)

On the following models, the intermittent operating zone can be extended by using HRV control.

• α 3/3000HV



• α 6/3000HV



CAUTION

HRV control sometimes cannot be used depending on the CNC system. Using HRV control increases the intermittent operating zone at high motor operating speeds. The continuous operating zone, however, is the same as when conventional control methods are used.

3.3 OUTLINE DRAWINGS

| Model | Fig. No. |
|---|------------------|
| Models $\alpha 3/3000$ HV and $\alpha 6/3000$ HV | Fig. 3.3 (a) |
| Models $\alpha 3/3000$ HV and $\alpha 6/3000$ HV (with the brake) | Fig. 3.3 (b) |
| Models $\alpha 3/3000$ HV and $\alpha 6/3000$ HV (shaft option) | Fig. 3.3 (c) |
| Models $\alpha 12/3000$ HV, $\alpha 22/3000$ HV, and $\alpha 30/3000$ HV | Fig. 3.3 (d) |
| Models $\alpha 12/3000$ HV, $\alpha 22/3000$ HV, and $\alpha 30/3000$ HV (with the brake) | Fig. 3.3 (e) |
| Models $\alpha 12/3000$ HV, $\alpha 22/3000$ HV, and $\alpha 30/3000$ HV (shaft option) | Fig. 3.3 (f) |
| Models $\alpha 40/2000$ HV | Fig. 3.3 (g) |
| Models $\alpha 40/2000$ HV (with the brake) | Fig. 3.3 (h) |
| Models $\alpha 1000/2000$ HV | Fig. 3.3 (i) (j) |

Fig. 3.3 (a) Models α 3/3000HV and α 6/3000HV




Fig. 3.3 (b) Models α 3/3000HV and α 6/3000HV (with the brake)




Fig. 3.3 (c) Models α3/3000HV and α6/3000HV (shaft option)




Fig. 3.3 (d) Models α12/3000HV, α22/3000HV and α30/3000HV




Fig. 3.3 (e) Models α12/3000HV, α22/3000HV and α30/3000HV (with the brake)




Fig. 3.3 (f) Models α 12/3000HV, α 22/3000HV and α 30/3000HV (shaft option)




Fig. 3.3 (g) Model α 40/2000HV






Fig. 3.3 (i) Model α 1000/2000HV




3.4 CONNECTION OF POWER LINE


Models
 α 3/3000HV and
 α 6/3000HV



Models
 α 12/3000HV, α 22/3000HV,
 α 30/3000HV, and
 α 40/3000HV



Models
 α 1000/2000HV



CAUTION

- 1 The motors should be installed with their connector facing downward as long as possible. When it is impossible to install a motor in this position, allow slack in the cable to keep liquids such as a dielectric fluid from going along the cable into the cable or motor. If there is a possibility that the motors and connectors get wet, provide a cover to protect them.
- 2 If a motor is not connected to the earth ground through the machine (frame), connect the motor grounding point and the amplifier grounding point to absorb noise using a 1.25 mm² or larger conductor other than the grounding conductor in the power cable. Keep the grounding conductor as far from the power cable as possible.

VII. FANUC AC SERVO MOTOR

α M (HV) series

1

GENERAL

The FANUC AC servo motor α M(HV) series is ideal for the feed shafts of small machine tools. The features of this servo motor are as follows:

Direct connection to a 400V power source

A 400V power source can be connected directly without using a transformer.

Excellent acceleration characteristics

A high maximum output torque and intermediate rotor inertia result in excellent acceleration characteristics.

Compact

The use of the latest ferrite magnet, combined with an optimized mechanical design, reduces both the overall length and weight. The result is compact, lightweight servo motors.

Excellent waterproofing

The use of waterproof connectors and FANUC's unique stator seal provide excellent waterproofing, ensuring that no liquid, such as coolant, can enter the motor.

Wide continuous operating zone

The latest servo software minimizes heat generation at high operating speeds, and extends the continuous operating zone.

Smooth rotation

Further improvements have been made to the unique magnetic pole shape to minimize torque ripple. The result is extremely smooth rotation.

Controllability

The use of the latest servo software maintains controllability even when a disturbance occurs.

High-performance detector

High-resolution pulse coder α A1000, α A64, α I64 is used in the standard configuration, enabling precise positioning.

Powerful brake

A powerful brake with an increased holding torque is available as an option. The brake uses an asbestos-free design.

The α M (HV) series includes the following models:

- Models α M6HV and α M9HV that are compatible with the installation dimensions of the α series models α 3 and α 6
- Models α M22HV, α M30HV, and α M40HV that are compatible with the installation dimensions of the α series models α 12, α 22, α 30, and α 40

2 TYPES OF MOTORS AND DESIGNATION

Models αM6/3000HV and αM9/3000HV

A06B-01 □□ -B ☆ ○○

□□

82 : Model αM6/3000HV

83 : Model αM9/3000HV

☆

0 : Taper shaft (standard)

2 : Taper shaft with the brake (8Nm/24VDC)

5 : Straight shaft

7 : Straight shaft with the brake (8Nm/24VDC)

○○

75 : Pulse coder αA64

77 : Pulse coder αI64

88 : Pulse coder αA1000

The standard shafts used for models αM6/3000HV and αM9/3000HV are taper shafts. Use a taper shaft as far as circumstances, such as the delivery time and maintenance, permit.

Models αM22/3000HV and αM30/3000HV

A06B-01 □□ -B ☆ ○○

□□

85 : Model αM22/3000HV

86 : Model αM30/3000HV

☆

0 : Straight shaft (standard)

2 : Straight shaft with the brake (35Nm/24VDC)

5 : Taper shaft

7 : Taper shaft with the brake (35Nm/24VDC)

○○

75 : Pulse coder αA64

77 : Pulse coder αI64

88 : Pulse coder αA1000

A straight shaft is fitted as the standard shaft for models αM22/3000HV and αM30/3000HV. When early delivery and ease-of-maintenance are important, a straight shaft should be used.

Models
 α M40/3000HV**A06B-0189-☆ ○○**☆**0** : Straight shaft (standard)**2** : Straight shaft with the brake (35Nm 24VDC)○○**75** : With the pulse coder α A64**77** : With the pulse coder α I64**88** : With the pulse coder α A1000

This model, a tapered shaft is not available.

3

SPECIFICATIONS AND CHARACTERISTICS



3.1 TYPES OF MOTORS AND SPECIFICATIONS

| Item | Unit | α M6/ 3000HV | α M9/ 3000HV | α M22/ 3000HV | α M30/ 3000HV | α M40/ 3000HV |
|-----------------------|-----------------------|------------------------|------------------------|-------------------------|--------------------------|-------------------------|
| Output | kw | 1.4 | 1.8 | 3.8 | 3.8 | 3.0 |
| | HP | 1.9 | 2.4 | 5.1 | 5.1 | 4.0 |
| Rated torque at stall | Nm | 6 | 9 | 20 | 30 | 40 |
| | kgf·cm | 61 | 92 | 204 | 306 | 408 |
| Rating rotation speed | min ⁻¹ | 3000 | 3000 | 3000 | 2000(S1) 3000(S3-60%) | 1000 |
| Rotor inertia | kg·m ² | 0.0013 | 0.0025 | 0.0058 | 0.011 | 0.012 |
| | kgf·cm·s ² | 0.014 | 0.026 | 0.059 | 0.11 | 0.12 |
| Mass | kg | 7.5 | 12 | 29 | 41 | 41 |

The above values are under the condition at 20°C.

3.2 CHARACTERISTIC CURVE AND DATA SHEET

Speed-torque characteristics

The intermittent operation zone is determined by the input voltage applied to the drive amplifier. The curve shown is the value for the rated input voltage (400V).

On model α M40/3000HV, “Intermittent operating (S3 to 25%)” in the “Speed-torque characteristics” is permitting operating zone in IEC34-1, and it enables to operate 2.5 min ON and 7.5 min OFF in 10 min cycle time.

Equally, (S3 to 60%)” in the “Speed-torque characteristics” enables to operate 6 min ON and 4 min OFF in 10 min cycle time.

On models α M6HV to α M9HV, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Overload duty characteristic

The overload duty characteristic curves are determined based on the temperature restriction for the single motor unit (the temperature is restricted by means of a thermal trip built into the motor). The curves are determined by assuming that the temperature increases gradually under certain overload conditions. Therefore, the curves do not apply to the rapid temperature rise which occurs, for example, when the motor shaft is locked. (An overcurrent flows in the motor windings until the thermal trip operates. The temperature rises momentarily.)

To detect such an abrupt temperature rise, the FANUC digital servo system provides a software thermal function that uses servo software to observe the current. During operation that is characterized by frequent acceleration/deceleration cycles, control is imposed by the software thermal function.

Driving units (such as amplifiers) and built-in detectors contain their own overheating protection devices. Therefore, note that control may be imposed according to how the equipment is being used.

Data sheet

The parameters given in the data sheet are representative values for an ambient temperature of 20°C. They are subject to an error of +10%.

The indicated logical values are threshold values for the single motor unit (when the motor is not restricted by the control system).

The maximum torque that can be produced during acceleration or deceleration in actual use is calculated as the approximate product of the motor torque constant and the current limit value of the amplifier.

Example : α M6/3000HV


- Motor torque constant = 1.50 (Nm/Arms)
- Amplifier limit value = 40 (Apeak)
- Maximum torque value
= $40 \times 0.707 \times 1.50$ (Nm)
(Converted to an effective value)

This value is for reference only. The actual value will vary depending on changes in the power supply, as well as variations in motor parameters and amplifier limit values.

In some models, if the maximum current flows in the motor, the actual maximum torque is affected by, for example, magnetic saturation. As a result, the actual maximum torque will be lower than the calculated value. The intermittent operation area (maximum torque value) indicated in the speed to torque characteristics is the effective value, determined according to the combination with the amplifier.

Model α M6/3000HV

Specification : A06B-0182-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 6 | | Nm |
| | | 61 | | kgfcm |
| Rotor inertia | Jm | 0.0013 | | kgm ² |
| | | 0.014 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 4.0 | | A (rms) |
| Torque constant (*) | Kt | 1.50 | | Nm/A (rms) |
| | | 15.3 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 52 | | V (rms)/1000min ⁻¹ |
| | | 0.50 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 1.80 | | Ω |
| Mechanical time constant (*) | tm | 0.003 | | s |
| Thermal time constant | tt | 45 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Maximum allowable current | Im | 60 | | A (peak) |
| Mass | | 7.5 | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model α M6HV, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Model α M9/3000HV

Specification : A06B-0183-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating rotation speed | Nmax | 3000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 9 | | Nm |
| | | 92 | | kgfcm |
| Rotor inertia | Jm | 0.0025 | | kgm ² |
| | | 0.026 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 5.8 | | A (rms) |
| Torque constant (*) | Kt | 1.56 | | Nm/A (rms) |
| | | 15.9 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 54 | | V (rms)/1000min ⁻¹ |
| | | 0.52 | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.67 | | Ω |
| Mechanical time constant (*) | tm | 0.002 | | s |
| Thermal time constant | tt | 50 | | min |
| Static friction | Tf | 0.3 | | Nm |
| | | 3 | | kgfcm |
| Maximum allowable current | Im | 120 | | A (peak) |
| Mass | | 12 | | kg |


(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

On model α M9HV, the maximum speed of rotation is increased by using HRV control. The speed-torque characteristics for when HRV control is used are described at the end of this item

Model α M22/3000HV

Specification : A06B-0185-B□□□



Data sheet


| Parameter | Symbol | Value | Unit |
|-------------------------------------|--------|--------|-------------------------------|
| Rating rotation speed | Nmax | 3000 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 20 | Nm |
| | | 204 | kgfcm |
| Rotor inertia | Jm | 0.0058 | kgm ² |
| | | 0.059 | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 12.1 | A (rms) |
| Torque constant (*) | Kt | 1.66 | Nm/A (rms) |
| | | 16.9 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 58 | V (rms)/1000min ⁻¹ |
| | | Kv | 0.55 |
| Armature resistance (1-phase) (*) | Ra | 0.26 | Ω |
| Mechanical time constant (*) | tm | 0.002 | s |
| Thermal time constant | tt | 60 | min |
| Static friction | Tf | 0.8 | Nm |
| | | 8 | kgfcm |
| Maximum allowable current | Im | 90 | A (peak) |
| Mass | | 18 | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

Model αM30/3000HV

Specification : A06B-0186-B□□□



Data sheet

| Parameter | Symbol | Value | | | Unit |
|-------------------------------------|--------|---------------|--|--|-------------------------------|
| | | | | | |
| Rating rotation speed | Nmax | 2000 (S1) | | | min ⁻¹ |
| | | 3000 (S3-60%) | | | |
| Rated torque at stall (*) | Ts | 30 | | | Nm |
| | | 306 | | | kgfcm |
| Rotor inertia | Jm | 0.011 | | | kgm ² |
| | | 0.11 | | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 16.3 | | | A (rms) |
| Torque constant (*) | Kt | 1.85 | | | Nm/A (rms) |
| | | 18.8 | | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 64 | | | V (rms)/1000min ⁻¹ |
| | Kv | 0.64 | | | V (rms)·sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.16 | | | Ω |
| Mechanical time constant (*) | tm | 0.002 | | | s |
| Thermal time constant | tt | 65 | | | min |
| Static friction | Tf | 1.2 | | | Nm |
| | | 12 | | | kgfcm |
| Maximum allowable current | Im | 160 | | | A (peak) |
| Mass | | 30 | | | kg |


(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed–torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo motor. (The above figures show average values.) These values may be changed without prior notice.

The 2000 to 3000 min⁻¹ range of this servo motor is the intermittent operation range, and is used mainly for positioning. In the intermittent operation range (S3 to 60%), ON operation of six minutes and OFF operation of four minutes in a 10-minute cycle is possible.

Model αM40/3000HV

Specification : A06B-0189-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|-------|--|-------------------------------|
| Rating speed | Nmax | 1000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 40 | | Nm |
| | | 408 | | kgfcm |
| Rotor inertia | Jm | 0.012 | | kgm ² |
| | | 0.12 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 20.2 | | A (rms) |
| Torque constant (*) | Kt | 1.98 | | Nm/A (rms) |
| | | 20.2 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 69 | | V (rms)/1000min ⁻¹ |
| | | 0.66 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.13 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 70 | | min |
| Static friction | Tf | 1.8 | | Nm |
| | | 18 | | kgfcm |
| Weight | | 41 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)


These values may be changed without prior notice.

S3 to 25% intermitting operating zone shows 2.5 min continuous operating zone in 10 min cycle.


(Remarks)
Speed-torque
characteristics
(HRV control)

On the following models, the intermittent operating zone can be extended by using HRV control.

● α M6/3000HV



● α M9/3000HV



NOTE

HRV control sometimes cannot be used depending on the CNC system. Using HRV control increases the intermittent operating zone at high motor operating speeds. The continuous operating zone, however, is the same as when conventional control methods are used.

3.3 OUTLINE DRAWINGS

| Model | Fig. No. |
|--|--------------|
| Models α M6/3000HV and α M9/3000HV (standard) | Fig. 3.3 (a) |
| Models α M6/3000HV and α M9/3000HV (with the brake) | Fig. 3.3 (b) |
| Models α M6/3000HV (shaft option) | Fig. 3.3 (c) |
| Models α M9/3000HV (shaft option) | Fig. 3.3 (d) |
| Models α M22/3000HV and α M30/3000HV (standard) | Fig. 3.3 (e) |
| Models α M22/3000HV and α M30/3000HV (with the brake) | Fig. 3.3 (f) |
| Models α M22/3000HV and α M30/3000HV (shaft option) | Fig. 3.3 (g) |
| Model α M40/3000HV | Fig. 3.3 (h) |
| Model α M40/3000HV (with the brake) | Fig. 3.3 (i) |

Fig. 3.3 (a) Models αM6/3000HV and αM9/3000HV (standard)




Fig. 3.3 (c) Models αM6/3000HV (shaft option)




Fig. 3.3 (e) Models αM22/3000HV and αM30/3000HV (standard)




Fig. 3.3 (h) Model αM40/2000HV (standard)






Fig. 3.3 (i) Model αM40/2000HV (with the brake)



3.4 CONNECTION OF POWER LINE


Models

α M6/3000HV and α M9/3000HV



Models

α M22/3000HV, α M30/3000HV, and α M40/3000HV



VIII. SUPPLEMENT

(Following AC servo motors are extended the allowable maximum speed.)

1

REQUIRED CONDITIONS

| | |
|-------------------------------|---|
| Servo Motor | <ul style="list-style-type: none"> • The following table shows the applied motors and their allowable maximum speed. • The specification numbers of Servo Motor for order are same as before. • Some motors need the manufacture date since January '99. |
| Servo Software | <ul style="list-style-type: none"> • It is necessary to use 90A0 or later series software and HRV2 (LEVEL-UP HRV) control. |
| Servo Parameters | <ul style="list-style-type: none"> • It is necessary to change the parameters. |
| Servo Amplifier (SVM, SVU) | <ul style="list-style-type: none"> • It is not necessary to change. |
| Power supply module (PSM) | <ul style="list-style-type: none"> • It may be necessary to select again depending on the situation. |

2

SERVO MOTOR

- The following table shows the applied motors and their allowable maximum speed.
- The specification numbers of Servo Motor for order are same as before.
- Some motors need the manufacture date since January '99.

| | Allowable maximum speed | | Applicable manufacture date |
|---------------------------|-------------------------|-----------------------|--------------------------------|
| | Before | After | |
| α 12/3000 | 3000min ⁻¹ | 4000min ⁻¹ | since Jan. 1999 |
| α 22/3000 | 3000min ⁻¹ | 4000min ⁻¹ | since Jan. 1999 |
| α 30/3000 | 3000min ⁻¹ | 4000min ⁻¹ | since Jan. 1999 |
| α 40/2000 | 2000min ⁻¹ | 2500min ⁻¹ | – not required |
| α 40/2000 with fan | 2000min ⁻¹ | 2500min ⁻¹ | – not required |
| α 65/2000 | 2000min ⁻¹ | 2500min ⁻¹ | – not required |
| α 100/2000 | 2000min ⁻¹ | 2500min ⁻¹ | – not required |
| α 150/2000 | 2000min ⁻¹ | 2500min ⁻¹ | – not required |
| α M22/3000 | 3000min ⁻¹ | 4000min ⁻¹ | – not required |
| α M30/3000 | 3000min ⁻¹ | 4000min ⁻¹ | – not required |
| α 12/3000HV | 3000min ⁻¹ | 4000min ⁻¹ | since Jan. 1999 |
| α M22/3000HV | 3000min ⁻¹ | 4000min ⁻¹ | – not required |
| α M30/3000HV | 3000min ⁻¹ | 4000min ⁻¹ | – not required |

NOTE

α 22/3000HV and α 30/3000HV are not extend the maximum allowable speed for the moment.

3

SERVO SOFTWARE



It is necessary for 90A0 or later series servo software and the control to be HRV2 (LEVEL-UP HRV) control.

Refer to “FANUC AC SERVO MOTOR α series PARAMETER MANUAL (B-65150E /after edition 03)” as 90A0 series servo software and its edition for HRV2 (LEVEL-UP HRV) control.

4 SERVO PARAMETER

- The parameters for extended the maximum allowable speed are the following.
 - 1) α 12/3000, α 22/3000, α 30/3000, α 40/2000, α 40/2000 (with fan), α 65/2000, α 100/2000, α 150/2000, α 12/3000HV
 1. Download the parameter in 90A0-001U and after.
 2. Set up the LEVEL-UP HRV control.
 - No.1809 / 2004 00000011
 - No.1852 / 2040 Multiply normal parameter by 0.8
 - No.1853 / 2041 Multiply normal parameter by 1.6
 - 2) α M22/3000, α M30/3000, (α M40/3000, α M40/3000 (with fan)), α M22/3000HV, α M30/3000HV
 1. Download the parameter in 90A0-001U and after.
 2. Change the parameter as Table 4.


Table 4 Parameter for changing (inside the bold flame)

| | Model | α M22/3000 | α M30/3000 | α M22/3000HV | α M30/3000HV | α M40/3000 (with fan) | α M40/3000 | |
|---------|---------------|-------------------|-------------------|---------------------|---------------------|------------------------------|-------------------|----------|
| 99.11.2 | Spec. No. | 0165 | 0166 | 0185 | 0186 | 0170 | 0169 | |
| Symbol | ID No. | 100 | 101 | 106 | 107 | 108 | 110 | |
| | Parameter No. | | | | | | | |
| | FS15 | FS16,18 | | | | | | |
| | 1809 | 2004 | 00000011 | 00000011 | 00000011 | 00000011 | 01000011 | 00000011 |
| PK1 | 1852 | 2040 | 670 | 1030 | 1120 | 1059 | 2017 | 1197 |
| PK2 | 1853 | 2041 | -4054 | -5246 | -4755 | -4117 | -8287 | -5048 |
| PVPA | 1869 | 2057 | -7695 | -5129 | -5135 | -6422 | -3848 | -3865 |
| PALPH | 1870 | 2058 | -2700 | -1680 | -2000 | -3226 | -1144 | -3168 |
| AALPH | 1967 | 2074 | 12288 | 0 | 28672 | 8192 | 20480 | 0 |
| MFWKCE | 1736 | 2128 | 0 | 8000 | 0 | 1000 | 2000 | 2000 |
| PHDLY1 | 1756 | 2133 | 0 | 0 | 0 | 0 | 0 | 0 |
| PHDLY2 | 1757 | 2134 | 0 | 0 | 0 | 0 | 0 | 0 |

- 1 Although the α M40/3000 and α M40/3000 (with fan) are not intended for higher speeds, parameters best suited to LEVEL-UP HRV are available to them.
- 2 See the Parameter Manual (B-65150E) for details of servo software 90A0 001U.
- 3 See the Section 4.3 "LEVEL-UP HRV control" of the Parameter Manual (B-65150E) for details of setting the LEVEL-UP HRV control.
- 4 The parameter in Table 4 is the best-tuned parameter for LEVEL-UP HRV control. If the speed is not extended, it has better controllability with this parameter.
- 5 See the Parameter Manual (B-65150E edition 03 or later) for details of servo parameters.

5

SELECTING PSM



In case of the using motors with extended speed, it is necessary to use “Case 2” for accelerating maximum output in “FANUC SERVO AMPLIFIER α series DESCRIPTIONS (B-65162/after edition 03)” Refer to FANUC SERVO AMPLIFIER α series DESCRIPTIONS (B-65162/after edition 03)” as the details.

6


"CHARACTERISTICS CURVE" AND "DATA SHEET"



"Characteristics Curve" and "Data sheet" are shown in following pages.

Model α12/3000

Specification : A06B-0143-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating speed | Nmax | 3000 | | min ⁻¹ |
| Maximum speed | Nlim | 4000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 12 | | Nm |
| | | 122 | | kgfcm |
| Rotor inertia | Jm | 6.2E-3 | | kgm ² |
| | | 6.4E-2 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 15.5 | | A (rms) |
| Torque constant (*) | Kt | 0.77 | | Nm/A (rms) |
| | | 7.9 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 27.1 | | V (rms)/1000min ⁻¹ |
| | | 0.26 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.18 | | Ω |
| Mechanical time constant (*) | tm | 0.006 | | s |
| Thermal time constant | tt | 60 | | min |
| Static friction | Tf | 0.8 | | Nm |
| | | 8 | | kgfcm |
| Weight | | 18 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model $\alpha 22/3000$

Specification : A06B-0148-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating speed | Nmax | 3000 | | min ⁻¹ |
| Maximum speed | Nlim | 4000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 22 | | Nm |
| | | 224 | | kgfcm |
| Rotor inertia | Jm | 1.2E-2 | | kgm ² |
| | | 1.2E-1 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 32.1 | | A (rms) |
| Torque constant (*) | Kt | 0.68 | | Nm/A (rms) |
| | | 7.0 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 23.9 | | V (rms)/1000min ⁻¹ |
| | | 0.23 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.05 | | Ω |
| Mechanical time constant (*) | tm | 0.004 | | s |
| Thermal time constant | tt | 65 | | min |
| Static friction | Tf | 1.2 | | Nm |
| | | 12 | | kgfcm |
| Weight | | 30 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model α 30/3000

Specification : A06B-0153-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating speed | Nmax | 3000 | | min ⁻¹ |
| Maximum speed | Nlim | 4000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 30 | | Nm |
| | | 306 | | kgfcm |
| Rotor inertia | Jm | 1.7E-2 | | kgm ² |
| | | 1.7E-1 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 33.7 | | A (rms) |
| Torque constant (*) | Kt | 0.89 | | Nm/A (rms) |
| | | 9.1 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 31.1 | | V (rms)/1000min ⁻¹ |
| | | 0.30 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.05 | | Ω |
| Mechanical time constant (*) | tm | 0.003 | | s |
| Thermal time constant | tt | 70 | | min |
| Static friction | Tf | 1.8 | | Nm |
| | | 18 | | kgfcm |
| Weight | | 41 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)


These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model α 40/2000
Model α 40/2000FAN

Specification : A06B-0157-B□□□

Specification : A06B-0158-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--------|-------------------------------|
| Rating speed | Nmax | 2000 | 2000 | min ⁻¹ |
| Maximum speed | Nlim | 2500 | 2500 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 38 | 56 | Nm |
| | | 388 | 571 | kgfcm |
| Rotor inertia | Jm | 2.2E-2 | 2.2E-2 | kgm ² |
| | | 2.3E-1 | 2.3E-1 | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 27.2 | 40.1 | A (rms) |
| Torque constant (*) | Kt | 1.40 | 1.40 | Nm/A (rms) |
| | | 14.3 | 14.3 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 48.8 | 48.8 | V (rms)/1000min ⁻¹ |
| | | Kv | 0.47 | 0.47 |
| Armature resistance (1-phase) (*) | Ra | 0.08 | 0.08 | Ω |
| Mechanical time constant (*) | tm | 0.003 | 0.003 | s |
| Thermal time constant | tt | 75 | 30 | min |
| Static friction | Tf | 1.8 | 1.8 | Nm |
| | | 18 | 18 | kgfcm |
| Weight | | 52 | 55 | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model α65/2000

Specification : A06B-0331-B□□□



Data sheet

| Parameter | Symbol | Value | | | Unit |
|-------------------------------------|--------|--------|--|--|-------------------------------|
| Rating speed | Nmax | 2000 | | | min ⁻¹ |
| Maximum speed | Nlim | 2500 | | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 65 | | | Nm |
| | | 663 | | | kgfcm |
| Rotor inertia | Jm | 1.8E-2 | | | kgm ² |
| | | 1.9E-1 | | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 62.5 | | | A (rms) |
| Torque constant (*) | Kt | 1.04 | | | Nm/A (rms) |
| | | 10.6 | | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 36.3 | | | V (rms)/1000min ⁻¹ |
| | | 0.35 | | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.02 | | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | | s |
| Thermal time constant | tt | 120 | | | min |
| Static friction | Tf | 3.7 | | | Nm |
| | | 38 | | | kgfcm |
| Weight | | 80 | | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model $\alpha 100/2000$

Specification : A06B-0332-B□□□



Data sheet

| Parameter | Symbol | Value | Unit |
|-------------------------------------|--------|-----------------|--------------------------------|
| Rating speed | Nmax | 2000 | min^{-1} |
| Maximum speed | Nlim | 2500 | min^{-1} |
| Rated torque at stall (*) | Ts | 100 | Nm |
| | | 1020 | kgfcm |
| Rotor inertia | Jm | $2.6\text{E}-2$ | kgm^2 |
| | | $2.7\text{E}-1$ | kgfcm s^2 |
| Continuous RMS current at stall (*) | Is | 85.3 | A (rms) |
| Torque constant (*) | Kt | 1.17 | Nm/A (rms) |
| | | 12.0 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 40.9 | V (rms)/1000 min^{-1} |
| | | Kv | 0.39 |
| Armature resistance (1-phase) (*) | Ra | 0.01 | Ω |
| Mechanical time constant (*) | tm | 0.001 | s |
| Thermal time constant | tt | 130 | min |
| Static friction | Tf | 5.5 | Nm |
| | | 56 | kgfcm |
| Weight | | 100 | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model α150/2000

Specification : A06B-0333-B□□□



Data sheet

| Parameter | Symbol | Value | Unit |
|-------------------------------------|--------|--------|-------------------------------|
| Rating speed | Nmax | 2000 | min ⁻¹ |
| Maximum speed | Nlim | 2500 | min ⁻¹ |
| Rated torque at stall (*) | Ts | 150 | Nm |
| | | 1531 | kgfcm |
| Rotor inertia | Jm | 3.4E-2 | kgm ² |
| | | 3.5E-1 | kgfcm ² |
| Continuous RMS current at stall (*) | Is | 114.9 | A (rms) |
| Torque constant (*) | Kt | 1.30 | Nm/A (rms) |
| | | 13.3 | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 45.6 | V (rms)/1000min ⁻¹ |
| | | 0.44 | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.01 | Ω |
| Mechanical time constant (*) | tm | 0.001 | s |
| Thermal time constant | tt | 140 | min |
| Static friction | Tf | 7.4 | Nm |
| | | 75 | kgfcm |
| Weight | | 120 | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model α M22/3000

Specification : A06B-0165-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating speed | Nmax | 3000 | | min ⁻¹ |
| Maximum speed | Nlim | 4000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 20 | | Nm |
| | | 204 | | kgfcm |
| Rotor inertia | Jm | 5.8E-3 | | kgm ² |
| | | 5.9E-2 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 26.5 | | A (rms) |
| Torque constant (*) | Kt | 0.75 | | Nm/A (rms) |
| | | 7.7 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 26.3 | | V (rms)/1000min ⁻¹ |
| | | 0.25 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.07 | | Ω |
| Mechanical time constant (*) | tm | 0.002 | | s |
| Thermal time constant | tt | 60 | | min |
| Static friction | Tf | 0.8 | | Nm |
| | | 8 | | kgfcm |
| Weight | | 18 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model αM30/3000

Specification : A06B-0166-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating speed | Nmax | 2000 | | min ⁻¹ |
| Maximum speed | Nlim | 4000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 30 | | Nm |
| | | 306 | | kgfcm |
| Rotor inertia | Jm | 1.1E-2 | | kgm ² |
| | | 1.1E-1 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 27.9 | | A (rms) |
| Torque constant (*) | Kt | 1.08 | | Nm/A (rms) |
| | | 11.0 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 37.6 | | V (rms)/1000min ⁻¹ |
| | | 0.36 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.05 | | Ω |
| Mechanical time constant (*) | tm | 0.001 | | s |
| Thermal time constant | tt | 65 | | min |
| Static friction | Tf | 1.2 | | Nm |
| | | 12 | | kgfcm |
| Weight | | 30 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model $\alpha 12/3000HV$

Specification : A06B-0176-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating speed | Nmax | 3000 | | min ⁻¹ |
| Maximum speed | Nlim | 4000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 12 | | Nm |
| | | 122 | | kgfcm |
| Rotor inertia | Jm | 6.2E-3 | | kgm ² |
| | | 6.4E-2 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 8.8 | | A (rms) |
| Torque constant (*) | Kt | 1.36 | | Nm/A (rms) |
| | | 13.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 47.4 | | V (rms)/1000min ⁻¹ |
| | | 0.45 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.56 | | Ω |
| Mechanical time constant (*) | tm | 0.006 | | s |
| Thermal time constant | tt | 60 | | min |
| Static friction | Tf | 0.8 | | Nm |
| | | 8 | | kgfcm |
| Weight | | 18 | | kg |

(*) The values are the standard values at 20°C and the tolerance is $\pm 10\%$.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model α M22/3000HV

Specification : A06B-0185-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating speed | Nmax | 3000 | | min ⁻¹ |
| Maximum speed | Nlim | 4000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 20 | | Nm |
| | | 204 | | kgfcm |
| Rotor inertia | Jm | 5.8E-3 | | kgm ² |
| | | 5.9E-2 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 12.1 | | A (rms) |
| Torque constant (*) | Kt | 1.66 | | Nm/A (rms) |
| | | 16.9 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 57.9 | | V (rms)/1000min ⁻¹ |
| | | 0.55 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.26 | | Ω |
| Mechanical time constant (*) | tm | 0.002 | | s |
| Thermal time constant | tt | 60 | | min |
| Static friction | Tf | 0.8 | | Nm |
| | | 8 | | kgfcm |
| Weight | | 18 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.


The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

Model α M30/3000HV

Specification : A06B-0186-B□□□



Data sheet

| Parameter | Symbol | Value | | Unit |
|-------------------------------------|--------|--------|--|-------------------------------|
| Rating speed | Nmax | 3000 | | min ⁻¹ |
| Maximum speed | Nlim | 4000 | | min ⁻¹ |
| Rated torque at stall (*) | Ts | 30 | | Nm |
| | | 306 | | kgfcm |
| Rotor inertia | Jm | 1.1E-2 | | kgm ² |
| | | 1.1E-1 | | kgfcms ² |
| Continuous RMS current at stall (*) | Is | 16.3 | | A (rms) |
| Torque constant (*) | Kt | 1.85 | | Nm/A (rms) |
| | | 18.8 | | kgfcm/A (rms) |
| Back EMF constant (1-phase) (*) | Ke | 64.5 | | V (rms)/1000min ⁻¹ |
| | | 0.62 | | V (rms)-sec/rad |
| Armature resistance (1-phase) (*) | Ra | 0.16 | | Ω |
| Mechanical time constant (*) | tm | 0.002 | | s |
| Thermal time constant | tt | 65 | | min |
| Static friction | Tf | 1.2 | | Nm |
| | | 12 | | kgfcm |
| Weight | | 30 | | kg |

(*) The values are the standard values at 20°C and the tolerance is ± 10%.

The speed-torque characteristics vary depending on the type of software, parameter setting, and input voltage of the digital servo software. (The above figures show average values.)

These values may be changed without prior notice.

S3 to 60% intermitting operating zone shows 6 min "ON" and 4 min "OFF" in 10 min cycle.

[Numbers]

200 VAC input types, 56, 58
400 VAC input types, 57, 58

[A]

About connector cables, 100
Absolute-type pulse coder, 69
Acceptance and storage, 21
Applicable Amplifiers, 6
Applicable amplifiers, 6
Applicable motors, 56
Approved specifications, 63
Axis load, 17

[B]

Brake cable (TUV/EMC compatible), 84
Brake specifications, 80
Built-in brake, 79
Built-in detector, 67

[C]

Cable assembly specifications ($\alpha 3$ or above) (14m standard), 98
Cable assembly specifications (14m standard) (for $\alpha 1$ and $\alpha 2$), 90
Calculating conditions for selecting a motor, 28
Calculating the acceleration torque, 34
Calculating the load torque and load inertia, 29
Calculating the percentage duty cycle with the maximum cutting torque, 39
Calculating the root-mean-square value of the torques, 37
Characteristic curve and data sheet, 52, 112, 154, 187, 205, 226, 256
Characteristics Curve” and “Data Sheet”, 282
Conditions for approval related to the IEC34 standard, 55
Connection of power line, 144, 180, 198, 217, 247, 274
Connection of the brakes, 83
Connector kit specifications, 89
Connector on the motor side, 87
Connector shapes, 82

Connectors, 86
Connectors on the cable side (models $\alpha 1$ and $\alpha 2$), 89
Cooling fan, 99
Cooling fan specifications, 100
Cooling method (ICE34-6), 64
Coupling, 15

[D]

Data, 45
Data for Selecting PSM, 13
Data sheet, 52
Detector input/output signals, 70
Drive shaft coupling, 23
Drives, 58

[E]

Environment, 18
External dimensions of separate type pulse coder, 75

[F]

Feedback detector, 66

[H]

Heat protection (IEC34-11), 65
How to fill in the servo motor selection data table, 43
How to use duty cycle curves, 54

[I]

Input signals and layout of connector pins of separate type pulse coder, 73
Installation, 14
Instructions, 22

[M]

Machine movement per 1 revolution of motor shaft, 26
Models $\alpha 1$ and $\alpha 2$, 59
Models $\alpha 3$ and higher, 61
Motor connector specifications, 100

Motor speed (IEC34-1), 63
 Mounting method (IEC34-7), 65

[O]

Outline drawings, 128, 166, 193, 210, 236, 264
 Output (IEC34-1), 64

[P]

Performance curves, 52
 Power cable connectors, 59
 Precautions for using linear scale, 41
 Precautions on use, 5
 Protection type (IEC34-5), 64
 Pulse coder resolution and control resolution, 68

[R]

Recommended parts in brake circuits, 84
 Reducing the brake shaft fall amount, 85
 Required Conditions, 277

[S]

Selecting a motor, 27
 Selecting PSM, 281
 Separate type position detector, 71

Separate type pulse coder specifications, 72
 Separate type pulse coder type and specifications, 71
 Servo Motor, 278
 Servo Parameter, 280
 Servo Software, 279
 Specifications and characteristics, 109, 152, 185, 203, 224, 254
 Specifications of connectors on the motor side, 87
 Specifications of plug connectors on the cable side (non-waterproof type), 96
 Specifications of plug connectors on the cable side (waterproof TÜV-approved type), 93
 Specifications of plug connectors on the cable side (waterproof type), 94
 Specifications of the connectors on the cable side (models $\alpha 3$ and higher), 91

[T]

Title, 44
 Type of motors and specifications, 110
 Types of motors and designation, 106, 150, 184, 202, 222, 252
 Types of motors and specifications, 153, 186, 204, 225, 255

[W]

Wiring diagram, 101

Revision Record

FANUC AC SERVO MOTOR α series DESCRIPTIONS (B-65142E)

| Edition | Date | Contents | Edition | Date | Contents |
|---------|------------|---|---------|------|----------|
| 04 | Feb., 2001 | Addition of models α M40, α M40 with fan, α 40/2000HV, α M40/3000HV, α 300/2000, α 400/2000, and α 1000/2000HV Addition of "VIII. SUPPLEMENT" Correction of errors | | | |
| 03 | Dec., 1998 | Addition of "VII. FANUC AC SERVO MOTOR α M(HV) series" | | | |
| 02 | Mar., 1995 | Addition of "5. CONDITIONS FOR APPROVAL RELATED TO THE IEC34 STANDARD" in Part I Addition of "8. CONNECTORS" in Part I Addition of "III. FANUC AC SERVO MOTOR α (HV) series" | | | |
| 01 | Mar., 1994 | _____ | | | |
| Edition | Date | Contents | Edition | Date | Contents |

- *No part of this manual may be reproduced in any form.*
- *All specifications and designs are subject to change without notice.*